

N40PK



Learjet (Bombardier)

35A

HOUR METER

12647.70

S/N: 35-260
TT: 12,647.70

CYC: 8,968
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
001,	300 hr Phase A1 through A6	Inspection	05-10-01			Hours	-12	10/28/2008	0
				Comments:	C/W at (a) 300 hrs. or (b) 1 yrs.				
002,	600 hr Phase B1 through B6	Inspection	05-10-07			Hours	377	11/29/2009	377
				Comments:	C/W at (a) 600 hrs. or (b) 2 yrs.				
003,	1200 hr Phase C1 through C6	Inspection	05-10-13			Hours	420	05/05/2009	420
				Comments:	C/W at (a) 1,200 hrs. or (b) 4 yrs.				
004,	2400 hr Phase D1 through D6	Inspection	05-10-19			Hours	1950	10/15/2008	264
				Comments:	C/W at (a) 2,400 hrs. or (b) 8 yrs.				
005,	3,000 Landings	Inspection	05-10-25			Cycles	6096	10/02/2024	6096
				Comments:	Inspect every 3,000 landings.				
006,	6,000 Landings (Major Landing Gear Insp.)	Inspection	05-10-26			Cycles	3039	05/20/2016	3039
				Comments:	Inspect every 6,000 landings.				
007,	12 Year Airframe	Inspection	05-10-27			Cycles	5984	11/14/2015	2851
				Comments:	C/W every (a) 6,000 cycles or (b) 12 yrs.				
008,	12,000 Hour Airframe	Inspection	05-10-28			Hours	5550	04/05/2023	5550
				Comments:	C/W every 12,000 hrs. then every 6000 hours thereafter				
021,	74-08-08 Rv.2, Lavatory & Receptacle Placards	AD	11-30-			Hours	777	03/11/2010	777
		Cabin		Comments:	Inspect every 1,000 hrs. in/a/w SB 35/36-11-04				
022,	82-01-05 Rv.2, Accelerometer (Stall Warning)	AD	27-40-62			Hours	-2	01/24/2008	0
				Comments:	Operational check every 220 hrs. in/a/w SB 35/36-27-12				
023a,	87-02-06, 420 hr Fwd. Engine Mount Casting - Left	AD				Hours	-29	01/24/2008	0
		Left		Comments:	Visual insp. every 420 hrs. in/a/w SB 35/36-71-3.				
023b,	87-02-06, 420 hr Fwd. Engine Mount Casting - Right	AD				Hours	-29	01/24/2008	0
		Right		Comments:	Visual insp. every 420 hrs. in/a/w SB 35/36-71-3				
024a,	87-02-06, 1500 hr Fwd. Engine Mount Casting - Left	AD				Hours	1050	12/09/2010	1050
		Left		Comments:	Inspect (NDT) every 1,500 hrs. in/a/w SB 35/36-71-3.				
024b,	87-02-06, 1500 hr Fwd. Engine Mount Casting - Right	AD				Hours	1050	12/09/2010	1050
		Right		Comments:	Inspect (NDT) every 1,500 hrs. in/a/w SB 35/36-71-3				

N40PK



Page 2 of 15

Learjet (Bombardier)

35A

HOUR METER

12647.70

S/N: 35-260
TT: 12,647.70

CYC: 8,968
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
025a, 04-03-08, 1200 hr Pylon/Engine Beam Structure - Left	AD	Left		Comments: Inspect every 1,200 hrs. in/a/w SB 35/36-51-3		Hours	750	02/12/2010	750
025b, 04-03-08, 1200 hr Pylon/Engine Beam Structure - Right	AD	Right		Comments: Inspect every 1,200 hrs. in/a/w SB 35/36-51-3		Hours	750	02/12/2010	750
056, Life Vest	Inspection	Cabin	C2561000	Comments: Recertify per manufacturer's Instructions		Date	0	10/26/2008	275
059, 30 day Hand Held Fire Extinguisher	Inspection	Cabin		Comments: Visually inspect every 30 days		Date	0	01/26/2008	2
064a, Cap Check #1 Main Ship Battery (Concorde)	Inspection	Tailcone	G1222002	Comments: Cap check at 12 months or 600 hours, then every 3 months or 200 hours		Hours	122	01/11/2009	122
064b, Cap Check #2 Main Ship Battery (Concorde)	Inspection	Tailcone	G1222002	Comments: Cap check at 12 months or 600 hours, then every 3 months or 200 hours		Hours	122	01/11/2009	122
065, 100 hr Emergency Power Supply (PS823)	Inspection	Nose	D1223000	501-1075-02 Comments: Inspect every 100 hours or 3 months		Hours	22	04/11/2008	22
066, 12 Month Emergency Power Supply (PS823)	Inspection	Nose	D1223001	501-1075-02 Comments: Discharge/Recharge every 12 months		Date	0	08/09/2008	197
070, 1200 hr Cabin Leak Rate	Inspection	Cabin	H2130007	Comments: Perform cabin leak rate check every 1,200 hours		Hours	1122	02/19/2011	1122
071a, 2000 hr Generator Overhaul (Left)	Inspection	E1	C2431015	Comments: Overhaul Generator every 2000 hours		Hours	1550	04/22/2012	1550
071b, 2000 hr Generator Overhaul (Right)	Inspection	E2	C2431015	Comments: Overhaul Generator every 2000 hours		Hours	1168	04/06/2011	1168
072a, 1050 hr Generator Bearing (Left)	Inspection	E1	C2431016	Comments: Replace Generator Bearings every 1050 hours		Hours	600	09/15/2009	600
072b, 1050 hr Generator Bearing (Right)	Inspection	E2	C2431016	Comments: Replace Generator Bearings every 1050 hours		Hours	218	08/29/2008	218
073, 300 hr Battery Cables & Receptacles	Inspection	Tailcone	H2431017	Comments: Inspect every 300 hours		Hours	-12	01/24/2008	0

N40PK



Page 3 of 15

Learjet (Bombardier)

35A

HOUR METER

12647.70

S/N: 35-260
TT: 12,647.70

CYC: 8,968
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
074, 12 Month Emergency Locator Transmitter (FAR 91.207)	Inspection	J2563001				Date	0	08/01/2008	189
	Empennage			Comments:	Inspect batteries and Perform Functional check every 12 months				
075, 2 yr CVR, Underwater Locating Beacon	Inspection	F2565000				Date	0	11/29/2009	675
	Tailcone			Comments:	Perform functional check every 2 years				
076, 600 hr Horizontal Stab Actuator	Inspection	H2740021				Hours	377	02/04/2009	377
	Empennage			Comments:	Inspect every 600 Hours				
080a, 1400 hr Generator Drive Spline - Left	Inspection	E2431030				Hours	950	08/31/2010	950
	E1			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
080b, 1400 hr Generator Drive Spline - Right	Inspection	E2431030				Hours	886	06/28/2010	886
	E2			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
081a, 1400 hr Engine Fire Detector Element - Left	Inspection	E2610020				Hours	950	08/31/2010	950
	E1			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
081a, 1400 hr Engine Fire Detector Element - Right	Inspection	E2610020				Hours	886	06/28/2010	886
	E2			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
082a, 1400 hr Nacelle Inlet - Left	Inspection	E302001				Hours	950	08/31/2010	950
	E1			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
082a, 1400 hr Nacelle Inlet - Right	Inspection	E302001				Hours	886	06/28/2010	886
	E2			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
083a, 1400 hr High Pressure Bleed Air Hoses - Left	Inspection	E3610001				Hours	950	08/31/2010	950
	E1			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
083a, 1400 hr High Pressure Bleed Air Hoses - Right	Inspection	E3610001				Hours	886	06/28/2010	886
	E2			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
084a, 1400 hr Engine Mount Castings - Left	Inspection	E7120024				Hours	950	08/31/2010	950
	E1			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
084b, 1400 hr Engine Mount Castings - Right	Inspection	E7120024				Hours	886	06/28/2010	886
	E2			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
085a, 12 yr Engine Mounts NDT - Left	Inspection	E120029/E7120034				Date	0	08/01/2019	4206
	E1			Comments:	Perform complete MPI of Mounts and related parts as specified in Chapter 5 every 12 years or nearest MPI prior to 12 Year Insp				

Learjet (Bombardier)

35A

HOUR METER

12647.70

S/N: 35-260

CYC: 8,968

TT: 12,647.70

RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN	
		LOC								
085b, 12 yr Engine Mounts NDT - Right	Inspection	E2	E120029/E7120034	Comments:	Perform complete MPI of Mounts and related parts as specified in Chapter 5 every 12 years or nearest MPI prior to 12 Year Insp	Date	0	08/01/2019	4206	
086a, 1400 hr FWD engine Mount Casting NDT - Left	Inspection	E1	D7120031	Comments:	AD87-02-06 par B Inspect at every Major Engine Inspection/Unscheduled Engine Change	Hours	950	08/31/2010	950	
086a, 1400 hr FWD engine Mount Casting NDT - Right	Inspection	E2	D7120031	Comments:	AD87-02-06 par B. Inspect at every Major Engine Inspection/Unscheduled Engine Change	Hours	886	06/28/2010	886	
087a, 1400 hr Engine Mount Isolator - Left	Inspection	E1	L7120063	Comments:	Inspect FWD and AFT Isolators at every MPI	Hours	950	08/31/2010	950	
087b, 1400 hr Engine Mount Isolator - Right	Inspection	E2	L7120063	Comments:	Inspect FWD and AFT Isolators at every MPI	Hours	886	06/28/2010	886	
088a, 1400 hr AFT Engine Attach Bolt - Left	Inspection	E1	L7120067	2652002	Comments:	Perform Fluorsecent Penetrant Inspection at every MPI	Hours	950	08/31/2010	950
088b, 1400 hr AFT Engine Attach Bolt - Right	Inspection	E2	L7120067	2652002	Comments:	Perform Fluorsecent Penetrant Inspection at every MPI	Hours	886	06/28/2010	886
089a, 1400 hr Fuel Computer Wiring Harness - Left	Inspection	E1	E7611001	Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change	Hours	950	08/31/2010	950	
089b, 1400 hr Fuel Computer Wiring Harness - Right	Inspection	E2	E7611001	Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change	Hours	886	06/28/2010	886	
090a, 1400 hr Engine Exhaust Nozzle - Left	Inspection	E1	E7810005	Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change	Hours	950	08/31/2010	950	
090b, 1400 hr Engine Exhaust Nozzle - Right	Inspection	E2	E7810005	Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change	Hours	886	06/28/2010	886	
091a, 1400 hr Starter Oil Change - Left	Inspection	E1	E8010004	Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change	Hours	950	08/31/2010	950	
091b, 1400 hr Starter Oil Change - Right	Inspection	E2	E8010004	Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change	Hours	950	08/31/2010	950	
092, 24 Month Lower Cabin Door	Inspection	Fuselage	L5210025	Comments:	Inspect every 24 months	Date	0	08/01/2009	554	

N40PK



Learjet (Bombardier)
35A

S/N: 35-260
TT: 12,647.70

CYC: 8,968
RIN:

HOUR METER

12647.70

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
093, 12 yr Aft Pressure Bulkhead	Inspection	J5320006				Cycles	3712	11/14/2015	2851
	Fuselage			Comments:	Inspect Frame 22, FS421.42 for corrosion every 12 years/6,000 landings				
096, 2,000 hr Nose Steering Servo (P/N 6608278)	Inspection	C3255001	6608278			Hours	847	05/20/2010	847
	Nose			Comments:	Inspect every 2,000 hours				
097, 5 yr Oxygen Bottle Hydro	Inspection	J3500016	DOT3AA1800 (STEEL)			Date	0	05/04/2009	465
	Nose			Comments:	Hydro Inspection every 5 years (DOT3AA1800) STEEL				
099a, 6 yr Emergency Air Bottle - Hydro (6600194-6)	Inspection	H3610006	6600194-6			Date	0	11/14/2009	660
	Nose			Comments:	Hydrostatic Check due every 6 years				
099b, 12 yr Emergency Air Bottle - X-Ray (6600194-6)	Inspection	H3610006	6600194-6			Date	0	11/14/2009	660
	Nose			Comments:	X-Ray due every 12 years				
101, 600 hr A/C Motor Brush Wear	Inspection	K2150010				Hours	377	02/04/2009	377
	Tailcone			Comments:	Perform brush wear check every 600 hours				
102, 1200 hr A/C Motor Fan - Dye Penetrant	Inspection	K2150028				Hours	420	03/19/2009	420
	Tailcone			Comments:	Perform Dye Penetrant Insp every 1200 hours				
103, 600 hr A/C Pressure Switch	Inspection	L2150051				Hours	377	02/04/2009	377
	Tailcone			Comments:	Perfrom functional check of A/C pressure Switch evert 600 hours.				
104, 6 month Battery Installation	Inspection	B2432010				Date	0	07/11/2008	168
	Tailcone			Comments:	Inspect Mainship Battery Installation every 6 months				
105, 6 month Drag Chute	Inspection	E2562001				Date	0	07/11/2008	168
	Tailcone			Comments:	Functional Check every 6 months				
106, 6 month Engine Fire Bottles	Inspection	B2620005				Date	0	07/11/2008	168
	Tailcone			Comments:	Pressure & Plumbing checks every 6 months				
107, 12 month Engine Fire Bottles	Inspection	E2620010				Date	0	08/01/2008	189
	Tailcone			Comments:	Perform weight check every 12 months				
108a, 5 yr Engine Fire Bottle, Left - Hydro	Inspection	C2620025				Date	0	06/22/2011	1244
	Tailcone			Comments:	Hydrostatic check every 5 years				
108b, 5 yr Engine Fire Bottle, Right - Hydro	Inspection	C2620025				Date	0	06/22/2011	1244
	Tailcone			Comments:	Hydrostatic check every 5 years.				

N40PK



Page 6 of 15

Learjet (Bombardier)
35A

S/N: 35-260
TT: 12,647.70

CYC: 8,968
RIN:

HOUR METER

12647.70

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
109a,	1400 hr Pylon Beam Structure- Left	Inspection	J5450043/J5450045			Hours	950	08/31/2010	950
		E1		Comments:	Inspect every MPI				
109b,	1400 hr Pylon Beam Structure- Right	Inspection	J5450043/J5450045			Hours	886	06/28/2010	886
		E2		Comments:	Inspect every MPI				
110a,	12 yr Engine Beam Support Fittings - Left	Inspection	H5450044			Date	0	08/01/2019	4206
		E1		Comments:	Perform Eddy Current Inspection every 12 years				
110b,	12 yr Engine Beam Support Fittings - Right	Inspection	H5450044			Date	0	08/01/2019	4206
		E2		Comments:	Perform Eddy Current Inspection every 12 years				
111,	1200 hr Flap Cam Follower Bearings	Inspection	H2750044			Hours	750	02/12/2010	750
		Wing		Comments:	Detailed Visual Inspection Left & Right every 1,200 hours				
112,	1200 hr Flap Track Attach Fittings	Inspection	H2750048			Hours	750	02/12/2010	750
		Wing		Comments:	Visual Inspect Left & Right every 1,200 hours				
113,	24 month Tip Tank Flapper Valves (P/N S-461)	Inspection	M2812003			Date	0	08/01/2009	554
		Wing		Comments:	Inspect every 24 months				
114,	24 month Tip Tanks	Inspection	L2812001			Date	0	08/01/2009	554
		Wing		Comments:	Inspect every 24 months				
115,	24 month Internal Wing	Inspection	L2812020			Date	0	08/01/2009	554
		Wing		Comments:	Inspect every 24 months				
116,	24 month Dry Bays	Inspection	L5710035			Date	0	08/01/2009	554
		Wing		Comments:	Inspect every 24 months				
117,	1200 hr Flap Track Support Fittings	Inspection	H5750046			Hours	750	02/12/2010	750
		Wing		Comments:	Detailed Visual Inspection every 1,200 hours				
203,	12 yr Keelbeam Attach Bolts	Component	E5322000			Cycles	5739	08/01/2019	4206
		Fuselage		Comments:	Replace bolts FWD & AFT bolts every 12 years or 6,000 landings				
204,	12 yr Right Essential A and B Bus (40 Amp) Circuit Breaker	Component	G2431045	35-202 & Sub		Cycles	5739	08/01/2019	4206
		Cockpit		Comments:	Replace every 12 years or 6,000 landings				
205,	12 yr Left Essential A and B Bus (40 Amp) Circuit Breaker	Component	G2431047	35-202 & Sub		Cycles	5739	08/01/2019	4206
		Cockpit		Comments:	Replace every 12 years or 6,000 landings				

N40PK



Page 7 of 15

Learjet (Bombardier)
35A

HOUR METER

12647.70

S/N: 35-260
TT: 12,647.70CYC: 8,968
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
206,	12 yr MAIN BUS TIE (50 Amp) Circuit Breaker	Component	G2431049			Cycles	5739	08/01/2019	4206
		Cockpit		Comments:	Replace every 12 years or 6,000 landings				
209,	CVR ULB Battery	Component	F2566000			Date	0	11/14/2008	295
		Tailcone		Comments:	Replace battery on or before due date				
210,	2400 hour Pri Rudder Flight Control Cables	Component	F2720012			Hours	1670	08/20/2012	1670
		Empennage		Comments:	Replace every 2,400 hours				
211,	20,000 hr Rudder Assembly	Component	E2720018	2633001		Hours	7352	03/11/2028	7352
		Empennage		Comments:	Replacve every 20,000 hours				
212,	20,000 hr Rudder Hinge Bolts	Component	E2720021	NAS144A23 & AN4H11A		Hours	7352	03/11/2028	7352
		Empennage		Comments:	Replacve every 20,000 hours				
213,	20,000 hr Rudder Lower Bearing Assy	Component	E2720023	2312040		Hours	7352	03/11/2028	7352
		Empennage		Comments:	Replacve every 20,000 hours				
214,	20,000 hr Rudder Hinge Assy - Upper	Component	E2720024	2331030		Hours	7352	03/11/2028	7352
		Empennage		Comments:	Replacve every 20,000 hours				
215,	20,000 hr Rudder Hinge Assy - Lower	Component	E2720025	2331031		Hours	7352	03/11/2028	7352
		Empennage		Comments:	Replacve every 20,000 hours				
216,	2400 hr Pri Elevator Flight Control Cables	Component	F2730015			Hours	1670	08/20/2012	1670
		Empennage		Comments:	Replace every 2,400, hours				
217a,	20,000 hr Evelator Assy - Left	Component	E2730016	2434000		Hours	7352	03/11/2028	7352
		Empennage		Comments:	Replace every 20,000 hours				
217b,	20,000 hr Evelator Assy - Right	Component	E2730016	2434000		Hours	7352	03/11/2028	7352
		Empennage		Comments:	Replace every 20,000 hours				
218a,	20,000 hr Elevator Hinge Brackets - Left	Component	E2730020			Hours	7352	03/11/2028	7352
		Empennage		Comments:	Replace Outboard, Center, Inboard every 20,000 hours				
218b,	20,000 hr Elevator Hinge Brackets - Right	Component	E2730020			Hours	7352	03/11/2028	7352
		Empennage		Comments:	Replace Outboard, Center, Inboard every 20,000 hours				
219a,	20,000 hr Elevator Hinge Bellcranks - Left	Component	E2730021	2331511		Hours	7352	03/11/2028	7352
		Empennage		Comments:	Replace every 20,000 hours				

N40PK



Page 8 of 15

Learjet (Bombardier)
35A

HOUR METER

12647.70

S/N: 35-260
TT: 12,647.70

CYC: 8,968
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
219b, 20,000 hr Elevator Hinge Bellcranks - Right	Component	E2730021	2331511			Hours	7352	03/11/2028	7352
	Empennage			Comments:	Replace every 20,000 hours				
220a, 20,000 hr Elevator Dual Push-Pull Rods - Left	Component	E2730023	2331510			Hours	7352	03/11/2028	7352
	Empennage			Comments:	Replace every 20,000 hours				
220b, 20,000 hr Elevator Dual Push-Pull Rods - Right	Component	E2730023	2331510			Hours	7352	03/11/2028	7352
	Empennage			Comments:	Replace every 20,000 hours				
221a, 20,000 hr Elevator Hinge Bolts - Left	Component	E2730024	AN4H11A			Hours	7352	03/11/2028	7352
	Empennage			Comments:	Replace every 20,000 hours				
221b, 20,000 hr Elevator Hinge Bolts - Right	Component	E2730024	AN4H11A			Hours	7352	03/11/2028	7352
	Empennage			Comments:	Replace every 20,000 hours				
222, 12 yr Elevator Downspring Drawbolt Bushing	Component	E2730026	2631507-7			Cycles	2451	11/12/2011	1388
	Empennage			Comments:	Replace every 12 years or 6,000 landings				
223, 12 yr Elevator Downspring Assy Attach Bolt	Component	E2730027	AN23-16			Cycles	2451	11/12/2011	1388
	Empennage			Comments:	Replace every 12 years or 6,000 landings				
224, 12 yr Elevator Downspring Assy Attach Bushings	Component	E2730028	2631507-6			Cycles	2451	11/12/2011	1388
	Empennage			Comments:	Replace every 12 years or 6,000 landings				
225, 20,000 hr Horizontal Stab Hinge Pin	Component	E2740010	2331028			Hours	7352	03/11/2028	7352
	Empennage			Comments:	Replace every 20,000 hours				
226, 12 yr Horizontal Stab Act Attach Bolts	Component	G2740011	NAS464P6			Cycles	3712	11/14/2015	2851
	Empennage			Comments:	Replace every 12 years or 6,000 landings				
229a, 4200 hr FWD Engine Shock Mount Cover - Upper - Left	Component	K7120036	LM-833-3			Hours	2728	07/14/2015	2728
	E1			Comments:	Replace every 4,200 hours				
229b, 4200 hr FWD Engine Shock Mount Cover - Lower - Left	Component	K7120036	LM-833-3			Hours	2728	07/14/2015	2728
	E1			Comments:	Replace every 4,200 hours				
230a, 4200 hr FWD Engine Shock Mount Cover - Upper - Right	Component	K7120036	LM-833-3			Hours	3686	02/26/2018	3686
	E2			Comments:	Replace every 4,200 hours				
230b, 4200 hr FWD Engine Shock Mount Cover - Upper - Right	Component	K7120036	LM-833-3			Hours	3686	02/26/2018	3686
	E2			Comments:	Replace every 4,200 hours				

Learjet (Bombardier)

35A

HOUR METER

12647.70

S/N: 35-260

CYC: 8,968

TT: 12,647.70

RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
231a, 8400 hr Aft Engine Isolator Assy - Left	Component	L7120037	6600309-3			Hours	2561	01/28/2015	2561
	E1			Comments:	Replace every 8,400 hours. assy (6600309-3), housing (LM-833-30), center bonding joint (LM-833-16) or aft assy (6600309-005)				
231b, 8400 hr Aft Engine Isolator Assy - Right	Component	L7120037	6600309-3			Hours	3426	06/11/2017	3426
	E2			Comments:	Replace every 8,400 hours. assy (6600309-3), housing (LM-833-30), center bonding joint (LM-833-16) or aft assy (6600309-005)				
232a, 20,000 hr FWD Engine Mount Bolts - Left	Component	E7120038	2651026			Hours	7352	03/11/2028	7352
	E1			Comments:	Replace bolts every 20,000 hours				
232b, 20,000 hr FWD Engine Mount Bolts - Right	Component	E7120038	2651026			Hours	7352	03/11/2028	7352
	E2			Comments:	Replace bolts every 20,000 hours				
233a, 20,000 hr AFT Engine Attach Bolts - Left	Component	E7120039	2652002 & 2651027			Hours	7352	03/11/2028	7352
	E1			Comments:	Replace bolts every 20,000 hours				
233b, 20,000 hr AFT Engine Attach Bolts - Right	Component	E7120039	2652002 & 2651027			Hours	7352	03/11/2028	7352
	E2			Comments:	Replace bolts every 20,000 hours				
234a, 20,000 hr Fwd Upper & Lower Engine Shock Support Bolts - Left	Component	E7120040	6600187 & NAS1307-3H			Hours	7352	03/11/2028	7352
	E1			Comments:	Replace bolts every 20,000 hours				
234b, 20,000 hr Fwd Upper & Lower Engine Shock Support Bolts - Right	Component	E7120040	6600187 & NAS1307-3H			Hours	7352	03/11/2028	7352
	E2			Comments:	Replace bolts every 20,000 hours				
235a, 20,000 hr AFT Engine Shock Mount Attach Bolts - Left	Component	E7120041	NAS335CP23			Hours	7352	03/11/2028	7352
	E1			Comments:	Replace bolts every 20,000 hours				
235b, 20,000 hr AFT Engine Shock Mount Attach Bolts - Right	Component	E7120041	NAS335CP23			Hours	7352	03/11/2028	7352
	E2			Comments:	Replace bolts every 20,000 hours				
236a, 4200 hr FWD Engine Shock Mount Bolts - Left	Component	K7120064	NAS1304-1H			Hours	2728	07/14/2015	2728
	E1			Comments:	Replace bolts every 4,200 hours				
236b, 4200 hr FWD Engine Shock Mount Bolts - Right	Component	K7120064	NAS1304-1H			Hours	3686	02/26/2018	3686
	E2			Comments:	Replace bolts every 4,200 hours				
237a, 8400 hr FWD Engine Shock Mount Mounting Assy - Left	Component	L7120065	LM-833-1			Hours	6928	01/12/2027	6928
	E1			Comments:	Replace Assy every 8,400 hours				
237b, 8400 hr FWD Engine Shock Mount Mounting Assy - Right	Component	L7120065	LM-833-1			Hours	2027	08/12/2013	2027
	E2			Comments:	Replace Assy every 8,400 hours				

N40PK



Page 10 of 15

Learjet (Bombardier)

35A

HOUR METER

12647.70

S/N: 35-260

CYC: 8,968

TT: 12,647.70

RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
238a, 8400 hr FWD Engine Shock Mount Housing - Left	Component	L7120066	LM-833-2		Hours	6928	01/12/2027	6928	
	E1		Comments:	Replace every 8,400 hours					
238b, 8400 hr FWD Engine Shock Mount Housing - Right	Component	L7120066	LM-833-2		Hours	3426	06/11/2017	3426	
	E2		Comments:	Replace every 8,400 hours					
240a, 9000 cycle Main Gear Strut - Left	Component	E3211070	2341100 or 2341101		Cycles	32	02/25/2008	32	
	Left Gear		Comments:	Replace every 9,000 landings (w/cylinder 2341100 or 2341101)					
240b, 9000 cycle Main Gear Strut - Right	Component	E3211070	2341100 or 2341101		Cycles	32	02/25/2008	32	
	Right Gear		Comments:	Replace every 9,000 landings (w/cylinder 2341100 or 2341101)					
241a, 9000 cycles Main Gear Actuator Pin - Left	Component	E3211072	2341109		Cycles	32	02/25/2008	32	
	Left Gear		Comments:	Replace every 9,000 Landings (2341109)					
241b, 9000 cycles Main Gear Actuator Pin - Right	Component	E3211072	2341109		Cycles	32	02/25/2008	32	
	Right Gear		Comments:	Replace every 9,000 Landings (2341109)					
242a, 12,000 cycle Main Gear Strut - Left	Component	E3211075	2441011		Cycles	3032	05/13/2016	3032	
	Left Gear		Comments:	Replace every 12,000 landings (w/cylinder 2441011)					
242b, 12,000 cycle Main Gear Strut - Right	Component	E3211075	2441011		Cycles	3032	05/13/2016	3032	
	Right Gear		Comments:	Replace every 12,000 landings (w/cylinder 2441011)					
243a, 18,000 cycles Main Gear Actuator Pillar Assy - Left	Component	E3211080	2341123-1 & 2341123-14		Cycles	9032	10/16/2032	9032	
	Left Gear		Comments:	Replace every 18,000 landings (2341123-1 & -14)					
243b, 18,000 cycles Main Gear Actuator Pillar Assy - Right	Component	E3211080	2341123-1 & 2341123-14		Cycles	9032	10/16/2032	9032	
	Right Gear		Comments:	Replace every 18,000 landings (2341123-1 & -14)					
244, 20,000 cycles Nose Gear Strut	Component	E3211082	2342100		Cycles			11032	
	Nose		Comments:	Replace every 20,000 Landings (2342100)				Scheduled	
245, 20,000 cycles Nose Gear Actuator	Component	E3211083	2317100		Cycles			11032	
	Nose		Comments:	Replace every 20,000 landings (2317100)				Scheduled	
246a, 20,000 cycles Main Gear Actuator Pin - Left	Component	E3211084	5441101		Cycles			11032	
	Left Gear		Comments:	Replace every 20,000 Landings				Scheduled	
246b, 20,000 cycles Main Gear Actuator Pin - Right	Component	E3211084	5441101		Cycles			11032	
	Right Gear		Comments:	Replace every 20,000 Landings				Scheduled	

N40PK



Page 11 of 15

Learjet (Bombardier)

35A

HOUR METER

12647.70

S/N: 35-260
TT: 12,647.70

CYC: 8,968
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
247a, 20,000 cycles Main Gear Actuator Pillar Assy - Left	Component	E3211085	2341123-18			Cycles			11032
	Left Gear		Comments:	Replace every 20,000 landings (2341123-18)					Scheduled
247b, 20,000 cycles Main Gear Actuator Pillar Assy - Right	Component	E3211085	2341123-18			Cycles			11032
	Right Gear		Comments:	Replace every 20,000 landings (2341123-18)					Scheduled
248a, 20,000 cycles Main Gear Actuator - Left	Component	E3211087	2327100			Cycles			11032
	Left Gear		Comments:	Replace every 20,000 landings (2327100)					Scheduled
248b, 20,000 cycles Main Gear Actuator - Right	Component	E3211087	2327100			Cycles			11032
	Right Gear		Comments:	Replace every 20,000 landings (2327100)					Scheduled
249a, 12,000 cycle Main Gear Strut - Left	Component	F3211094	6041101			Cycles	3032	05/13/2016	3032
	Left Gear		Comments:	Replace every 12,000 landings (w/cylinder 6041101)					
249b, 12,000 cycle Main Gear Strut - Right	Component	F3211094	6041101			Cycles	3032	05/13/2016	3032
	Right Gear		Comments:	Replace every 12,000 landings (w/cylinder 6041101)					
252a, 4 yr Engine Fire Bottle Squibs - Left	Component	E2620040	M13083-5			Date	0	02/24/2008	31
	Tailcone		Comments:	Replace every 4 years.					
252b, 4 yr Engine Fire Bottle Squibs - Right	Component	E2620040	M13083-5			Date	0	02/24/2008	31
	Tailcone		Comments:	Replace every 4 years.					
253, 2400 hr Pri Aileron Flight Control Cables	Component	F2710009				Hours	1669	08/19/2012	1669
	Wing		Comments:	Replace every 2,400 hours					
254a, 3600 hr Aileron Drive Yoke Bolts - Left	Component	E2710010	NAS1104-38D			Hours	464	05/02/2009	464
	Left Wing		Comments:	Replace every 3,600 hours					
254b, 3600 hr Aileron Drive Yoke Bolts - Right	Component	E2710010	NAS1104-38D			Hours	464	05/02/2009	464
	Right Wing		Comments:	Replace every 3,600 hours					
255a, 3600 hr Aileron Center Hinge Bolt - Left	Component	E2710014	AN4H13A			Hours	464	05/02/2009	464
	Left Wing		Comments:	Replace every 3,600 hours					
255b, 3600 hr Aileron Center Hinge Bolt - Right	Component	E2710014	AN4H13A			Hours	464	05/02/2009	464
	Right Wing		Comments:	Replace every 3,600 hours					
256a, 20,000 hr Aileron Assy - Left	Component	G2710016				Hours	7352	03/11/2028	7352
	Left Wing		Comments:	Replace every 20,000 hours					

N40PK



Page 12 of 15

Learjet (Bombardier)

35A

HOUR METER

12647.70

S/N: 35-260
TT: 12,647.70

CYC: 8,968
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
256b, 20,000 hr	Aileron Assy - Right	Component	G2710016			Hours	7352	03/11/2028	7352
		Right Wing		Comments:	Replace every 20,000 hours				
257a, 20,000 hr	Aileron Clevis Bolt - Left	Component	E2710020	NAS464P4		Hours	7352	03/11/2028	7352
		Left Wing		Comments:	Replace every 20,000 hours (NAS464P4)				
257b, 20,000 hr	Aileron Clevis Bolt - Right	Component	E2710020	NAS464P4		Hours	7352	03/11/2028	7352
		Right Wing		Comments:	Replace every 20,000 hours (NAS464P4)				
258a, 20,000 hr	Aileron Inbd & Outbd Hinge Bolt - Left	Component	M2710021	AN4H12A		Hours	7352	03/11/2028	7352
		Left Wing		Comments:	Replace every 20,000 hours				
258b, 20,000 hr	Aileron Inbd & Outbd Hinge Bolt - Right	Component	M2710021	AN4H12A		Hours	7352	03/11/2028	7352
		Right Wing		Comments:	Replace every 20,000 hours				
259a, 20,000 hr	Aileron Pulley Assy - Left	Component	E2710023	2324513		Hours	7352	03/11/2028	7352
		Left Wing		Comments:	Replace every 20,000 hours (2324513)				
259b, 20,000 hr	Aileron Pulley Assy - Right	Component	E2710023	2324513		Hours	7352	03/11/2028	7352
		Right Wing		Comments:	Replace every 20,000 hours (2324513)				
260a, 20,000 hr	Aileron Clevis - Left	Component	E2710025	2324512 or 2324517		Hours	7352	03/11/2028	7352
		Left Wing		Comments:	Replace every 20,000 hours				
260b, 20,000 hr	Aileron Clevis - Right	Component	E2710025	2324512 or 2324517		Hours	7352	03/11/2028	7352
		Right Wing		Comments:	Replace every 20,000 hours				
261a, 20,000 hr	Aileron Yoke Assy - Left	Component	E2710027	2324511 or 2324518		Hours	7352	03/11/2028	7352
		Left Wing		Comments:	Replace every 20,000 hours				
261b, 20,000 hr	Aileron Yoke Assy - Right	Component	E2710027	2324511 or 2324518		Hours	7352	03/11/2028	7352
		Right Wing		Comments:	Replace every 20,000 hours				
262a, 20,000 hr	Aileron Bearing Support Assy - Left	Component	E2710029	2324505 or 2324510		Hours	7352	03/11/2028	7352
		Left Wing		Comments:	Replace every 20,000 hours				
262b, 20,000 hr	Aileron Bearing Support Assy - Right	Component	E2710029	2324505 or 2324510		Hours	7352	03/11/2028	7352
		Right Wing		Comments:	Replace every 20,000 hours				
263a, 20,000 hr	Aileron Hinge Bracket Assy - Left	Component	E2710031	2322530		Hours	7352	03/11/2028	7352
		Left Wing		Comments:	Replace every 20,000 hours				

N40PK



Page 13 of 15

Learjet (Bombardier)

35A

HOUR METER

12647.70

S/N: 35-260
TT: 12,647.70

CYC: 8,968
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
263b, 20,000 hr	Aileron Hinge Bracket Assy - Right	Component	E2710031	2322530		Hours	7352	03/11/2028	7352
		Right Wing		Comments:	Replace every 20,000 hours				
264a, 1200 hr	Flap Nose Roller Bushings - Left	Component	E2750002	NAS76A4		Hours	420	03/19/2009	420
		Left Flap		Comments:	Replace every 1,200 Hours				
264b, 1200 hr	Flap Nose Roller Bushings - Right	Component	E2750002	NAS76A4		Hours	420	03/19/2009	420
		Right Flap		Comments:	Replace every 1,200 Hours				
265a, 19,300 hr	Flap Assy - Left	Component	E2750015	2325010		Hours	6652	04/11/2026	6652
		Left Flap		Comments:	Replace every 19,300 hours (2325010) P/N 2625010 not life limited				
265b, 19,300 hr	Flap Assy - Right	Component	E2750015	2325010		Hours	6652	04/11/2026	6652
		Right Flap		Comments:	Replace every 19,300 hours (2325010) P/N 2625010 not life limited				
266a, 20,000 hr	Inboard Flap Hinge Fitting - Left	Component	F2750017	2625023		Hours	7352	03/11/2028	7352
		Left Flap		Comments:	Replace every 20,000 hours				
266b, 20,000 hr	Inboard Flap Hinge Fitting - Right	Component	F2750017	2625023		Hours	7352	03/11/2028	7352
		Right Flap		Comments:	Replace every 20,000 hours				
267a, 20,000 hr	Outboard Flap Hinge Fitting - Left	Component	F2750019	2625024		Hours	7352	03/11/2028	7352
		Left Flap		Comments:	Repalce every 20,000 Hours				
267b, 20,000 hr	Outboard Flap Hinge Fitting - Right	Component	F2750019	2625024		Hours	7352	03/11/2028	7352
		Right Flap		Comments:	Repalce every 20,000 Hours				
268a, 20,000 hr	Inbd & Outbd Flap Track Assy - Left	Component	E2750021	2325022		Hours	7352	03/11/2028	7352
		Left Flap		Comments:	Replace every 20,000 hours				
268b, 20,000 hr	Inbd & Outbd Flap Track Assy - Right	Component	E2750021	2325022		Hours	7352	03/11/2028	7352
		Right Flap		Comments:	Replace every 20,000 hours				
269a, 20,000 hr	Inbd Flap Nose Roller Track - Left	Component	E2750023	2322511		Hours	7352	03/11/2028	7352
		Left Flap		Comments:	Replace every 20,000 hours				
269b, 20,000 hr	Inbd Flap Nose Roller Track - Right	Component	E2750023	2322511		Hours	7352	03/11/2028	7352
		Right Flap		Comments:	Replace every 20,000 hours				
270a, 20,000 hr	Outbd Flap Nose Roller Track - Left	Component	E2750024	2322512		Hours	7352	03/11/2028	7352
		Left Flap		Comments:	Replace every 20,000 hours				

N40PK



Page 14 of 15

Learjet (Bombardier)

35A

HOUR METER

12647.70

S/N: 35-260

CYC: 8,968

TT: 12,647.70

RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
270b, 20,000 hr Outbd Flap Nose Roller Track - Right	Component	E2750024	2322512			Hours	7352	03/11/2028	7352
	Right Flap			Comments:	Replace every 20,000 hours				
271a, 12 yr Wing Flap Sector Mount Bolt - Left	Component	G2750034				Cycles	5739	08/03/2019	4208
	Left Wing			Comments:	Replace every 12 years or 6,000 landings				
271b, 12 yr Wing Flap Sector Mount Bolt - Right	Component	G2750034				Cycles	5739	08/03/2019	4208
	Right Wing			Comments:	Replace every 12 years or 6,000 landings				
275a, 9000 hr 1/4" Spoiler Actuator Bolt - Left	Component	E2760066	NAS464P4			Hours	5304	08/02/2022	5304
	Left Spoiler			Comments:	Replace bolt every 9000 hours				
275b, 9000 hr 1/4" Spoiler Actuator Bolt - Right	Component	E2760066	NAS464P4			Hours	5304	08/02/2022	5304
	Right Spoiler			Comments:	Replace bolt every 9000 hours				
276a, 9000 hr 5/16" Spoiler Attach Bolts - Left	Component	E2760067	NAS464P5			Hours	5304	08/02/2022	5304
	Left Spoiler			Comments:	Replace bolts every 9000 hours				
276b, 9000 hr 5/16" Spoiler Attach Bolts - Right	Component	E2760067	NAS464P5			Hours	5304	08/02/2022	5304
	Right Spoiler			Comments:	Replace bolts every 9000 hours				
277a, 9000 hr 5/16" Spoiler Pivot Bolt - Left	Component	E2760068	NAS464P5			Hours	5304	08/02/2022	5304
	Left Spoiler			Comments:	Replace bolts every 9000 hours				
277a, 9000 hr 5/16" Spoiler Pivot Bolt - Right	Component	E2760068	NAS464P5			Hours	5304	08/02/2022	5304
	Right Spoiler			Comments:	Replace bolts every 9000 hours				
278a, 9000 hr Spoiler Assy - Left	Component	E2760069	2422510-71 & Sub			Hours	-15	01/24/2008	0
	Left Spoiler			Comments:	Replace spoiler p/n 2422510-71 & Sub every 9000 hours				
278b, 9000 hr Spoiler Assy - Right	Component	E2760069	2422510-71 & Sub			Hours	-15	01/24/2008	0
	Right Spoiler			Comments:	Replace spoiler p/n 2422510-71 & Sub every 9000 hours				
279a, 9000 hr Spoiler Actuator Arm Assy - Left	Component	E2760071	2422511			Hours	5304	08/02/2022	5304
	Left Spoiler			Comments:	Replace every 9000 hours				
279b, 9000 hr Spoiler Actuator Arm Assy - Right	Component	E2760071	2422511			Hours	5304	08/02/2022	5304
	Right Spoiler			Comments:	Replace every 9000 hours				
280a, 20,000 hr Spoiler Actuator Fitting and Bolt - Left	Component	E2760076	2422513 & BACB30MT4, BAD			Hours	7352	03/11/2028	7352
	Left Spoiler			Comments:	Replace fitting and bolt every 20,000 hours				

N40PK

Learjet (Bombardier)
35AS/N: 35-260
TT: 12,647.70CYC: 8,968
RIN:HOUR METER **12647.70**

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
280a,	20,000 hr Spoiler Actuator Fitting and Bolt - Right	Component	E2760076	2422513 & BACB30MT4, BAD		Hours	7352	03/11/2028	7352
		Right Spoiler		Comments:	Replace fitting and bolt every 20,000 hours				
301,	Medical Litter	Inspection				Date	0	07/11/2008	168
		Cabin		Comments:	Inspect every 6 months				
302,	Medical Litter	Inspection				Date	0	07/07/2008	164
		Cabin		Comments:	Inspect ever 12 months				
304,	ELT Battery	Component				Date	0	09/30/2010	979
		Empennage		Comments:	Replace battery on or before due date				
305,	Part 135 Avionics Functional Check	Inspection				Date	0	06/27/2008	154
				Comments:	Inspect every 24 months				
306,	Aircraft Reweigh (FAR135.185)	Inspection				Date	0	06/30/2008	157
				Comments:	Reweigh every 3 yrs.				
307,	Altimeters and Transponders (FAR 91.411 & 91.413)	Inspection				Date	0	03/17/2009	417
				Comments:	Certify Every 24 months				
308,	GPS Update	Inspection				Date	0	02/16/2008	23
				Comments:	Update every 30 days				