

N55FN



Page 1 of 16

Learjet (Bombardier)

35A

HOUR METER

11576.50

S/N: 35-202
TT: 11,576.50

CYC: 9,654
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	LOC	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
001,	300 hr Phase A1 through A6		Inspection	05-10-01			Hours	25	10/12/2008	8
					Comments:	C/W at (a) 300 hrs. or (b) 1 yrs.				
002,	600 hr Phase B1 through B6		Inspection	05-10-07			Hours	325	10/12/2009	108
					Comments:	C/W at (a) 600 hrs. or (b) 2 yrs.				
003,	1200 hr Phase C1 through C6		Inspection	05-10-13			Hours	925	10/12/2011	308
					Comments:	C/W at (a) 1,200 hrs. or (b) 4 yrs.				
004,	2400 hr Phase D1 through D6		Inspection	05-10-19			Hours	36	02/05/2010	12
					Comments:	C/W at (a) 2,400 hrs. or (b) 8 yrs.				
005,	3,000 Landings		Inspection	05-10-25			Cycles	2319	05/31/2014	2319
					Comments:	Inspect every 3,000 landings.				
006,	6,000 Landings (Major Landing Gear Insp.)		Inspection	05-10-26			Cycles	2336	06/17/2014	2336
					Comments:	Inspect every 6,000 landings.				
007,	12 Year Airframe		Inspection	05-10-27			Cycles	4639	06/04/2014	2322
					Comments:	C/W every (a) 6,000 cycles or (b) 12 yrs.				
008,	12,000 Hour Airframe		Inspection	05-10-28			Hours	3525	04/13/2011	1175
					Comments:	C/W at 12,000 hrs. then every 6000 hours after				
021,	74-08-08 Rv.2, Lavatory & Receptacle Placards	Cabin	AD	11-30-			Hours	725	09/21/2008	241
					Comments:	Inspect every 1,000 hrs. in/a/w SB 35/36-11-04				
022,	82-01-05 Rv.2, Accelerometer (Stall Warning)		AD	27-40-62			Hours	111	03/01/2008	37
					Comments:	Operational check every 220 hrs. in/a/w SB 35/36-27-12				
023a,	87-02-06, 420 hr Fwd. Engine Mount Casting - Left	Left	AD				Hours	145	03/12/2008	48
					Comments:	Visual insp. every 420 hrs. in/a/w SB 35/36-71-3.				
023b,	87-02-06, 420 hr Fwd. Engine Mount Casting - Right	Right	AD				Hours	145	03/12/2008	48
					Comments:	Visual insp. every 420 hrs. in/a/w SB 35/36-71-3				
024a,	87-02-06, 1500 hr Fwd. Engine Mount Casting - Left	Left	AD				Hours	1225	03/07/2009	408
					Comments:	Inspect (NDT) every 1,500 hrs. in/a/w SB 35/36-71-3.				
024b,	87-02-06, 1500 hr Fwd. Engine Mount Casting - Right	Right	AD				Hours	96	02/25/2008	32
					Comments:	Inspect (NDT) every 1,500 hrs. in/a/w SB 35/36-71-3				

N55FN



Page 2 of 16

Learjet (Bombardier)
35A

S/N: 35-202
TT: 11,576.50

CYC: 9,654
RIN:

HOUR METER **11576.50**

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
025a, 04-03-08, 1200 hr Pylon/Engine Beam Structure - Left	AD	Left		Comments: Inspect every 1,200 hrs. in/a/w SB 35/36-51-3		Hours	1516	06/12/2009	505
025b, 04-03-08, 1200 hr Pylon/Engine Beam Structure - Right	AD	Right		Comments: Inspect every 1,200 hrs. in/a/w SB 35/36-51-3		Hours	1516	06/12/2009	505
056, Life Vest	Inspection	Cabin	C2561000	Comments: Recertify per manufacturer's instructions		Date	0	01/31/2008	7
059, 30 day Hand Held Fire Extinguisher	Inspection	Cabin		Comments: Visually inspect every 30 days		Date	0	01/26/2008	2
064a, Cap Check #1 Main Ship Battery (Concorde)	Inspection	Tailcone	G1222002	Comments: Cap check at 12 months or 600 hours, then every 3 months or 200 hours		Hours	224	09/15/2008	74
064b, Cap Check #2 Main Ship Battery (Concorde)	Inspection	Tailcone	G1222002	Comments: Cap check at 12 months or 600 hours, then every 3 months or 200 hours		Hours	224	09/15/2008	74
067, 6 Month Emergency Power Supply (PS835)	Inspection	Nose	F1223010	PS835 Comments: Ops Check every 6 months.		Date	0	06/27/2008	154
068, 12 Month Emergency Power Supply (PS835)	Inspection	Nose	D1223015	PS835 Comments: Perform discharge/recharge every 12 months		Date	0	12/27/2008	338
070, 1200 hr Cabin Leak Rate	Inspection	Cabin	H2130007	Comments: Perform cabin leak rate check every 1,200 hours		Hours	925	11/27/2008	308
071a, 2000 hr Generator Overhaul (Left)	Inspection	E1	C2431015	Comments: Overhaul Generator every 2000 hours		Hours	1627	07/19/2009	542
071b, 2000 hr Generator Overhaul (Right)	Inspection	E2	C2431015	Comments: Overhaul Generator every 2000 hours		Hours	1116	01/30/2009	372
072a, 1050 hr Generator Bearing (Left)	Inspection	E1	C2431016	Comments: Replace Generator Bearings every 1050 hours		Hours	677	09/05/2008	225
072b, 1050 hr Generator Bearing (Right)	Inspection	E2	C2431016	Comments: Replace Generator Bearings every 1050 hours		Hours	166	03/19/2008	55
073, 300 hr Battery Cables & Receptacles	Inspection	Tailcone	H2431017	Comments: Inspect every 300 hours		Hours	25	02/01/2008	8

N55FN



Page 3 of 16

Learjet (Bombardier)

35A

HOUR METER

11576.50

S/N: 35-202
TT: 11,576.50

CYC: 9,654
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
074, 12 Month Emergency Locator Transmitter (FAR 91.207)	Inspection	J2563001				Date	0	06/22/2008	149
	Empennage			Comments:	Inspect batteries and Perform Functional check every 12 months				
075, 2 yr CVR, Underwater Locating Beacon	Inspection	F2565000				Date	0	04/13/2009	444
	Tailcone			Comments:	Perform functional check every 2 years				
076, 600 hr Horizontal Stab Actuator	Inspection	H2740021	2332540-214			Hours	548	07/24/2008	182
	Empennage			Comments:	Inspect every 600 Hours P/N 2332540-214				
080a, 1400 hr Generator Drive Spline - Left	Inspection	E2431030				Hours	1125	02/02/2009	375
	E1			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
080b, 1400 hr Generator Drive Spline - Right	Inspection	E2431030				Hours	-4	01/24/2008	0
	E2			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
081a, 1400 hr Engine Fire Detector Element - Left	Inspection	E2610020				Hours	1125	02/02/2009	375
	E1			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
081a, 1400 hr Engine Fire Detector Element - Right	Inspection	E2610020				Hours	-4	01/24/2008	0
	E2			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
082a, 1400 hr Nacelle Inlet - Left	Inspection	E302001				Hours	1125	02/02/2009	375
	E1			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
082a, 1400 hr Nacelle Inlet - Right	Inspection	E302001				Hours	-4	01/24/2008	0
	E2			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
083a, 1400 hr High Pressure Bleed Air Hoses - Left	Inspection	E3610001				Hours	1125	02/02/2009	375
	E1			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
083a, 1400 hr High Pressure Bleed Air Hoses - Right	Inspection	E3610001				Hours	-4	01/24/2008	0
	E2			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
084a, 1400 hr Engine Mount Castings - Left	Inspection	E7120024				Hours	1125	02/02/2009	375
	E1			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
084b, 1400 hr Engine Mount Castings - Right	Inspection	E7120024				Hours	-4	01/24/2008	0
	E2			Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
086a, 1400 hr FWD engine Mount Casting NDT - Left	Inspection	D7120031				Hours	1125	02/02/2009	375
	E1			Comments:	AD87-02-06 par B Inspect at every Major Engine Inspection/Unscheduled Engine Change				

01/24/2008

www.Tdata.com

Copyright © 2007 Tdata, Inc. All rights reserved.

N55FN



Page 4 of 16

Learjet (Bombardier)

35A

HOUR METER

11576.50

S/N: 35-202
TT: 11,576.50

CYC: 9,654
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	LOC	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
086a,	1400 hr FWD engine Mount Casting NDT - Right	E2	Inspection	D7120031			Hours	-4	01/24/2008	0
					Comments:	AD87-02-06 par B. Inspect at every Major Engine Inspection/Unscheduled Engine Change				
087a,	1400 hr Engine Mount Isolator - Left	E1	Inspection	L7120063			Hours	1125	02/02/2009	375
					Comments:	Inspect FWD and AFT Isolators at every MPI				
087b,	1400 hr Engine Mount Isolator - Right	E2	Inspection	L7120063			Hours	-4	01/24/2008	0
					Comments:	Inspect FWD and AFT Isolators at every MPI				
088a,	1400 hr AFT Engine Attach Bolt - Left	E1	Inspection	L7120067	2652002		Hours	1125	02/02/2009	375
					Comments:	Perform Fluorescent Penetrant Inspection at every MPI				
088b,	1400 hr AFT Engine Attach Bolt - Right	E2	Inspection	L7120067	2652002		Hours	-4	01/24/2008	0
					Comments:	Perform Fluorescent Penetrant Inspection at every MPI				
089a,	1400 hr Fuel Computer Wiring Harness - Left	E1	Inspection	E7611001			Hours	1125	02/02/2009	375
					Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
089b,	1400 hr Fuel Computer Wiring Harness - Right	E2	Inspection	E7611001			Hours	-4	01/24/2008	0
					Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
090a,	1400 hr Engine Exhaust Nozzle - Left	E1	Inspection	E7810005			Hours	1125	02/02/2009	375
					Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
090b,	1400 hr Engine Exhaust Nozzle - Right	E2	Inspection	E7810005			Hours	-4	01/24/2008	0
					Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
091a,	1400 hr Starter Oil Change - Left	E1	Inspection	E8010004			Hours	1125	02/02/2009	375
					Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
091b,	1400 hr Starter Oil Change - Right	E2	Inspection	E8010004			Hours	-4	01/24/2008	0
					Comments:	Inspect at every Major Engine Inspection/Unscheduled Engine Change				
092,	24 Month Lower Cabin Door	Fuselage	Inspection	L5210025			Date	0	02/28/2008	35
					Comments:	Inspect every 24 months				
093,	12 yr Aft Pressure Bulkhead	Fuselage	Inspection	J5320006			Cycles	4639	06/30/2014	2348
					Comments:	Inspect Frame 22, FS421.42 for corrosion every 12 years/6,000 landings				
096,	2,000 hr Nose Steering Servo (P/N 6608278)	Nose	Inspection	C3255001	6608278		Hours	1123	02/01/2009	374
					Comments:	Inspect every 2,000 hours				

N55FN



Page 5 of 16

Learjet (Bombardier)
35A

HOUR METER **11576.50**

S/N: 35-202
TT: 11,576.50

CYC: 9,654
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
097,	5 yr Oxygen Bottle Hydro	Inspection	J3500016	DOT3AA1800 (STEEL)		Date	0	04/13/2012	1540
	Nose			Comments:	Hydro Inspection every 5 years (DOT3AA1800) STEEL				
100a,	3 yr Emergency Air Bottle - Hydro	Inspection	N3610043	6600194-4		Date	0	01/05/2009	347
	Nose			Comments:	Perform Hydro every 3 years				
100b,	9 yr Emergency Air Bottle - X-Ray	Inspection	N3610043	6600194-4		Date	0	09/30/2012	1710
	Nose			Comments:	Perform X-Ray inspection at 9 at years				
100c,	12 yr Emergency Air Bottle - X-Ray	Inspection	N3610043	6600194-4		Date	0	09/30/2009	614
	Nose			Comments:	Perform X-Ray inspection at 12 at years				
100d,	15 yr Emergency Air Bottle - MPI	Inspection	N3610043	6600194-4		Date	0	09/30/2009	614
	Nose			Comments:	Perform X-Ray, Hydro, and Magnetic Particle inspection at 15 years, and every 2 years thereafter				
101,	600 hr A/C Motor Brush Wear	Inspection	K2150010			Hours	325	05/11/2008	108
	Tailcone			Comments:	Perform brush wear check every 600 hours				
102,	1200 hr A/C Motor Fan - Dye Penetrant	Inspection	K2150028			Hours	925	11/27/2008	308
	Tailcone			Comments:	Perform Dye Penetrant Insp every 1200 hours				
103,	600 hr A/C Pressure Switch	Inspection	L2150051			Hours	325	05/11/2008	108
	Tailcone			Comments:	Perfrom functional check of A/C pressure Switch evert 600 hours.				
104,	6 month Battery Installation	Inspection	B2432010			Date	0	06/27/2008	154
	Tailcone			Comments:	Inspect Mainship Battery Installation every 6 months				
105,	6 month Drag Chute	Inspection	E2562001			Date	0	06/27/2008	154
	Tailcone			Comments:	Functional Check every 6 months				
106,	6 month Engine Fire Bottles	Inspection	B2620005			Date	0	06/27/2008	154
	Tailcone			Comments:	Pressure & Plumbing checks every 6 months				
107,	12 month Engine Fire Bottles	Inspection	E2620010			Date	0	06/22/2008	149
	Tailcone			Comments:	Perform weight check every 12 months				
108a,	5 yr Engine Fire Bottle, Left - Hydro	Inspection	C2620025			Date	0	06/22/2012	1610
	Tailcone			Comments:	Hydrostatic check every 5 years				
108b,	5 yr Engine Fire Bottle, Right - Hydro	Inspection	C2620025			Date	0	04/30/2008	96
	Tailcone			Comments:	Hydrostatic check every 5 years.				

N55FN



Page 6 of 16

Learjet (Bombardier)

35A

HOUR METER

11576.50

S/N: 35-202
TT: 11,576.50

CYC: 9,654
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
109a, 1400 hr Pylon Beam Structure- Left	Inspection	J5450043/J5450045				Hours	1125	02/02/2009	375
	E1			Comments:	Inspect every MPI				
109b, 1400 hr Pylon Beam Structure- Right	Inspection	J5450043/J5450045				Hours	-4	01/24/2008	0
	E2			Comments:	Inspect every MPI				
110a, 12 yr Engine Beam Support Fittings - Left	Inspection	H5450044				Date	0	06/04/2014	2322
	E1			Comments:	Perform Eddy Current Inspection every 12 years				
110b, 12 yr Engine Beam Support Fittings - Right	Inspection	H5450044				Date	0	06/04/2014	2322
	E2			Comments:	Perform Eddy Current Inspection every 12 years				
111, 1200 hr Flap Cam Follower Bearings	Inspection	H2750044				Hours	925	11/27/2008	308
	Wing			Comments:	Detailed Visual Inspection Left & Right every 1,200 hours				
112, 1200 hr Flap Track Attach Fittings	Inspection	H2750048				Hours	925	11/27/2008	308
	Wing			Comments:	Visual Inspect Left & Right every 1,200 hours				
113, 24 month Tip Tank Flapper Valves (P/N S-461)	Inspection	M2812003				Date	0	02/27/2008	34
	Wing			Comments:	Inspect every 24 months				
114, 24 month Tip Tanks	Inspection	L2812001				Date	0	02/27/2008	34
	Wing			Comments:	Inspect every 24 months				
115, 24 month Internal Wing	Inspection	L2812020				Date	0	02/20/2008	27
	Wing			Comments:	Inspect every 24 months				
116, 24 month Dry Bays	Inspection	L5710035				Date	0	02/28/2008	35
	Wing			Comments:	Inspect every 24 months				
117, 1200 hr Flap Track Support Fittings	Inspection	H5750046				Hours	925	11/27/2008	308
	Wing			Comments:	Detailed Visual Inspection every 1,200 hours				
201, 12 yr Fuel Hose Assemblies	Component	G2820002				Cycles	5433	12/15/2017	3613
	Fuselage			Comments:	Replace Flexible fuel hoses every 12 years or 6,000 landings				
202, 12 yr Hydraulic Hose Assemblies	Component	G2900001				Cycles	5448	02/27/2018	3687
	Fuselage			Comments:	Replace flexible hydraulic hoses every 12 years or 6,000 landings				
203, 12 yr Keelbeam Attach Bolts	Component	E5322000				Cycles	2336	08/31/2009	584
	Fuselage			Comments:	Replace bolts FWD & AFT bolts every 12 years or 6,000 landings				

N55FN



Page 7 of 16

Learjet (Bombardier)

35A

HOUR METER

11576.50

S/N: 35-202
TT: 11,576.50

CYC: 9,654
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
204,	12 yr Right Essential A and B Bus (40 Amp) Circuit Breaker	Component Cockpit	G2431045	35-202 & Sub		Cycles	5448	02/27/2018	3687
				Comments:	Replace every 12 years or 6,000 landings				
205,	12 yr Left Essential A and B Bus (40 Amp) Circuit Breaker	Component Cockpit	G2431047	35-202 & Sub		Cycles	5448	02/27/2018	3687
				Comments:	Replace every 12 years or 6,000 landings				
206,	12 yr MAIN BUS TIE (50 Amp) Circuit Breaker	Component Cockpit	G2431049			Cycles	5448	02/27/2018	3687
				Comments:	Replace every 12 years or 6,000 landings				
209,	CVR ULB Battery	Component Tailcone	F2566000			Date	0	03/30/2013	1891
				Comments:	Replace battery on or before due date				
210,	2400 hour Pri Rudder Flight Control Cables	Component Empennage	F2720012			Hours	36	02/05/2008	12
				Comments:	Replace every 2,400 hours				
211,	20,000 hr Rudder Assembly	Component Empennage	E2720018	2633001		Hours	8423	10/01/2015	2807
				Comments:	Replacve every 20,000 hours				
212,	20,000 hr Rudder Hinge Bolts	Component Empennage	E2720021	NAS144A23 & AN4H11A		Hours	8423	10/01/2015	2807
				Comments:	Replacve every 20,000 hours				
213,	20,000 hr Rudder Lower Bearing Assy	Component Empennage	E2720023	2312040		Hours	8423	10/01/2015	2807
				Comments:	Replacve every 20,000 hours				
214,	20,000 hr Rudder Hinge Assy - Upper	Component Empennage	E2720024	2331030		Hours	8423	10/01/2015	2807
				Comments:	Replacve every 20,000 hours				
215,	20,000 hr Rudder Hinge Assy - Lower	Component Empennage	E2720025	2331031		Hours	8423	10/01/2015	2807
				Comments:	Replacve every 20,000 hours				
216,	2400 hr Pri Elevator Flight Control Cables	Component Empennage	F2730015			Hours	36	02/05/2008	12
				Comments:	Replace every 2,400, hours				
217a,	20,000 hr Evelator Assy - Left	Component Empennage	E2730016	2434000		Hours	8423	10/01/2015	2807
				Comments:	Replace every 20,000 hours				
217b,	20,000 hr Evelator Assy - Right	Component Empennage	E2730016	2434000		Hours	8423	10/01/2015	2807
				Comments:	Replace every 20,000 hours				
218a,	20,000 hr Elevator Hinge Brackets - Left	Component Empennage	E2730020			Hours	8423	10/01/2015	2807
				Comments:	Replace Outboard, Center, Inboard every 20,000 hours				

N55FN



Page 8 of 16

Learjet (Bombardier)

35A

HOUR METER

11576.50

S/N: 35-202

CYC: 9,654

TT: 11,576.50

RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
218b, 20,000 hr Elevator Hinge Brackets - Right	Component	E2730020				Hours	8423	10/01/2015	2807
	Empennage			Comments:	Replace Outboard, Center, Inboard every 20,000 hours				
219a, 20,000 hr Elevator Hinge Bellcranks - Left	Component	E2730021	2331511			Hours	8423	10/01/2015	2807
	Empennage			Comments:	Replace every 20,000 hours				
219b, 20,000 hr Elevator Hinge Bellcranks - Right	Component	E2730021	2331511			Hours	8423	10/01/2015	2807
	Empennage			Comments:	Replace every 20,000 hours				
220a, 20,000 hr Elevator Dual Push-Pull Rods - Left	Component	E2730023	2331510			Hours	8423	10/01/2015	2807
	Empennage			Comments:	Replace every 20,000 hours				
220b, 20,000 hr Elevator Dual Push-Pull Rods - Right	Component	E2730023	2331510			Hours	8423	10/01/2015	2807
	Empennage			Comments:	Replace every 20,000 hours				
221a, 20,000 hr Elevator Hinge Bolts - Left	Component	E2730024	AN4H11A			Hours	8423	10/01/2015	2807
	Empennage			Comments:	Replace every 20,000 hours				
221b, 20,000 hr Elevator Hinge Bolts - Right	Component	E2730024	AN4H11A			Hours	8423	10/01/2015	2807
	Empennage			Comments:	Replace every 20,000 hours				
222, 12 yr Elevator Downspring Drawbolt Bushing	Component	E2730026	2631507-7			Cycles	2336	08/31/2009	584
	Empennage			Comments:	Replace every 12 years or 6,000 landings				
223, 12 yr Elevator Downspring Assy Attach Bolt	Component	E2730027	AN23-16			Cycles	2336	08/31/2009	584
	Empennage			Comments:	Replace every 12 years or 6,000 landings				
224, 12 yr Elevator Downspring Assy Attach Bushings	Component	E2730028	2631507-6			Cycles	2336	08/31/2009	584
	Empennage			Comments:	Replace every 12 years or 6,000 landings				
225, 20,000 hr Horizontal Stab Hinge Pin	Component	E2740010	2331028			Hours	8423	10/01/2015	2807
	Empennage			Comments:	Replace every 20,000 hours				
226, 12 yr Horizontal Stab Act Attach Bolts	Component	G2740011	NAS464P6			Cycles	2336	03/31/2016	2336
	Empennage			Comments:	Replace every 12 years or 6,000 landings				
227a, 2400 hr Fuel Hoses Engine Nacelle, Left	Component	G7110021				Hours	1535	06/18/2009	511
	E1			Comments:	Replace every 2,400 hours or 5 years				
227b, 2400 hr Fuel Hoses Engine Nacelle, Right	Component	G7110021				Hours	1535	06/18/2009	511
	E2			Comments:	Replace every 2,400 hours or 5 years				

Learjet (Bombardier)

35A

HOUR METER

11576.50

S/N: 35-202

CYC: 9,654

TT: 11,576.50

RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	LOC	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
228a,	2400 hr Hydraulic Hoses Engine Nacelle, Left	E1	Component	G7110022			Hours	1535	06/18/2009	511
					Comments:	Replace every 2,400 hours or 5 years				
228a,	2400 hr Hydraulic Hoses Engine Nacelle, Right	E2	Component	G7110022			Hours	1535	06/18/2009	511
					Comments:	Replace every 2,400 hours or 5 years				
229a,	4200 hr FWD Engine Shock Mount Cover - Upper - Left	E1	Component	K7120036	LM-833-3		Hours	2204	01/27/2010	734
					Comments:	Replace every 4,200 hours				
229b,	4200 hr FWD Engine Shock Mount Cover - Lower - Left	E1	Component	K7120036	LM-833-3		Hours	2204	01/27/2010	734
					Comments:	Replace every 4,200 hours				
230a,	4200 hr FWD Engine Shock Mount Cover - Upper - Right	E2	Component	K7120036	LM-833-3		Hours	2204	01/27/2010	734
					Comments:	Replace every 4,200 hours				
230b,	4200 hr FWD Engine Shock Mount Cover - Upper - Right	E2	Component	K7120036	LM-833-3		Hours	2204	01/27/2010	734
					Comments:	Replace every 4,200 hours				
231a,	8400 hr Aft Engine Isolator Assy - Left	E1	Component	L7120037	6600309-3		Hours	2290	02/25/2010	763
					Comments:	Replace every 8,400 hours. assy (6600309-3), housing (LM-833-30), center bonding joint (LM-833-16) or aft assy (6600309-005)				
231b,	8400 hr Aft Engine Isolator Assy - Right	E2	Component	L7120037	6600309-3		Hours	6996	06/13/2014	2332
					Comments:	Replace every 8,400 hours. assy (6600309-3), housing (LM-833-30), center bonding joint (LM-833-16) or aft assy (6600309-005)				
232a,	20,000 hr FWD Engine Mount Bolts - Left	E1	Component	E7120038	2651026		Hours	8423	10/01/2015	2807
					Comments:	Replace bolts every 20,000 hours				
232b,	20,000 hr FWD Engine Mount Bolts - Right	E2	Component	E7120038	2651026		Hours	8423	10/01/2015	2807
					Comments:	Replace bolts every 20,000 hours				
233a,	20,000 hr AFT Engine Attach Bolts - Left	E1	Component	E7120039	2652002 & 2651027		Hours	8423	10/01/2015	2807
					Comments:	Replace bolts every 20,000 hours				
233b,	20,000 hr AFT Engine Attach Bolts - Right	E2	Component	E7120039	2652002 & 2651027		Hours	8423	10/01/2015	2807
					Comments:	Replace bolts every 20,000 hours				
234a,	20,000 hr Fwd Upper & Lower Engine Shock Support Bolts - Left	E1	Component	E7120040	6600187 & NAS1307-3H		Hours	8423	10/01/2015	2807
					Comments:	Replace bolts every 20,000 hours				
234b,	20,000 hr Fwd Upper & Lower Engine Shock Support Bolts - Right	E2	Component	E7120040	6600187 & NAS1307-3H		Hours	8423	10/01/2015	2807
					Comments:	Replace bolts every 20,000 hours				

N55FN



Page 10 of 16

Learjet (Bombardier)

35A

HOUR METER

11576.50

S/N: 35-202

CYC: 9,654

TT: 11,576.50

RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
235a, 20,000 hr AFT Engine Shock Mount Attach Bolts - Left	Component	E7120041	NAS335CP23			Hours	8423	10/01/2015	2807
	E1		Comments:	Replace bolts every 20,000 hours					
235b, 20,000 hr AFT Engine Shock Mount Attach Bolts - Right	Component	E7120041	NAS335CP23			Hours	8423	10/01/2015	2807
	E2		Comments:	Replace bolts every 20,000 hours					
236a, 4200 hr FWD Engine Shock Mount Bolts - Left	Component	K7120064	NAS1304-1H			Hours	3337	02/09/2011	1112
	E1		Comments:	Replace bolts every 4,200 hours					
236b, 4200 hr FWD Engine Shock Mount Bolts - Right	Component	K7120064	NAS1304-1H			Hours	3337	02/09/2011	1112
	E2		Comments:	Replace bolts every 4,200 hours					
237a, 8400 hr FWD Engine Shock Mount Mounting Assy - Left	Component	L7120065	LM-833-1			Hours	7537	12/10/2014	2512
	E1		Comments:	Replace Assy every 8,400 hours					
237b, 8400 hr FWD Engine Shock Mount Mounting Assy - Right	Component	L7120065	LM-833-1			Hours	7537	12/10/2014	2512
	E2		Comments:	Replace Assy every 8,400 hours					
238a, 8400 hr FWD Engine Shock Mount Housing - Left	Component	L7120066	LM-833-2			Hours	7537	12/10/2014	2512
	E1		Comments:	Replace every 8,400 hours					
238b, 8400 hr FWD Engine Shock Mount Housing - Right	Component	L7120066	LM-833-2			Hours	7537	12/10/2014	2512
	E2		Comments:	Replace every 8,400 hours					
242a, 12,000 cycle Main Gear Strut - Left	Component	E3211075	2441011			Cycles	2346	06/27/2014	2346
	Left Gear		Comments:	Replace every 12,000 landings (w/cylinder 2441011)					
242b, 12,000 cycle Main Gear Strut - Right	Component	E3211075	2441011			Cycles	2346	06/27/2014	2346
	Right Gear		Comments:	Replace every 12,000 landings (w/cylinder 2441011)					
243a, 18,000 cycles Main Gear Actuator Pillar Assy - Left	Component	E3211080	2341123-1 & 2341123-14			Cycles	8346	11/30/2030	8346
	Left Gear		Comments:	Replace every 18,000 landings (2341123-1 & -14)					
243b, 18,000 cycles Main Gear Actuator Pillar Assy - Right	Component	E3211080	2341123-1 & 2341123-14			Cycles	8346	11/30/2030	8346
	Right Gear		Comments:	Replace every 18,000 landings (2341123-1 & -14)					
244, 20,000 cycles Nose Gear Strut	Component	E3211082	2342100			Cycles			19448
	Nose		Comments:	Replace every 20,000 Landings (2342100)					Scheduled
245, 20,000 cycles Nose Gear Actuator	Component	E3211083	2317100			Cycles			19448
	Nose		Comments:	Replace every 20,000 landings (2317100)					Scheduled

N55FN



Page 11 of 16

Learjet (Bombardier)
35A

HOUR METER

11576.50

S/N: 35-202
TT: 11,576.50

CYC: 9,654
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
246a,	20,000 cycles Main Gear Actuator Pin - Left	Component	E3211084	5441101		Cycles			19329
	Left Gear			Comments:	Replace every 20,000 Landings				Scheduled
246b,	20,000 cycles Main Gear Actuator Pin - Right	Component	E3211084	5441101		Cycles			19329
	Right Gear			Comments:	Replace every 20,000 Landings				Scheduled
247a,	20,000 cycles Main Gear Actuator Pillar Assy - Left	Component	E3211085	2341123-18		Cycles	10346		10346
	Left Gear			Comments:	Replace every 20,000 landings (2341123-18)				Scheduled
247b,	20,000 cycles Main Gear Actuator Pillar Assy - Right	Component	E3211085	2341123-18		Cycles	10346		10346
	Right Gear			Comments:	Replace every 20,000 landings (2341123-18)				Scheduled
248a,	20,000 cycles Main Gear Actuator - Left	Component	E3211087	2327100		Cycles			19463
	Left Gear			Comments:	Replace every 20,000 landings (2327100)				Scheduled
248b,	20,000 cycles Main Gear Actuator - Right	Component	E3211087	2327100		Cycles			16342
	Right Gear			Comments:	Replace every 20,000 landings (2327100)				Scheduled
249a,	1000 cycle Main Gear Strut - Left	Inspection	F3211094	6041101		Cycles	319	12/08/2008	319
	Left Gear			Comments:	1000 cycle inspection per STC ST00814WI				
249b,	12,000 cycle Main Gear Strut - Right	Component	F3211094	6041101		Cycles			11319
	Right Gear			Comments:	Replace every 12,000 landings (w/cylinder 6041101)				Scheduled
250,	12 yr Emergency Air Hoses	Component	L3233013			Cycles	5448	02/27/2018	3687
	Fuselage			Comments:	Repalce every 12 years or 6,000 landings				
252a,	4 yr Engine Fire Bottle Squibs - Left	Component	E2620040	M13083-5		Date	0	04/13/2011	1174
	Tailcone			Comments:	Replace every 4 years.				
252b,	4 yr Engine Fire Bottle Squibs - Right	Component	E2620040	M13083-5		Date	0	06/22/2011	1244
	Tailcone			Comments:	Replace every 4 years.				
253,	2400 hr Pri Aileron FLight Control Cables	Component	F2710009			Hours	36	02/05/2008	12
	Wing			Comments:	Replace every 2,400 hours				
254a,	3600 hr Aileron Drive Yoke Bolts - Left	Component	E2710010	NAS1104-38D		Hours	2565	05/28/2010	855
	Left Wing			Comments:	Replace every 3,600 hours				
254b,	3600 hr Aileron Drive Yoke Bolts - Right	Component	E2710010	NAS1104-38D		Hours	2565	05/28/2010	855
	Right Wing			Comments:	Replace every 3,600 hours				

N55FN



Page 12 of 16

Learjet (Bombardier)
35A

S/N: 35-202
TT: 11,576.50

CYC: 9,654
RIN:

HOUR METER **11576.50**

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
255a, 3600 hr Aileron Center Hinge Bolt - Left	Component	E2710014	AN4H13A			Hours	2565	05/28/2010	855
	Left Wing			Comments:	Replace every 3,600 hours				
255b, 3600 hr Aileron Center Hinge Bolt - Right	Component	E2710014	AN4H13A			Hours	2565	05/28/2010	855
	Right Wing			Comments:	Replace every 3,600 hours				
256a, 20,000 hr Aileron Assy - Left	Component	G2710016				Hours	8423	10/01/2015	2807
	Left Wing			Comments:	Replace every 20,000 hours				
256b, 20,000 hr Aileron Assy - Right	Component	G2710016				Hours	8423	10/01/2015	2807
	Right Wing			Comments:	Replace every 20,000 hours				
257a, 20,000 hr Aileron Clevis Bolt - Left	Component	E2710020	NAS464P4			Hours	11999		3999
	Left Wing			Comments:	Replace every 20,000 hours (NAS464P4)				
257b, 20,000 hr Aileron Clevis Bolt - Right	Component	E2710020	NAS464P4			Hours	11999		3999
	Right Wing			Comments:	Replace every 20,000 hours (NAS464P4)				
258a, 20,000 hr Aileron Inbd & Outbd Hinge Bolt - Left	Component	M2710021	AN4H12A			Hours	8423	10/01/2015	2807
	Left Wing			Comments:	Replace every 20,000 hours				
258b, 20,000 hr Aileron Inbd & Outbd Hinge Bolt - Right	Component	M2710021	AN4H12A			Hours	8423	10/01/2015	2807
	Right Wing			Comments:	Replace every 20,000 hours				
259a, 20,000 hr Aileron Pulley Assy - Left	Component	E2710023	2324513			Hours	8423	10/01/2015	2807
	Left Wing			Comments:	Replace every 20,000 hours (2324513)				
259b, 20,000 hr Aileron Pulley Assy - Right	Component	E2710023	2324513			Hours	8423	10/01/2015	2807
	Right Wing			Comments:	Replace every 20,000 hours (2324513)				
260a, 20,000 hr Aileron Clevis - Left	Component	E2710025	2324512 or 2324517			Hours	8423	10/01/2015	2807
	Left Wing			Comments:	Replace every 20,000 hours				
260b, 20,000 hr Aileron Clevis - Right	Component	E2710025	2324512 or 2324517			Hours	8423	10/01/2015	2807
	Right Wing			Comments:	Replace every 20,000 hours				
261a, 20,000 hr Aileron Yoke Assy - Left	Component	E2710027	2324511 or 2324518			Hours	8423	10/01/2015	2807
	Left Wing			Comments:	Replace every 20,000 hours				
261b, 20,000 hr Aileron Yoke Assy - Right	Component	E2710027	2324511 or 2324518			Hours	8423	10/01/2015	2807
	Right Wing			Comments:	Replace every 20,000 hours				

N55FN



Page 13 of 16

Learjet (Bombardier)

35A

HOUR METER

11576.50

S/N: 35-202

CYC: 9,654

TT: 11,576.50

RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
262a, 20,000 hr Aileron Bearing Support Assy - Left	Component	E2710029	2324505 or 2324510	Hours	8423	10/01/2015	2807		
	Left Wing		Comments: Replace every 20,000 hours						
262b, 20,000 hr Aileron Bearing Support Assy - Right	Component	E2710029	2324505 or 2324510	Hours	8423	10/01/2015	2807		
	Right Wing		Comments: Replace every 20,000 hours						
263a, 20,000 hr Aileron Hinge Bracket Assy - Left	Component	E2710031	2322530	Hours	8423	10/01/2015	2807		
	Left Wing		Comments: Replace every 20,000 hours						
263b, 20,000 hr Aileron Hinge Bracket Assy - Right	Component	E2710031	2322530	Hours	8423	10/01/2015	2807		
	Right Wing		Comments: Replace every 20,000 hours						
264a, 1200 hr Flap Nose Roller Bushings - Left	Component	E2750002	NAS76A4	Hours	1	01/24/2008	0		
	Left Flap		Comments: Replace every 1,200 Hours						
264b, 1200 hr Flap Nose Roller Bushings - Right	Component	E2750002	NAS76A4	Hours	1	01/24/2008	0		
	Right Flap		Comments: Replace every 1,200 Hours						
265a, 19,300 hr Flap Assy - Left	Component	E2750015	2325010	Hours	7723	02/10/2015	2574		
	Left Flap		Comments: Replace every 19,300 hours (2325010) P/N 2625010 not life limited						
265b, 19,300 hr Flap Assy - Right	Component	E2750015	2325010	Hours	7723	02/10/2015	2574		
	Right Flap		Comments: Replace every 19,300 hours (2325010) P/N 2625010 not life limited						
266a, 20,000 hr Inboard Flap Hinge Fitting - Left	Component	F2750017	2625023	Hours	8423	10/01/2015	2807		
	Left Flap		Comments: Replace every 20,000 hours						
266b, 20,000 hr Inboard Flap Hinge Fitting - Right	Component	F2750017	2625023	Hours	8423	10/01/2015	2807		
	Right Flap		Comments: Replace every 20,000 hours						
267a, 20,000 hr Outboard Flap Hinge Fitting - Left	Component	F2750019	2625024	Hours	8423	10/01/2015	2807		
	Left Flap		Comments: Repalce every 20,000 Hours						
267b, 20,000 hr Outboard Flap Hinge Fitting - Right	Component	F2750019	2625024	Hours	8423	10/01/2015	2807		
	Right Flap		Comments: Repalce every 20,000 Hours						
268a, 20,000 hr Inbd & Outbd Flap Track Assy - Left	Component	E2750021	2325022	Hours	8423	10/01/2015	2807		
	Left Flap		Comments: Replace every 20,000 hours						
268b, 20,000 hr Inbd & Outbd Flap Track Assy - Right	Component	E2750021	2325022	Hours	8423	10/01/2015	2807		
	Right Flap		Comments: Replace every 20,000 hours						

N55FN



Page 14 of 16

Learjet (Bombardier)
35A

HOUR METER

11576.50

S/N: 35-202
TT: 11,576.50

CYC: 9,654
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
269a, 20,000 hr Inbd Flap Nose Roller Track - Left	Component	E2750023	2322511			Hours	8423	10/01/2015	2807
	Left Flap			Comments:	Replace every 20,000 hours				
269b, 20,000 hr Inbd Flap Nose Roller Track - Right	Component	E2750023	2322511			Hours	8423	10/01/2015	2807
	Right Flap			Comments:	Replace every 20,000 hours				
270a, 20,000 hr Outbd Flap Nose Roller Track - Left	Component	E2750024	2322512			Hours	8423	10/01/2015	2807
	Left Flap			Comments:	Replace every 20,000 hours				
270b, 20,000 hr Outbd Flap Nose Roller Track - Right	Component	E2750024	2322512			Hours	8423	10/01/2015	2807
	Right Flap			Comments:	Replace every 20,000 hours				
271a, 12 yr Wing Flap Sector Mount Bolt - Left	Component	G2750034				Cycles	4639	06/04/2014	2322
	Left Wing			Comments:	Replace every 12 years or 6,000 landings				
271b, 12 yr Wing Flap Sector Mount Bolt - Right	Component	G2750034				Cycles	4639	06/04/2014	2322
	Right Wing			Comments:	Replace every 12 years or 6,000 landings				
275a, 9000 hr 1/4" Spoiler Actuator Bolt - Left	Component	E2760066	NAS464P4			Hours	6317	10/29/2013	2105
	Left Spoiler			Comments:	Replace bolt every 9000 hours				
275b, 9000 hr 1/4" Spoiler Actuator Bolt - Right	Component	E2760066	NAS464P4			Hours	6317	10/29/2013	2105
	Right Spoiler			Comments:	Replace bolt every 9000 hours				
276a, 9000 hr 5/16" Spoiler Attach Bolts - Left	Component	E2760067	NAS464P5			Hours	6317	10/29/2013	2105
	Left Spoiler			Comments:	Replace bolts every 9000 hours				
276b, 9000 hr 5/16" Spoiler Attach Bolts - Right	Component	E2760067	NAS464P5			Hours	6317	10/29/2013	2105
	Right Spoiler			Comments:	Replace bolts every 9000 hours				
277a, 9000 hr 5/16" Spoiler Pivot Bolt - Left	Component	E2760068	NAS464P5			Hours	6317	10/29/2013	2105
	Left Spoiler			Comments:	Replace bolts every 9000 hours				
277a, 9000 hr 5/16" Spoiler Pivot Bolt - Right	Component	E2760068	NAS464P5			Hours	6317	10/29/2013	2105
	Right Spoiler			Comments:	Replace bolts every 9000 hours				
278a, 9000 hr Spoiler Assy - Left	Component	E2760069	2422510-71 & Sub			Hours	1110	01/28/2009	370
	Left Spoiler			Comments:	Replace spoiler p/n 2422510-71 & Sub every 9000 hours				
278b, 9000 hr Spoiler Assy - Right	Component	E2760069	2422510-71 & Sub			Hours	1110	01/28/2009	370
	Right Spoiler			Comments:	Replace spoiler p/n 2422510-71 & Sub every 9000 hours				

N55FN



Page 15 of 16

Learjet (Bombardier)

35A

HOUR METER

11576.50

S/N: 35-202

CYC: 9,654

TT: 11,576.50

RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
		LOC							
279a, 9000 hr Spoiler Actuator Arm Assy - Left	Component	E2760071	2422511			Hours	6317	10/29/2013	2105
	Left Spoiler			Comments:	Replace every 9000 hours				
279b, 9000 hr Spoiler Actuator Arm Assy - Right	Component	E2760071	2422511			Hours	6317	10/29/2013	2105
	Right Spoiler			Comments:	Replace every 9000 hours				
280a, 20,000 hr Spoiler Actuator Fitting and Bolt - Left	Component	E2760076	2422513 & BACB30MT4, BAD			Hours	8423	10/01/2015	2807
	Left Spoiler			Comments:	Replace fitting and bolt every 20,000 hours				
280a, 20,000 hr Spoiler Actuator Fitting and Bolt - Right	Component	E2760076	2422513 & BACB30MT4, BAD			Hours	8423	10/01/2015	2807
	Right Spoiler			Comments:	Replace fitting and bolt every 20,000 hours				
301, Medical Litter	Inspection					Date	0	06/01/2008	128
	Cabin			Comments:	Inspect every 6 months				
302, Medical Litter	Inspection					Date	0	06/01/2008	128
	Cabin			Comments:	Inspect ever 12 months				
303, Stretcher O2 Bottle	Inspection					Date	0	05/01/2011	1192
	Cabin			Comments:	Hydro every 5 years				
304, ELT Battery	Component					Date	0	09/30/2012	1710
	Empennage			Comments:	Replace Battery every 24 months				
306, Aircraft Reweigh (FAR135.185)	Inspection					Date	0	12/15/2008	326
				Comments:	Reweigh every 3 yrs.				
307, Altimeters and Transponders (FAR 91.411 & 91.413)	Inspection					Date	0	09/20/2008	239
				Comments:	Certify Every 24 months				
308, GPS Update	Inspection					Date	0	01/26/2008	2
				Comments:	Update every 30 days				
309, 40 cycle DEEC Download	Inspection					Cycles	20	02/13/2008	20
	Tailcone			Comments:	Download DEECs every 40 cycles				
310, 24 month RVSM	Inspection					Date	0	09/22/2008	241
				Comments:	comply with every 24 months per STC				
311, 96 month RVSM	Inspection					Date	0	09/22/2014	2432
				Comments:	comply with every 96 months (8 yrs) per STC				

N55FN



Learjet (Bombardier)
35A

HOUR METER **11576.50**

S/N: 35-202
TT: 11,576.50

CYC: 9,654
RIN:

A I R C R A F T S T A T U S R E P O R T

ITEM	DESCRIPTION	LOC	TYPE	ATA	ASSY/PN	SERIAL NUMBER	TRACKED BY	UNITS REMAING	PROJECTED DATE	DAYS REMAIN
312,	144 month RVSM		Inspection				Date	0	09/22/2018	3893
					Comments:	comply with every 144 months (12yrs) per STC				
313,	24 month Pitot/Static Probe		Inspection				Date	0	09/22/2008	241
					Comments:	Inspect every 24 months				
314,	10,000 hr Pitot/Static Probe - Left		Component				Hours	9123	05/22/2016	3041
					Comments:	Replace Probe every 10,000 hours				
315,	10,000 hr Pitot/Static Probe - Right		Component				Hours	9123	05/22/2016	3041
					Comments:	Replace Probe every 10,000 hours				