



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
055601	INSPECT WINDSHIELD SURFACE RE-SEAL	MCO			MTH HRS 1450	07-Aug-2009 1450	O/C			
055602	INSPECT HUMP SEAL REPAIR *CF				MTH HRS 1450	28-Feb-2002 1450	O/C			
5-12-01 051201	PHASE 1	MCO			MTH HRS 1573.2 LDG 1064	11-Mar-2010 1573.2 1064	24 300		31-Mar-2012 1873.2	22 m 11 d 264.1
5-12-02 051202	PHASE 2	MCO			MTH HRS 1573.2 LDG 1064	11-Mar-2010 1573.2 1064	24 300		31-Mar-2012 1873.2	22 m 11 d 264.1
5-12-03 051203	PHASE 3	MCO			MTH HRS 1573.2 LDG 1064	11-Mar-2010 1573.2 1064	24 300		31-Mar-2012 1873.2	22 m 11 d 264.1
5-12-04 051204	PHASE 4	MCO			MTH HRS 1573.2 LDG 1064	11-Mar-2010 1573.2 1064	24 300		31-Mar-2012 1873.2	22 m 11 d 264.1
5-12-05 051205	PHASE 5	MCO			MTH HRS 1201	03-Apr-2008 1201	36 1200		30-Apr-2011 2401	11 m 10 d 791.9
5-12-07 051207	PHASE 7	MCO			MTH HRS 1573.2 LDG 1064	11-Mar-2010 1573.2 1064	300		1873.2	264.1
5-12-08 051208	PHASE 8	MCO			MTH HRS 1450	07-Aug-2009 1450	6		28-Feb-2010	-2 m 20 d Over Due
A262002 CABIN 051208	WEIGHT CHECK PORTABLE HALON FIRE EXTINGUISHER : PHASE 8	MCO		C352CS X-466135	MTH HRS 1450	07-Aug-2009 1450	6		28-Feb-2010	-2 m 20 d Over Due
A262002 COCKPIT 051208	WEIGHT CHECK PORTABLE HALON FIRE EXTINGUISHER : PHASE 8	MCO		C352CS X-466164	MTH HRS 1450	07-Aug-2009 1450	6		28-Feb-2010	-2 m 20 d Over Due
5-12-0B 051200B	PHASE B	MCO			MTH HRS 1573.2 LDG 1064	11-Mar-2010 1573.2 1064	150		1723.2	114.1
5-12-18 051218	PHASE 18	MCO			MTH HRS 1450	07-Aug-2009 1450	12		31-Aug-2010	3 m 11 d
5-12-20	PHASE 20				MTH	28-Feb-2002	24			
B341006 NO. 1 051220 : ADC	CALIBRATION TEST (PILOT) AIR DATA COMPUTER (FAR 91.411) : PHASE 20	MCO		7014700-914 01105776	MTH HRS 1552	29-Jan-2010 1552	24		31-Jan-2012	20 m 11 d
B341006 NO. 2 051220 : ADC#2	CALIBRATION TEST (COPILOT) AIR DATA COMPUTER (FAR 91.411): PHASE 20	MCO		7014700-914 01105703	MTH HRS 1552	29-Jan-2010 1552	24		31-Jan-2012	20 m 11 d
B341006 SECONDARY 051220 : ADU	CALIBRATION TEST FLIGHT ADU (FAR 91.411) : PHASE 20	MCO		27101-01-01 M012093	MTH HRS 1552	29-Jan-2010 1552	24		31-Jan-2012	20 m 11 d
B341007 051220	INSPECTION RVSM SKIN WAVINESS: PHASE 20	MCO			MTH HRS 1552	29-Jan-2010 1552	24		31-Jan-2012	20 m 11 d
B345001 NO. 1 051220 : XPDR	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413) : PHASE 20	MCO		7517400-902 01095966	MTH HRS 1552	29-Jan-2010 1552	24		31-Jan-2012	20 m 11 d
B345001 NO. 2 051220 : XPDR2	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413) : PHASE 20	MCO		7517400-902 01085841	MTH HRS 1552	29-Jan-2010 1552	24		31-Jan-2012	20 m 11 d

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
5-12-21	PHASE 21					MTH 28-Feb-2002	24			
A237001 051221 : CVR	INSPECT COCKPIT VOICE RECORDER COCKPIT VOICE RECORDER AND ULD: PHASE 21	MCO		2100-1020-02 000150004	MTH 29-Jan-2010 HRS 1552	24			31-Jan-2012	20 m 11 d
B237003 051221 : CVR	PINGER TEST UNDERWATER LOCATOR BEACON (USING DUKANE PL-1 TESTER) UNDERWATER LOCATOR BEACON INSTALLED ON COCKPIT VOICE RECORDER: PHASE 21	MCO		DK100 DV13017	MTH 29-Jan-2010 HRS 1552	24			31-Jan-2012	20 m 11 d
5-12-22	PHASE 22				MTH 28-Feb-2002	36				
B323004 051222 : GEAR	RESTORATION (HYDROSTATIC TEST) PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE : PHASE 22	MCO		40005347-3 3217	MTH 03-Apr-2008 HRS 1201	36	1		31-Mar-2011	10 m 11 d
5-12-23	PHASE 23				MTH 28-Feb-2002	60				
B262007 AFT 051223 : AFT	HYDROSTATIC TEST ENGINE FIRE BOTTLE : PHASE 23	MCO		30400037-1 46950B1	MTH 13-Sep-2006 HRS 937	60			30-Sep-2011	16 m 10 d
B262007 APU 051223 : APU	HYDROSTATIC TEST FIRE BOTTLE : PHASE 23	MCO		30100033 39353A1	MTH 13-Sep-2006 HRS 937	60			30-Sep-2011	16 m 10 d
B262007 FORWARD 051223 : FWD	HYDROSTATIC TEST ENGINE FIRE BOTTLE : PHASE 23	MCO		30400037-1 46657B1	MTH 13-Sep-2006 HRS 937	60			30-Sep-2011	16 m 10 d
B351003 051222 : OXY	HYDROSTATIC TEST OXYGEN CYLINDER DOT3HT-1850 OR DOT3FC-1850 MANUFACTURED UNDER DOT-E-8162: PHASE 23	MCO		804882-14 10405	MTH 03-Apr-2008 HRS 1201	60	1		31-Mar-2013	34 m 11 d
5-12-28	PHASE 28	MCO			MTH 11-Mar-2010 HRS 1573.2 LDG 1064	100				
D243002 051228	RECONDITION MAIN SHIP (UY006) BATTERY BATTERY (MAIN POWER): PHASE 28	MCO		30978-002 10103784	MTH 11-Mar-2010 HRS 1573.2 LDG 1064	100			1673.2	64.1
5-12-30 051230	PHASE 30	MCO			MTH 09-Aug-2008 HRS 1262	600			1862	252.9
5-12-47	PHASE 47				MTH 28-Feb-2002	144				
B262002 CABIN 051247 : CABIN	HYDROSTATIC TEST PORTABLE HALON FIRE EXTINGUISHER : PHASE 47	MCO		C352CS X-466135	MTH 03-Apr-2008 HRS 1201	144			30-Apr-2020	119 m 10 d
B262002 COCKPIT 051247 : CKPT	HYDROSTATIC TEST PORTABLE HALON FIRE EXTINGUISHER : PHASE 47	MCO		C352CS X-466164	MTH 03-Apr-2008 HRS 1201	144			30-Apr-2020	119 m 10 d
5-12-48	PHASE 48				MTH 28-Feb-2002	72				
B262003 CABIN 051248 : CABIN	EMPTY/INSPECT/RECHARGE PORTABLE HALON FIRE EXTINGUISHER : PHASE 48	MCO		C352CS X-466135	MTH 03-Apr-2008 HRS 1201	72			30-Apr-2014	47 m 10 d
B262003 COCKPIT 051248 : CKPT	EMPTY/INSPECT/RECHARGE PORTABLE HALON FIRE EXTINGUISHER : PHASE 48	MCO		C352CS X-466164	MTH 03-Apr-2008 HRS 1201	72			30-Apr-2014	47 m 10 d
5-12-49 051249	PHASE 49	MCO			MTH 03-Apr-2008 HRS 1201	36 1200			30-Apr-2011 2401	11 m 10 d 791.9
5-12-51 051251	PHASE 51	*CF			MTH 28-Feb-2002 HRS 0	2400			2400	790.9

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
5-12-53 051253	PHASE 53	MCO			MTH HRS	07-Aug-2009 1450	12 900		31-Aug-2010 2350	3 m 11 d 740.9
5-12-54	PHASE 54				MTH	28-Feb-2002	120			
B351005 PORTABLE 051254	HYDROSTATIC TEST OXYGEN (DOT-3AA) CYLINDER DOT-3AA: PHASE 54	*CF		PN SN-UNKNOWN	MTH	28-Feb-2002	120		29-Feb-2012	21 m 9 d
5-12-58 051258	PHASE 58	MCO			MTH APUH	19-May-2007 639		500		0
A801101 APU	INSPECT STARTER/GENERATOR AUXILIARY POWER AB UNIT (APU) STARTER GENERATOR BRUSH: PHASE 58			300SGL138Q-5 3155	MTH APUH	19-May-2007 639		500		1139 -470.1
5-12-59	PHASE 59				MTH HRS	28-Feb-2002 0	12 600			
A361101 NO. 1 ENGINE 051259 : E1**L	GENERAL VISUAL INSPECTION PRECOOLER HEAT EXCHANGER : PHASE 59				MTH HRS	07-Aug-2009 1450	12 600		31-Aug-2010 2050	3 m 11 d 440.9
A361101 NO. 2 ENGINE 051259 : E2**R	GENERAL VISUAL INSPECTION PRECOOLER HEAT EXCHANGER : PHASE 59				MTH HRS	07-Aug-2009 1450	12 600		31-Aug-2010 2050	3 m 11 d 440.9
5-12-60 051260	PHASE 60	*CF			MTH HRS	28-Feb-2002 0		2400		2400 790.9
5-12-63 051263	PHASE 63	MCO			MTH HRS	07-Aug-2009 1450	12		31-Aug-2010	3 m 11 d
5-12-66 051266	PHASE 66	*CF			MTH HRS	28-Feb-2002 0		3000		3000 1390.9
5-12-67 051267	PHASE 67	MCO			MTH HRS	07-Aug-2009 1450	12 400		31-Aug-2010 1850	3 m 11 d 240.9
5-12-68 051268	PHASE 68	MCO			MTH HRS	29-Jan-2010 1552		500		
5-12-MD 0512MD	PHASE MD	*CF			MTH HRS	28-Feb-2002 0	120 6000		29-Feb-2012 6000	21 m 9 d 4390.9
5-12-ME 0512ME	PHASE ME	*CF			MTH HRS	28-Feb-2002 0		15000		15000 13390.9
5-12-MF 0512MF	PHASE MF	*CF			MTH HRS	28-Feb-2002 0		7500		7500 5890.9
5-12-MJ 0512MJ	PHASE MJ	*CF			MTH HRS	28-Feb-2002 0		13000		13000 11390.9
5-12-ML 0512ML	PHASE ML	*CF			MTH HRS	28-Feb-2002 0		11500		11500 9890.9
5-12-MM 0512MM	PHASE MM	*CF			MTH HRS	28-Feb-2002 0		11000		11000 9390.9
5-12-MN 0512MN	PHASE MN	*CF			MTH HRS	28-Feb-2002 0		9000		9000 7390.9
5-12-MO 0512MO	PHASE MO	*CF			MTH HRS	28-Feb-2002 0		12500		12500 10890.9
057109 E1 051209 : E1**L	OIL & FILTER CHANGE	MCO			MTH HRS	03-Apr-2008 1201	24 900		30-Apr-2010 2101	-20 d 491.9
Over Due										
057109 E2 051209 : E2**R	OIL & FILTER CHANGE	MCO			MTH HRS	03-Apr-2008 1201	24 900		30-Apr-2010 2101	-20 d 491.9
Over Due										
057120 E1	INSPECTION LOW UTILIZATION	*CF			MTH	28-Feb-2002	120		29-Feb-2012	21 m 9 d

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
057120 E2	INSPECTION LOW UTILIZATION	*CF			MTH	28-Feb-2002	120		29-Feb-2012	21 m 9 d
057159 E1 051259 : E1**L	MINOR INSPECTION	MCO			MTH HRS	07-Aug-2009 1450	12 600		31-Aug-2010 2050	3 m 11 d 440.9
057159 E2 051259 : E2**R	MINOR INSPECTION	MCO			MTH HRS	07-Aug-2009 1450	12 600		31-Aug-2010 2050	3 m 11 d 440.9
312001A LEFT HAND	REPLACE BATTERY DIGITAL CLOCK	MCO		M877A5V 13037	MTH HRS	07-Aug-2009 1450	12		30-Sep-2010	4 m 10 d
312001B RIGHT HAND 312001A : 2	REPLACE BATTERY DIGITAL CLOCK	MCO		M877A5V 13038	MTH HRS	07-Aug-2009 1450	12		30-Sep-2010	4 m 10 d
054906	REPLACE FUEL NOZZLE ASSEMBLY	*CF			APUS	28-Feb-2002 0	4000	10	4000	2661
710060 E1 057902 : E1**L	CLEAN/INSPECT/TEST ENGINE WIRING HARNESS CONNECTORS	MCO			MTH HRS	13-Sep-2006 937	900		1837	227.9
710060 E2 057902 : E2**R	CLEAN/INSPECT/TEST ENGINE WIRING HARNESS CONNECTORS	MCO			MTH HRS	13-Sep-2006 937	900		1837	227.9
720010 E1 710001 : E1**L	ENGINE OVERHAUL	*CF			MTH HRS	28-Feb-2002 0	5000		5000	3390.9
720010 E2 710001 : E2**R	ENGINE OVERHAUL	*CF			MTH HRS	28-Feb-2002 0	5000		5000	3390.9
720060 E1 057102 : E1**L	HOT SECTION INSPECTION	*CF			MTH HRS	28-Feb-2002 0	2500	11	2500	890.9
720060 E2 057102 : E2**R	HOT SECTION INSPECTION	*CF			MTH HRS	28-Feb-2002 0	2500	11	2500	890.9
731030 E1 052003 : E1**L	INSTALL NEW FUEL FILTER ELEMENT	MCO			MTH HRS	03-Apr-2008 1201	24 900		30-Apr-2010 2101	-20 d 491.9
										Over Due
731030 E2 052003 : E2**R	INSTALL NEW FUEL FILTER ELEMENT	MCO			MTH HRS	03-Apr-2008 1201	24 900		30-Apr-2010 2101	-20 d 491.9
										Over Due
731100 E1 052002 : E1**L	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	MCO			MTH HRS	03-Apr-2008 1201	24 900		30-Apr-2010 2101	-20 d 491.9
										Over Due
731100 E2 052002 : E2**R	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	MCO			MTH HRS	03-Apr-2008 1201	24 900		30-Apr-2010 2101	-20 d 491.9
										Over Due
740010 E1 057401 : E1**L	CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION	MCO			MTH HRS	07-Aug-2009 1450	300		1750	140.9
740010 E2 057401 : E2**R	CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION	MCO			MTH HRS	07-Aug-2009 1450	300		1750	140.9

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
211002	EMERGENCY PRESSURIZATION FLOW (UY005) VALVE MCO			27441482-06 11AV31	MTH HRS	22-Oct-2003 337	O/C	0		
211120 LEFT	BI LEVEL VALVE 9912492-1	*CF		1988-00-3 1695A	MTH	28-Feb-2002	O/C			
211120 RIGHT	BI LEVEL VALVE 9912492-1	*CF		1988-00-3 1642A	MTH	28-Feb-2002	O/C			
212200	MOTOR AND BLOWER ASSEMBLY *CF			7003-400 297	MTH	28-Feb-2002	O/C			
213005	MANUAL TOGGLE VALVE 9912409-12	*CF		52773-114 975	MTH	28-Feb-2002	O/C			
213006	CABIN ALTITUDE (U1005) CONTROLLER 9912409-9	MCO		52770-114 1913	MTH HRS	23-Feb-2008 1176	O/C	0		
213007 PRIMARY	OUTFLOW VALVE 9912409-19	MCO		52771-314 K846B	MTH HRS	08-May-2008 1214	O/C	0		
213007 SECONDARY	OUTFLOW VALVE 9912409-11	*CF	G	52772-114 965	MTH	28-Feb-2002	O/C			
213101	ALT PRESSURE SWITCH 9910095-6	*CF		GB300NA161 0133864	MTH	28-Feb-2002	O/C			
215001	ENVIRONMENTAL CONTROL UNIT 9912493-1	*CF		2215460-2 350	MTH	28-Feb-2002	O/C			
215004	PAC OVERHEAT SWITCH 1173T0570	MCO		927223-2-1 0553	MTH HRS	11-Nov-2003 354	O/C	0		
215005	ACM COOLING TURBINE *CF			2206610-1 348	MTH	28-Feb-2002	O/C			
215006	HEAT EXCHANGER *CF			2340594-6 394	MTH	28-Feb-2002	O/C			
215100	WATER SPRAY ECU ASPIRATOR 9912493-3	*CF		2215605-1 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
215101	WATER SEPARATOR TEMP 1 SENSOR 9914130-20	MCO		1E62-1 1AV3	MTH HRS	11-Nov-2003 354	O/C	0		
216002	ENVIRONMENTAL TEMP CONTROLLER 9912518-3	*CF		1E45-11 7AU70	MTH	28-Feb-2002	O/C			
216003 NO. 1	CABIN TEMP SENSOR 9914130-3	*CF		1E47-1 6AU205	MTH	28-Feb-2002	O/C			
216003 NO. 2	CABIN TEMP SENSOR 9914130-3	*CF		1E47-1 10AT338	MTH	28-Feb-2002	O/C			
216009 CABIN	ZONE TEMPERATURE (UC021) SENSOR 9914130-6	*CF		1E46-1 12AT353	MTH	28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
216009 COCKPIT	ZONE TEMPERATURE (UF029) SENSOR 9914130-6	*CF		1E46-1 9AU175		MTH 28-Feb-2002	O/C			
216099 216100	ECU TEMP CONTROL VALVE 9912518-2	*CF		27241287-14 10AUH522		MTH 28-Feb-2002	O/C			
216100 LEFT	CABIN TEMPERATURE CONTROL (VT029) VALVE 9912518-2	*CF		27241287-14 10AU169		MTH 28-Feb-2002	O/C			
216100 RIGHT	COCKPIT TEMPERATURE CONTROL (VT030) VALVE 9912518-2	*CF		27241287-14 10AU167		MTH 28-Feb-2002	O/C			
216101 LEFT	CABIN DUCT OVERHEAT (SC013) SWITCH *CF			1173T42 2277		MTH 28-Feb-2002	O/C			
216101 RIGHT	COCKPIT DUCT OVERHEAT (SF034) SWITCH *CF			1173T42 1694		MTH 28-Feb-2002	O/C			
217001	WATER SEPARATOR 9912493-7	*CF		2341316-2 363		MTH 28-Feb-2002	O/C			
217101 LEFT	OZONE CONVERTER 9914523-2	*CF	D	31A437-1 04330790		MTH 28-Feb-2002	O/C			
217101 RIGHT	OZONE CONVERTER 9914523-2	*CF	D	31A437-1 04690911		MTH 28-Feb-2002	O/C			
221009	AUTOPILOT (PC400) CONTROLLER PC-400	MCO		7003897-923 98111532		MTH 06-Jun-2002 HRS 67	O/C		1102	
221010 AILERON	DRIVE SERVO SM-200	*CF		4006719-906 01096137		MTH 28-Feb-2002	O/C			
221010 ELEVATOR	DRIVE SERVO SM-200	ICT		4006719-906 01096185		MTH 17-Jun-2002 HRS 69	O/C		69	
221010 RUDDER	DRIVE SERVO SM-200	*CF		4006719-910 1086210		MTH 28-Feb-2002	O/C			
232003 NO. 1	COMM ANTENNA *CF			S65-8282-1 1025		MTH 28-Feb-2002	O/C			
232003 NO. 2	COMM ANTENNA *CF			21-38-1RF/36 8371		MTH 28-Feb-2002	O/C			
232004	FLITEPHONE 800 RADIOTELEPHONE (RT800) TRANCEIVER *CF A			500-10096-001 601221		MTH 28-Feb-2002	O/C			
232007	FLITEPHONE 800 RADIOTELEPHONE ANTENNA *CF			CI5000-1 1041797		MTH 28-Feb-2002	O/C			
232008 NO. 1	HONEYWELL PRIMUS II SRZ850 INTEGRATED (RCZ851) COMMUNICATION UNIT RCZ-833E	MCO		7510700-766 01117087		MTH 18-Sep-2007 HRS 1129	O/C		0	
232008 NO. 2	HONEYWELL PRIMUS II SRZ850 INTEGRATED (RCZ851) COMMUNICATION UNIT RCZ-833E	MCO		7510700-766 01086874		MTH 18-Sep-2007 HRS 1129	O/C		1129	

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
232010 NO. 1	COMM TRANSCEIVER TR-833	MCO		7510763-901 0114462	MTH HRS	18-Sep-2007 1129	O/C	0		
232010 NO. 2	COMM TRANSCEIVER TR-833	MCO		7510763-901 01084203	MTH HRS	18-Sep-2007 1129	O/C	1129		
232013 NO. 1	CLUSTER COMM MODULE XC-833	MCO		7510784-835 01056800	MTH HRS	18-Sep-2007 1129	O/C	0		
232013 NO. 2	CLUSTER COMM MODULE XC-833	MCO		7510784-835 01087284	MTH HRS	18-Sep-2007 1129	O/C	1129		
235001 NO. 1	AUDIO CONTROL PANEL AMPLIFIER AV-850A	*CF W		7511001-913 01107644	MTH HRS	28-Feb-2002 1489	O/C			
235001 NO. 2	AUDIO CONTROL PANEL AMPLIFIER AV-850A	MCO		7511001-913 91020389	MTH HRS	14-Oct-2009 1489	O/C	913		
237001	COCKPIT VOICE RECORDER FA2100	*CF	3	2100-1020-02 000150004	MTH	28-Feb-2002	O/C			
237002	CVR GRAVITY SWITCH	*CF		6895D1-X-5-5 3609	MTH	28-Feb-2002	O/C			
237004	CVR CONTROL UNIT	*CF	4	S251-1120-00 000155394	MTH	28-Feb-2002	O/C			
237006	UNDERWATER LOCATOR BEACON	MCO		DK100 DV13017	MTH HRS	04-Dec-2007 1161	O/C	0		
237006A	CVR UNDERWATER LOCATOR BEACON BATTERY 266-E0305-00	MCO		810-2007/K 0111	MTH HRS	04-Dec-2007 1161	72	35	31-Jan-2011	8 m 11 d
238001	STDBY CONTROL UNIT CD-850	*CF	G	7513000-835 01061972	MTH	28-Feb-2002	O/C			
240001 LEFT	POWER CONTROL (UD015) UNIT 9914216-6	*CF		91479-1 589	MTH	28-Feb-2002	O/C			
240001 RIGHT	POWER CONTROL (UE016) UNIT 9914216-6	*CF		91479-1 549	MTH	28-Feb-2002	O/C			
242050 LEFT	AC (UD017) GENERATOR 9914435-8	*CF		91372-3 496	MTH	28-Feb-2002	O/C			
242050 RIGHT	AC (UE018) GENERATOR 9914435-8	*CF		91372-3 481	MTH	28-Feb-2002	O/C			
242100	STORMSCOPE INVERTER DO-160	*CF		SPC5 4092	MTH	28-Feb-2002	O/C			
243003 APU	GENERATOR (UT032) CONTROL UNIT	*CF	A	51525-001F Y11043	MTH	28-Feb-2002	O/C			
243003 LEFT	GENERATOR (UT007) CONTROL UNIT	*CF	A	51525-001F Y1801	MTH	28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
243003 RIGHT	GENERATOR (UT008) CONTROL UNIT	*CF	A	51525-001F Y1799		MTH 28-Feb-2002	O/C			
243004 LEFT	DC (EI011) AMMETER S3439-1	*CF		MD144-1 K21237		MTH 28-Feb-2002	O/C			
243004 RIGHT	DC (EI010) AMMETER S3439-1	*CF		MD144-1 K21235		MTH 28-Feb-2002	O/C			
243005	DC (EI009) VOLTMETER MD129-1	*CF		C662502-0101 K21251		MTH 28-Feb-2002	O/C			
243007	MAIN SHIP (UY006) BATTERY 9914058-6	*CF		30978-002 10103784		MTH 28-Feb-2002	O/C			
243008	OVERHEAT MONITOR	*CF	A	1529-1 3619		MTH 28-Feb-2002	O/C			
243009	BATTERY TEMP INDICATOR	*CF		1229-1 2779		MTH 28-Feb-2002	O/C			
243015	BATTERY DISCONNECT (KY001) RELAY	*CF		A876K CM90993		MTH 28-Feb-2002	O/C			
243016	OVERVOLTAGE (UZ003) MONITOR	*CF		1645-1-3 2798		MTH 28-Feb-2002	O/C			
245079 LEFT	START CNTL NZ013 PCB	*CF		6318324-5 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
245079 RIGHT	START CNTL NZ012 PCB	*CF		6318324-5 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
245080	TRIM NZ001 PCB	*CF		6518351-7 516		MTH 28-Feb-2002	O/C			
245081	PRESS NZ002 PCB	*CF		6518352-5 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
245082	DIMMING NZ023 PCB	MCO		6518366-3 0296		MTH 04-Oct-2005 HRS 742	O/C	0		
245083 LEFT	EEC INTERFACE NZ021 PCB	*CF		6618002-3 573		MTH 28-Feb-2002	O/C			
245083 RIGHT	EEC INTERFACE NZ020 PCB	*CF		6618002-3 574		MTH 28-Feb-2002	O/C			
245084	LANDING GEAR NZ004 PCB	*CF		6618704-6 351		MTH 28-Feb-2002	O/C			
245085	TAIL DEICE NZ005 PCB	MCO		6618705-6 0484		MTH 24-Jan-2005 HRS 592	O/C	0		
245086	SQUAT SW NZ006 PCB	*CF		6618706-1 333		MTH 28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
245087	CABIN DOOR NZ007 PCB	*CF		6618707-16 352		MTH 28-Feb-2002	O/C			
245091	NO TAKE-OFF NZ008 PCB	*CF		6618708-1 284		MTH 28-Feb-2002	O/C			
245092 LEFT	FUEL NZ015 PCB	*CF		6618714-11 416		MTH 28-Feb-2002	O/C			
245092 RIGHT	FUEL NZ014 PCB	*CF		6618714-11 574		MTH 28-Feb-2002	O/C			
245094	HYD NZ016 PCB	MCO		6618723-1 0360		MTH 30-Apr-2004 HRS 430	O/C	0		
245095	POS TAIL NZ017 PCB	MCO		6618721-1 0226		MTH 30-Apr-2004 HRS 430	O/C	0		
245096 LEFT	ANTI ICE NZ019 PCB	*CF		6618718-1 587		MTH 28-Feb-2002	O/C			
245096 RIGHT	ANTI-ICE NZ018 PCB	*CF		6618718-1 576		MTH 28-Feb-2002	O/C			
245097	FAN CONTROL NZ022 PCB	*CF		6618722-1 334		MTH 28-Feb-2002	O/C			
245098	RUDDER BIAS NZ029 PCB	*CF		6618812-1 344		MTH 28-Feb-2002	O/C			
245103	APU NZ025 PCB	*CF		6618808-11 272		MTH 28-Feb-2002	O/C			
245104	APU NZ026 PCB	*CF		6618809-1 276		MTH 28-Feb-2002	O/C			
252003	TEMPERATURE PROBE	*CF		102DB1AG A40579		MTH 28-Feb-2002	O/C			
256001 NO. 10	LIFE JACKET	MCO		PO723E105PA 457763		MTH 07-Aug-2009 HRS 1450	60	12	31-Aug-2013	39 m 11 d
256001 NO. 11	LIFE JACKET --	MCO		PO723E105PA 457740		MTH 07-Aug-2009 HRS 1450	60	12	31-Aug-2013	39 m 11 d
256001 NO. 1	LIFE JACKET	MCO		PO723E105PA 457667		MTH 07-Aug-2009 HRS 1450	60	12	31-Aug-2013	39 m 11 d
256001 NO. 2	LIFE JACKET	MCO		PO723E105PA 457724		MTH 07-Aug-2009 HRS 1450	60	12	31-Aug-2013	39 m 11 d
256001 NO. 3	LIFE JACKET	MCO		PO723E105PA 457674		MTH 07-Aug-2009 HRS 1450	60	12	31-Aug-2013	39 m 11 d
256001 NO. 4	LIFE JACKET	MCO		PO723E105PA 457799		MTH 07-Aug-2009 HRS 1450	60	12	31-Aug-2013	39 m 11 d

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
256001 NO. 5	LIFE JACKET	MCO		PO723E105PA 457804	MTH HRS	07-Aug-2009 1450	60	12	31-Aug-2013	39 m 11 d
256001 NO. 6	LIFE JACKET	MCO		PO723E105PA 457745	MTH HRS	07-Aug-2009 1450	60	12	31-Aug-2013	39 m 11 d
256001 NO. 7	LIFE JACKET	MCO		PO723E105PA 457677	MTH HRS	07-Aug-2009 1450	60	12	31-Aug-2013	39 m 11 d
256001 NO. 8	LIFE JACKET	MCO		PO723E105PA 457788	MTH HRS	07-Aug-2009 1450	60	12	31-Aug-2013	39 m 11 d
256001 NO. 9	LIFE JACKET	MCO		PO723E105PA 457690	MTH HRS	07-Aug-2009 1450	60	12	31-Aug-2013	39 m 11 d
256002	EMERGENCY LOCATOR TRANSMITTER ELT-110-4	*CF		453-0150 66962	MTH	28-Feb-2002	O/C			
256003	EMERGENCY LOCATOR BEACON BATTERY PACK ELT 110-4	MCO		452-0130 07012011	MTH HRS	07-Aug-2009 1450	24	2	30-Jun-2011	13 m 10 d
256004	ELT ANTENNA	*CF		DMQ18-3 9691	MTH	28-Feb-2002	O/C			
261002 LEFT	ENGINE FIRE DETECT (UT021) CONTROL UNIT 9912036-12	*CF		377-02838 0135129	MTH	28-Feb-2002	O/C			
261002 RIGHT	ENGINE FIRE DETECT (UT020) CONTROL UNIT 9912036-12	*CF		377-02838 0135123	MTH	28-Feb-2002	O/C			
262001 AFT	ENGINE FIRE BOTTLE	*CF		30400037-1 46950B1	MTH	28-Feb-2002	O/C	0		
262001 APU	FIRE BOTTLE 9914513-3	*CF		30100033 39353A1	MTH	28-Feb-2002	O/C	0		
262001 FORWARD	ENGINE FIRE BOTTLE	*CF		30400037-1 46657B1	MTH	28-Feb-2002	O/C	0		
262002 CABIN	PORTABLE HALON FIRE EXTINGUISHER MCO			C352CS X-466135	MTH HRS	03-Apr-2008 1201	O/C	0		
262002 COCKPIT	PORTABLE HALON FIRE EXTINGUISHER MCO			C352CS X-466164	MTH HRS	03-Apr-2008 1201	O/C	0		
263004 262003 : APU	REPLACE APU FIRE BOTTLE CARTRIDGE MCO			13083-5 12012011	MTH HRS	26-May-2006 859	72	0	31-May-2012	24 m 11 d
263006 262003 : FL	REPLACE FORWARD ENGINE BOTTLE FORWARD CARTRIDGE			13083-5 1105	MTH HRS	01-Mar-2006 821	72	0	31-Mar-2012	22 m 11 d
263008 262003 : FR	REPLACE FORWARD ENGINE BOTTLE AFT CARTRIDGE			13083-5 1105	MTH HRS	01-Mar-2006 821	72	0	31-Mar-2012	22 m 11 d
263010 262003 : AL	REPLACE AFT ENGINE BOTTLE FORWARD CARTRIDGE			13083-5 1105	MTH HRS	01-Mar-2006 821	72	0	31-Mar-2012	22 m 11 d

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
263012 262003 : AR	REPLACE AFT ENGINE BOTTLE AFT CARTRIDGE			13083-5 1105	MTH HRS	01-Mar-2006 821	72	0	31-Mar-2012	22 m 11 d
272001	RUDDER BIAS SHUTOFF VALVE *CF			5307-1 322B	MTH	28-Feb-2002	O/C			
272002 LEFT	STICK SHAKER (MC001) UNIT *CF	A		201 5254	MTH	28-Feb-2002	O/C			
272002 RIGHT	STICK SHAKER (MF004) UNIT *CF	A		201 5358	MTH	28-Feb-2002	O/C			
272003	RUDDER BIAS ACUTATOR *CF			6660613-12 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
273004	SERVO ACTUATOR *CF			44430-3739 T345	MTH	28-Feb-2002	O/C			
273201	ELEV TRIM SWITCH *CF			8-405-04 B53265	MTH	28-Feb-2002	O/C			
274000	HORIZONTAL STABILIZER ACTUATOR 9912548-7	MCO		41011680-108 0527	MTH HRS	29-Jan-2010 1552	O/C	0		
274013	HORIZONTAL STABILIZER ISOLATION (UY015) VALVE *CF			13027-4 4733	MTH	28-Feb-2002	O/C			
274044	HORIZONTAL STAB VALVE ASSY *CF			65680 3717	MTH	28-Feb-2002	O/C			
275001	FLAP CONTROL (UY024) VALVE *CF			66720 2471	MTH	28-Feb-2002	O/C			
275003 LEFT	FLAP ACTUATOR 9912007-1	*CF		1535000-1 1489	MTH	28-Feb-2002	O/C			
275003 RIGHT	FLAP ACTUATOR 9912007-1	*CF		1535000-1 1473	MTH	28-Feb-2002	O/C			
275004 LEFT WING LEFT INBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275004 LEFT WING LEFT OUTBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275004 LEFT WING RIGHT INBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275004 LEFT WING RIGHT OUTBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275004 RIGHT WING LEFT INBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275004 RIGHT WING LEFT OUTBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
275004 RIGHT WING RIGHT INBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275004 RIGHT WING RIGHT OUTBOARD	AFT FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275005 LEFT WING LEFT INBOARD	FWD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275005 LEFT WING LEFT OUTBOARD	FWD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275005 LEFT WING RIGHT INBOARD	FWD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275005 LEFT WING RIGHT OUTBOARD	FWD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275005 RIGHT WING LEFT INBOARD	FWD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275005 RIGHT WING LEFT OUTBOARD	FWD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275005 RIGHT WING RIGHT INBOARD	FWD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
275005 RIGHT WING RIGHT OUTBOARD	FWD FLAP ROLLER CF-2920	*CF		S3049-5F8 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	5000	0	5000	3913
276001 LEFT	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 1995	MTH	28-Feb-2002	O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 1927	MTH	28-Feb-2002	O/C			
276002	SPEED BRAKE CONTROL VALVE *CF			66720 2465	MTH	28-Feb-2002	O/C			
276003	SPEED BRAKE SAFETY VALVE *CF			68930 1215	MTH	28-Feb-2002	O/C			
280003 LEFT	FUEL RELIEF VALVE ASSY 9912501-2	*CF		840203-105 2349XP	MTH	28-Feb-2002	O/C			
280003 RIGHT	FUEL RELIEF VALVE ASSY 9912501-2	*CF		840203-105 2339XP	MTH	28-Feb-2002	O/C			
280004 LEFT	HIGH LVL FUEL VALVE 9914107-1	*CF		61087 2959	MTH	28-Feb-2002	O/C			
280004 RIGHT	HIGH LVL FUEL VALVE 9914107-1	*CF		61087 2966	MTH	28-Feb-2002	O/C			
281101 LEFT	FUEL VENT FLOAT VALVE 9914268-5	*CF		60221-4 624	MTH	28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
281101 RIGHT	FUEL VENT FLOAT VALVE 9914268-5	*CF		60221-4 612		MTH 28-Feb-2002	O/C			
282011 LEFT AFT	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 1553		MTH 28-Feb-2002	O/C			
282011 LEFT FORWARD	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 1526		MTH 28-Feb-2002	O/C			
282011 LEFT MID	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 1554		MTH 28-Feb-2002	O/C			
282011 RIGHT AFT	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 1561		MTH 28-Feb-2002	O/C			
282011 RIGHT FORWARD	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 1558		MTH 28-Feb-2002	O/C			
282011 RIGHT MID	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 1559		MTH 28-Feb-2002	O/C			
282012 LEFT 282012A : L	FUEL BOOST CARTRIDGE 9914421-2	*CF		LR55505 B615		MTH 28-Feb-2002	O/C			
282012 LEFT WING	BOOST FUEL ELECTRIC PUMP 9914421-2	*CF		LR55540 B596		MTH 28-Feb-2002	O/C			
282012 RIGHT 282012A : R	FUEL BOOST CARTRIDGE 9914421-2	*CF		LR55505 B613		MTH 28-Feb-2002	O/C			
282012 RIGHT WING	BOOST FUEL ELECTRIC PUMP 9914421-2	*CF		LR55540 B598		MTH 28-Feb-2002	O/C			
282013 LEFT WING	PRIMARY MOTIVE FLOW EJECTOR PUMP 9912483-1	*CF		2950023-101 521		MTH 28-Feb-2002	O/C			
282013 RIGHT WING	PRIMARY MOTIVE FLOW EJECTOR PUMP 9912483-1	*CF		2950023-101 526		MTH 28-Feb-2002	O/C			
282014	FUEL CROSSFEED ACTUATOR 9914423-2	*CF		MA20A1029-1 U06985		MTH 28-Feb-2002	O/C			
282100 LEFT WING	SINGLE PT REFUEL/DEFUEL SHUTOFF VALVE 9914423-2	*CF		80002-101 1216		MTH 28-Feb-2002	O/C			
282100 RIGHT WING	SINGLE PT REFUEL/DEFUEL SHUTOFF VALVE 9914423-2	ICT		80002-101 0707		MTH 16-Jun-2003 HRS 234	O/C	0		
282106	FUEL CROSSFEED VALVE 9914423-4	*CF		125838AW U06202		MTH 28-Feb-2002	O/C			
282108 LEFT	MOTIVE FLOW SHUTOFF (UY009) VALVE 9914423-4	*CF		4151 529		MTH 28-Feb-2002	O/C			
282108 RIGHT	MOTIVE FLOW SHUTOFF (UY008) VALVE 9914423-4	*CF		4151 518		MTH 28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
282118 LEFT	FUEL SHUT-OFF VALVE 9914094-1	*CF		71498 937		MTH 28-Feb-2002	O/C			
282118 RIGHT	FUEL SHUT-OFF VALVE 9914094-1	*CF		71498 924		MTH 28-Feb-2002	O/C			
282200 LEFT	LOW LEVEL VALVE ASSY 9914094-1	*CF		726400-1 450		MTH 28-Feb-2002	O/C			
282200 RIGHT	LOW LEVEL VALVE ASSY 9914094-1	*CF		726400-1 480		MTH 28-Feb-2002	O/C			
282201	VALVE-REFUEL/DEFUEL	*CF		9036-351-2 639		MTH 28-Feb-2002	O/C			
282202 LEFT	FUEL VALVE ASSY	*CF		750800-2 621E		MTH 28-Feb-2002	O/C			
282202 RIGHT	FUEL VALVE ASSY	ICT		750800-2 0099E		MTH 16-Jun-2003 HRS 234	O/C	0		
284010	FUEL QUANTITY FLOW (EI013) INDICATOR 9912497-3	*CF		10638N01M01 01070714A		MTH 28-Feb-2002	O/C			
284011	FUEL TEMPERATURE (EI014) INDICATOR 9914095-30	*CF		10583N01T00 437A		MTH 28-Feb-2002	O/C			
284012 LEFT	LOW FUEL LEVEL SENSOR 9914427-1	MCO		GIF5400-32 1756		MTH 24-Jan-2005 HRS 592	O/C	0		
284012 RIGHT	LOW FUEL LEVEL SENSOR 9914427-2	*CF		GIF5400-43 879		MTH 28-Feb-2002	O/C			
284013 LEFT WING	FUEL QTY W0 PROBE 9912498-8	*CF		10634T07Y00 960		MTH 28-Feb-2002	O/C			
284013 RIGHT WING	FUEL QTY W0 PROBE 9912498-8	*CF		10634T07Y00 1002		MTH 28-Feb-2002	O/C			
284014 LEFT WING	FUEL QTY W1 PROBE 9912498-1	*CF		10634T02Y00 998		MTH 28-Feb-2002	O/C			
284014 RIGHT WING	FUEL QTY W1 PROBE 9912498-1	*CF		10634T02Y00 993		MTH 28-Feb-2002	O/C			
284015 LEFT WING	FUEL QTY W2 PROBE 9912498-2	*CF		10634T03Y00 980		MTH 28-Feb-2002	O/C			
284015 RIGHT WING	FUEL QTY W2 PROBE 9912498-2	*CF		10634T03Y00 960		MTH 28-Feb-2002	O/C			
284016 LEFT WING	FUEL QTY W3 PROBE 9912498-3	*CF		10634T04Y00 B1147		MTH 28-Feb-2002	O/C			
284016 RIGHT WING	FUEL QTY W3 PROBE 9912498-3	*CF		10634T04Y00 B1126		MTH 28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
284017 LEFT WING	FUEL QTY W4 PROBE 9912498-4	*CF		10634T05Y00 B1112		MTH 28-Feb-2002	O/C			
284017 RIGHT WING	FUEL QTY W4 PROBE 9912498-4	*CF		10634T05Y00 B1115		MTH 28-Feb-2002	O/C			
284018 LEFT WING	FUEL QTY W5 PROBE 9912498-5	*CF		10634T01Y00 B1101		MTH 28-Feb-2002	O/C			
284018 RIGHT WING	FUEL QTY W5 PROBE 9912498-5	*CF		10634T01Y00 B1131		MTH 28-Feb-2002	O/C			
284019 LEFT WING	FUEL QTY W6 PROBE 9912498-6	*CF		10634T06Y00 B1137		MTH 28-Feb-2002	O/C			
284019 RIGHT WING	FUEL QTY W6 PROBE 9912498-6	*CF		10634T06Y00 B1055		MTH 28-Feb-2002	O/C			
284196	FUEL QUANTITY SIGNAL CONDITIONER 9912498-7	*CF		10635B01Y01 01100807		MTH 28-Feb-2002	O/C			
291001	HYDRAULIC RESERVOIR 9912542-1	MCO		7470 238		MTH 07-Nov-2002 HRS 141	O/C	0		
291002 LEFT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 3514		MTH 28-Feb-2002	O/C			
291002 RIGHT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 3573		MTH 28-Feb-2002	O/C			
291005 LEFT	HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 5427		MTH 28-Feb-2002	O/C			
291005 RIGHT	HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 5348		MTH 28-Feb-2002	O/C			
291008	SPEED BRAKE THERMAL RELIEF VALVE *CF			OAS5322-3-1700 1123		MTH 28-Feb-2002	O/C			
291009	HYD RELIEF VALVE *CF			4614 2194A		MTH 28-Feb-2002	O/C			
291010	HYD PRESS SWITCH *CF			1106P59 3849		MTH 28-Feb-2002	O/C			
291012	HYD BYPASS VALVE *CF			61510-1 1922A		MTH 28-Feb-2002	O/C			
291013 LEFT	FIREWALL HYD SHUTOFF VALVE LUZ			AV24B1325C5 T33880		MTH 03-Dec-2002	O/C			
291013 RIGHT	FIREWALL HYD SHUTOFF VALVE *CF			AV24B1325C5 U02946		MTH 28-Feb-2002	O/C			
301001 LEFT WING	ANTI-ICE BLEED AIR UNDER TEMP SL013 SWITCH *CF			1173T42-4 1700		MTH 28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
301001 RIGHT WING	ANTI-ICE BLEED AIR UNDER TEMP SR016 SWITCH *CF			1173T42-4 1704		MTH 28-Feb-2002	O/C			
301002	ISOLATION VALVE 9912403-2	*CF		2602-36 660		MTH 28-Feb-2002	O/C			
301008 LEFT	DEICE TAIL VALVE MCO			3D2353-06 N041130		MTH 18-May-2005 HRS 661	O/C	0		
301008 RIGHT	DEICE TAIL VALVE MCO			3D2353-06 N041820		MTH 18-May-2005 HRS 661	O/C	0		
301020	WINDSHIELD RAIN REMOVAL MN001 FAN *CF			011598-501 C01340015		MTH 28-Feb-2002	O/C			
301137 LEFT ENGINE	INLET ANTI-ICE PRESSURE REG SHUTOFF 9912495-1	*CF		VD001 VALVE 1962-00-7 1251		MTH 28-Feb-2002	O/C			
301137 RIGHT ENGINE	INLET ANTI-ICE PRESSURE REG SHUTOFF 9912495-1	*CF		VE002 VALVE 1962-00-7 1250		MTH 28-Feb-2002	O/C			
301201 LEFT	TAIL DEICE PRESSURE SV005 SWITCH MCO			1106P55-1 3108A		MTH 18-May-2005 HRS 661	O/C	0		
301201 RIGHT	TAIL DEICE PRESSURE SV004 SWITCH MCO			1106P55-1 3038A		MTH 18-May-2005 HRS 661	O/C	0		
301202 LEFT	HORIZ STAB DEICE BOOT MCO			P29S4D5280-11 MBHH120		MTH 14-Oct-2009 HRS 1489	O/C	0		
301202 RIGHT	HORIZ STAB DEICE BOOT MCO			P29S4D5280-12 MBPQ530		MTH 29-Jan-2010 HRS 1552	O/C	0		
302101 LEFT	PRESSURE REG VALVE 9912495-4	*CF		1946-00-19 2629		MTH 28-Feb-2002	O/C			
302101 RIGHT	PRESSURE REG VALVE 9912495-4	*CF		1946-00-19 2621		MTH 28-Feb-2002	O/C			
302104 LEFT	NACELLE INLET SWITCH *CF			1173T0759 1424		MTH 28-Feb-2002	O/C			
302104 RIGHT	NACELLE INLET SWITCH *CF			1173T0759 1428		MTH 28-Feb-2002	O/C			
303001 LEFT	PITOT TUBE *CF			PH1100-1-VCW B6080		MTH 28-Feb-2002	O/C			
303001 RIGHT	PITOT TUBE *CF			PH1100-1-VCW B6081		MTH 28-Feb-2002	O/C			
303001 STANDBY	PITOT TUBE *CF			PH1100-1-RCDW B6457		MTH 28-Feb-2002	O/C			
304100 LEFT	WINDSHIELD CONTROLLER 9914411-1	*CF		856-1-1 0131083		MTH 28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
304100 RIGHT	WINDSHIELD CONTROLLER 9914411-1	*CF		856-1-1 0131093		MTH 28-Feb-2002	O/C			
302005 E1 <i>302005X : E1**L</i>	ANTI-ICING VALVE 31J2879-04	*CF		540-0406-4 2658		MTH 28-Feb-2002	O/C			
302005 E2 <i>302005X : E2**R</i>	ANTI-ICING VALVE 31J2879-04	MCO		540-0406-4 2865		MTH 24-May-2003 HRS 227	O/C	0		
312001 LEFT HAND	DIGITAL CLOCK	*CF		M877A5V 13037		MTH 28-Feb-2002	O/C			
312001 RIGHT HAND	DIGITAL CLOCK	*CF		M877A5V 13038		MTH 28-Feb-2002	O/C			
313003 LEFT	ENGINE ACCELEROMETER	*CF		6222SM15 18253		MTH 28-Feb-2002	O/C			
313003 RIGHT	ENGINE ACCELEROMETER	*CF		6222SM15 18208		MTH 28-Feb-2002	O/C			
315001	FDR FAIL ANNUNCIATOR 9912504-11	*CF		1304-1-11 0117157		MTH 28-Feb-2002	O/C			
315101 LEFT	WARNING GEN/MIXER UNIT	*CF		1287-1-2 0143233		MTH 28-Feb-2002	O/C			
315101 RIGHT	WARNING GEN/MIXER UNIT	*CF		1287-1-2 0143235		MTH 28-Feb-2002	O/C			
316001	TILT INDICATOR	*CF		3001J72 22001		MTH 28-Feb-2002	O/C			
321003 LEFT MAIN LANDING GEAR	TRUNNION	*CF		6641630-5 SN-UNKNOWN		MTH 28-Feb-2002 LDG 0	6900	0	6900	5813
321003 RIGHT MAIN LANDING GEAR	TRUNNION	*CF		6641630-6 SN-UNKNOWN		MTH 28-Feb-2002 LDG 0	6900	0	6900	5813
321004 LEFT MAIN LANDING GEAR	TRAILING LINK	*CF		6641648-15 SN-UNKNOWN		MTH 28-Feb-2002 LDG 0	40300	0	40300	39213
321004 RIGHT MAIN LANDING GEAR	TRAILING LINK	*CF		6641648-14 SN-UNKNOWN		MTH 28-Feb-2002 LDG 0	40300	0	40300	39213
321011 LEFT MAIN LANDING GEAR	TRAILING LINK SPACER	*CF		6641533-1 SN-UNKNOWN		MTH 28-Feb-2002 LDG 0	33300	0	33300	32213
321011 RIGHT MAIN LANDING GEAR	TRAILING LINK SPACER	*CF		6641533-1 SN-UNKNOWN		MTH 28-Feb-2002 LDG 0	33300	0	33300	32213
322001 NOSE	LANDING GEAR ASSEMBLY	*CF		6642614-1 78		MTH 28-Feb-2002 LDG 0	33300	0	33300	32213
322002 NOSE GEAR	SHIMMY DAMPER	MCO		5543001-11 17611X		MTH 24-Sep-2003 HRS 316 LDG 225	O/C	0		

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
322007 NOSE GEAR	TRUNNION	*CF		6642611-9 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
323001 LEFT MAIN LANDING GEAR	ACTUATOR 9912537-3	*CF		1550000-3 512	MTH LDG	28-Feb-2002 0	70200	0	70200	69113
323001 RIGHT MAIN LANDING GEAR <i>323002 : R</i>	ACTUATOR 9912537-4	*CF		1550000-4 515	MTH LDG	28-Feb-2002 0	70200	0	70200	69113
323003 NOSE LANDING GEAR	ACTUATOR 9912491-3	*CF		1549300-5 253	MTH LDG	28-Feb-2002 0	33300	0	33300	32213
323004 LEFT	UPLOCK ACTUATOR	*CF		5527504-3 2296	MTH	28-Feb-2002	O/C			
323004 NOSE	UPLOCK ACTUATOR	*CF		5527504-3 2270	MTH	28-Feb-2002	O/C			
323004 RIGHT	UPLOCK ACTUATOR	*CF		5527504-3 2295	MTH	28-Feb-2002	O/C			
323005	PRESSURE EMER GEAR GAUGE *CF			19940929-1 009257	MTH	28-Feb-2002	O/C			
323006	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 9912505-2	*CF		40005347-3 3217	MTH	28-Feb-2002	O/C	7		
323007	LANDING GEAR CONTROL (VY047) VALVE *CF			71839-1 317	MTH	28-Feb-2002	O/C			
323008	DUMP VALVE	*CF		OAS5319-1 940	MTH	28-Feb-2002	O/C			
323009	LANDING GEAR CONTROL 9912550-1	*CF		049801-001 191	MTH	28-Feb-2002	O/C			
323010 LEFT MAIN LANDING GEAR	OLEO ASSEMBLY	MCO		6641615-4 44	MTH HRS LDG	18-Sep-2007 1129 782	38000	545	38237	37150
323010 RIGHT MAIN LANDING GEAR	OLEO ASSEMBLY	MCO		6641615-4 87	MTH HRS LDG	21-Jan-2007 992 610	38000	0	38610	37523
323011 LEFT MAIN LANDING GEAR	OLEO UPPER CAP	*CF		6641616-3 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	4600	0	4600	3513
323011 RIGHT MAIN LANDING GEAR	OLEO UPPER CAP	*CF		6641616-3 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	4600	0	4600	3513
324001 LEFT	MAIN WHEEL ASSEMBLY 9912487-9	*CF		3-1571-2 558	MTH	28-Feb-2002	O/C			
324001 RIGHT	MAIN WHEEL ASSEMBLY 9912487-9	*CF		3-1571-2 560	MTH	28-Feb-2002	O/C			
324002 NOSE	WHEEL ASSEMBLY 9914069-4	*CF		3-1418-OPT4 5744	MTH	28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
324003 LEFT	MAIN BRAKE ASSEMBLY 9912487-7	MCO		2-1601-1 0818	MTH HRS LDG	04-Dec-2007 1161 800	O/C			0
324004 RIGHT	MAIN BRAKE ASSEMBLY 9912487-7	MCO		2-1601-1 0667	MTH HRS LDG	04-Dec-2007 1161 800	O/C			0
324005 LEFT	MAIN TIRE 9912488-3	MCO		M13702 7107W161	MTH HRS LDG	07-Aug-2009 1450 985	O/C			0
324005 RIGHT	MAIN TIRE 9912488-3	MCO		M13702 7195W157	MTH HRS LDG	29-Jan-2010 1552 1049	O/C			0
324006	NOSE TIRE 9914070-1	MCO		031-613-8 9066W00144	MTH HRS LDG	29-Jan-2010 1552 1049	O/C			0
324009	POWER BRAKE VALVE 9912489-8	*CF		32-077-1 363	MTH	28-Feb-2002	O/C			
324010 LEFT	EXTEND/RETRACT VALVE *CF			98120 187	MTH	28-Feb-2002	O/C			
324010 NOSE	EXTEND/RETRACT VALVE *CF			98120 1923	MTH	28-Feb-2002	O/C			
324010 RIGHT	EXTEND/RETRACT VALVE *CF			98120 1873	MTH	28-Feb-2002	O/C			
324011 LEFT	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-15			98281-3 571	MTH HRS	13-Sep-2006 937	O/C			
324011 RIGHT	(PILOT SIDE) MASTER BRAKE CYLINDER ICT			95367-9 2093	MTH HRS LDG	29-Mar-2002 14 13	O/C			0
324012 LEFT	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-16	*CF		98281-4 675	MTH	28-Feb-2002	O/C			
324012 RIGHT	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-16	*CF		98281-4 677	MTH	28-Feb-2002	O/C			
324014	EMERGENCY AIR BRAKE CONTROL VALVE *CF			65830-4 624	MTH	28-Feb-2002	O/C			
324015 LEFT	BRAKE SHUTTLE VALVE *CF			211-114 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
324015 RIGHT	BRAKE SHUTTLE VALVE *CF			211-114 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
324019	BRAKE PRESS PUMP ASSEMBLY 9912166-3	*CF		640931 5739	MTH	28-Feb-2002	O/C			
324020	ANTISKID CONTROL (UY009) VALVE 9912489-4	*CF		39-837 418	MTH	28-Feb-2002	O/C			
324022	ANTISKID DIGITAL CONTROL 9912489-9	*CF		42-985-2 357	MTH	28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
324023	POWER BRAKE ACCUMULATOR *CF			57C57652 1538		MTH 28-Feb-2002	O/C			
324024 LEFT	WHEEL TRANSDUCER 9912305-2	MCO		40-955 2618		MTH 14-Oct-2009 HRS 1489	O/C	0		
324024 RIGHT	WHEEL TRANSDUCER 9912305-2	*CF		40-955 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
324025	PRESSURE (SN011) SWITCH *CF			GPP1250-52 132341		MTH 28-Feb-2002	O/C			
324026	POWER PACK MOTOR *CF			MP50B1 2135		MTH 28-Feb-2002	O/C			
324027	ANTISKID FAULT DISPLAY 9912305-9	*CF		42-92750 1006A		MTH 28-Feb-2002	O/C			
324101	PARKING BRAKE VALVE 9912388-2	MCO		95905 1709A		MTH 04-Dec-2007 HRS 1161	O/C	0		
324153 3242153	PRESS ANTISKID BRK SWITCH *CF			GPP1250-73 0129028		MTH 28-Feb-2002	O/C			
324200 324201	ANTISKID PRESSURE GAUGE *CF			19940929-1 9455		MTH 28-Feb-2002	O/C			
324206	ANTISKID HYD RELIEF VALVE *CF			1785-2 343		MTH 28-Feb-2002	O/C			
326005 LEFT	MAIN GEAR UP & LOCKED (S3) SWITCH *CF			65-430087 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
326005 RIGHT	MAIN GEAR UP & LOCKED (S3) SWITCH *CF			65-430087 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
326005	NOSE GEAR UP & LOCKED (SN001) SWITCH *CF			65-430087 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
331001 CENTER	5 VDC UN004 DIMMER POWER SUPPLY *CF			273-1 0137273		MTH 28-Feb-2002	O/C			
331001 LEFT	5 VDC UN002 DIMMER POWER SUPPLY *CF			273-1 0137264		MTH 28-Feb-2002	O/C			
331001 RIGHT	5 VDC UN006 DIMMER POWER SUPPLY *CF			273-1 0137291		MTH 28-Feb-2002	O/C			
331011	EL PANEL INVERTER *CF			EM2044-1 3541A		MTH 28-Feb-2002	O/C			
332001 LEFT NO. 1	LIGHT POWER SUPPLY *CF			AL750PS 14955		MTH 28-Feb-2002	O/C			
332001 LEFT NO. 2	LIGHT POWER SUPPLY *CF			AL750PS 14944		MTH 28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
332001 LEFT NO. 3	LIGHT POWER SUPPLY	*CF		AL750PS 14945		MTH 28-Feb-2002	O/C			
332001 LEFT NO. 4	LIGHT POWER SUPPLY	*CF		AL750PS 14958		MTH 28-Feb-2002	O/C			
332001 LEFT NO. 5	LIGHT POWER SUPPLY	*CF		AL750PS 14956		MTH 28-Feb-2002	O/C			
332001 LEFT NO. 6	LIGHT POWER SUPPLY	*CF		AL750PS 14957		MTH 28-Feb-2002	O/C			
332001 LEFT NO. 7	LIGHT POWER SUPPLY	*CF		AL750PS 14949		MTH 28-Feb-2002	O/C			
332001 LEFT NO. 8	LIGHT POWER SUPPLY	*CF		AL750PS 14950		MTH 28-Feb-2002	O/C			
332001 LEFT NO. 9	LIGHT POWER SUPPLY	*CF		AL750PS 14946		MTH 28-Feb-2002	O/C			
332001 RIGHT NO. 10	LIGHT POWER SUPPLY	*CF		AL750PS 15054		MTH 28-Feb-2002	O/C			
332001 RIGHT NO. 1	LIGHT POWER SUPPLY	*CF		AL750PS 15050		MTH 28-Feb-2002	O/C			
332001 RIGHT NO. 2	LIGHT POWER SUPPLY	*CF		AL750PS 15041		MTH 28-Feb-2002	O/C			
332001 RIGHT NO. 3	LIGHT POWER SUPPLY	*CF		AL750PS 15057		MTH 28-Feb-2002	O/C			
332001 RIGHT NO. 4	LIGHT POWER SUPPLY	*CF		AL750PS 15039		MTH 28-Feb-2002	O/C			
332001 RIGHT NO. 5	LIGHT POWER SUPPLY	*CF		AL750PS 15051		MTH 28-Feb-2002	O/C			
332001 RIGHT NO. 6	LIGHT POWER SUPPLY	*CF		AL750PS 15052		MTH 28-Feb-2002	O/C			
332001 RIGHT NO. 7	LIGHT POWER SUPPLY	*CF		AL750PS 15042		MTH 28-Feb-2002	O/C			
332001 RIGHT NO. 8	LIGHT POWER SUPPLY	*CF		AL750PS 15059		MTH 28-Feb-2002	O/C			
332001 RIGHT NO. 9	LIGHT POWER SUPPLY	*CF		AL750PS 15058		MTH 28-Feb-2002	O/C			
332002	GLARESHIELD INVERTER	*CF	A	6900173 3699		MTH 28-Feb-2002	O/C			
334002	EMPENNAGE LIGHT ASSY	*CF		01-0790044-37 SN-UNKNOWN		MTH 28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
334006 LEFT	STROBE POWER SUPPLY *CF			01-0790101-05 00554		MTH 28-Feb-2002	O/C			
334006 RIGHT	STROBE POWER SUPPLY *CF			01-0790101-05 00573		MTH 28-Feb-2002	O/C			
335001 AFT	EMERGENCY LIGHTING UC020 BATTERY PACK *CF			9913-1 960		MTH 28-Feb-2002	O/C			
335001 FORWARD	EMERGENCY LIGHTING UC019 BATTERY PACK *CF			9913-1 885		MTH 28-Feb-2002	O/C			
341009	SAFE FLIGHT AOA UF004 SENSOR *CF			C-12717-1 715		MTH 28-Feb-2002	O/C			
341010	SAFE FLIGHT AOA EI001 INDICATOR *CF			C12705-1 580		MTH 28-Feb-2002	O/C			
341011	SAFE FLIGHT AOA UC009 COMPUTER *CF			C13006-2 620		MTH 28-Feb-2002	O/C			
341014	SAFE FLIGHT AOA FI003 INDEXER *CF			C12763-1 471		MTH 28-Feb-2002	O/C			
341016 SECONDARY	FLIGHT ADU SAT			27101-01-01 M012093		MTH 07-Aug-2003 HRS 284	O/C	0		
341017	MEGGITT SECONDARY FLIGHT (EI016) DISPLAY ICT			38101-00-01 M006583		MTH 16-Jun-2003 HRS 234	O/C	0		
341025	RAM AIR TEMP DISPLAY 9912552-3 ICT			65018-005 115569		MTH 17-Jun-2002 HRS 69	O/C	0		
341101	DIFFERENTIAL PRESSURE SWITCH *CF			D45C-24 374		MTH 28-Feb-2002	O/C			
341107 NO. 1	(PILOT) AIR DATA COMPUTER AZ-850 MCO			7014700-914 01105776		MTH 04-Oct-2005 HRS 742	O/C	742		
341107 NO. 2	(COPILOT) AIR DATA COMPUTER AZ-850 MCO			7014700-914 01105703		MTH 04-Oct-2005 HRS 742	O/C	742		
342001 STANDBY	MAGNETIC COMPASS C2400-L4V2W-5B *CF			C660501-0301 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
342023	RADAR CONTROLLER WC-880 *CF			7008471-407 01096292		MTH 28-Feb-2002	O/C			
342050 LEFT	FLUX DETECTOR FX-220 *CF			2594484 1104902		MTH 28-Feb-2002	O/C			
342050 RIGHT	FLUX DETECTOR FX-220 *CF			2594484 1104892		MTH 28-Feb-2002	O/C			
342053	AERONETICS HSI-15 STANDBY HORIZONTAL SITUATION INDICATOR HSI-315B *CF 2			520-3151-003 21136		MTH 28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
342064	GYRO 2 (PS-835) BATTERY PACK PS-835	MCO		501-1228-04 2678	MTH HRS	07-Aug-2009 1450	O/C	0		
342065 NO. 1	AHRS 1 BATTERY PACK PS-835	MCO		501-1228-04 11018	MTH HRS	07-Aug-2009 1450	O/C	3583		
342069	HONEYWELL PRIMUS 1000 EFIS MC800 MULTIFUNCTION DISPLAY CONTROLLER MC-800	MCO		7007062-941 97061758	MTH HRS	24-Sep-2003 316	O/C	3579		
342072	MEGGITT STATIC CONVERTER *CF	6		501-1318-01 5094	MTH	28-Feb-2002	O/C			
342082 LEFT	AHRS TRAY *CF			140691 1699	MTH	28-Feb-2002	O/C			
342082 RIGHT	AHRS TRAY *CF			140691 1696	MTH	28-Feb-2002	O/C			
342083 LEFT	AHRS COMPUTER *CF	7		142185-1100 1621	MTH	28-Feb-2002	O/C			
342083 RIGHT	AHRS COMPUTER MCO			142185-3100 1111	MTH HRS	25-Apr-2003 217	O/C	437		
342104 LEFT	MSU CALIBRATION PROM UNIT *CF			124282 2763	MTH	28-Feb-2002	O/C			
342104 RIGHT	MSU CALIBRATION PROM UNIT *CF			124282 2757	MTH	28-Feb-2002	O/C			
342500	HONEYWELL PRIMUS 1000 EFIS RI553 REMOTE INSTRUMENT CONTROLLER RI-553	*CF		7016954-907 01111410	MTH	28-Feb-2002	O/C			
342502	HONEYWELL PRIMUS 1000 EFIS BL871 BEZEL CONTROLLER BL-871	*CF		7014332-841 01105808	MTH	28-Feb-2002	O/C			
342503 COPILOT	FLT DISPLAY CONTROLLER BL-870	*CF		7014331-931 01114364	MTH	28-Feb-2002	O/C			
342503 PILOT	HONEYWELL PRIMUS 1000 EFIS BL870 BEZEL CONTROLLER BL-870	*CF		7014331-931 0114390	MTH	28-Feb-2002	O/C			
342504 COPILOT	HONEYWELL PRIMUS 1000 EFIS DC550 DISPLAY CONTROLLER DC-550	*CF	E	7016986-747 01114153	MTH	28-Feb-2002	O/C			
342504 PILOT	HONEYWELL PRIMUS 1000 EFIS DC550 DISPLAY CONTROLLER DC-550	*CF	E	7016986-747 01114154	MTH	28-Feb-2002	O/C			
342505 NO.1	HONEYWELL PRIMUS 1000 EFIS IC600/IC615 INTEGRATED AVIONICS COMPUTER IC-600 (S3100-264)	ICT		7017000-82358 01094977	MTH HRS	16-Jun-2003 234	O/C	0		
342505 NO.2	HONEYWELL PRIMUS 1000 EFIS IC600/IC615 INTEGRATED AVIONICS COMPUTER IC-600 (S3100-265)	ICT		7017000-83358 01094946	MTH HRS	16-Jun-2003 234	O/C	0		
342506	HONEYWELL PRIMUS 1000 EFIS MS560 MODE SELECTOR UNIT MS-560	*CF		7018341-803 02012083	MTH	28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
342509 COPILOT <i>342501 : R</i>	HONEYWELL PRIMUS 1000 EFIS DU870 MULTIFUNCTION DISPLAY UNIT DU-870	*CF	H	7014300-901 0110A578		MTH 28-Feb-2002	O/C			
342509 PILOT <i>342501 : L</i>	HONEYWELL PRIMUS 1000 EFIS DU870 MULTIFUNCTION DISPLAY UNIT DU-870	*CF	H	7014300-901 0110A576		MTH 28-Feb-2002	O/C			
342510 CENTER <i>342501 : CNTR</i>	ELECTRONIC DISPLAY UNIT DU-870	*CF	H	7014300-901 0110A579		MTH 28-Feb-2002	O/C			
343001	GLIDESLOPE ANTENNA COUPLER *CF			CI503 1102284		MTH 28-Feb-2002	O/C			
343002 <i>343001 : B</i>	MARKER BEACON ANTENNA COUPLER *CF			CI509 1065221		MTH 28-Feb-2002	O/C			
344005	RADAR TRANSCEIVER WU-880	*CF	L	7021450-801 01103587		MTH 28-Feb-2002	O/C			
344022	RADIO ALTIMETER ALT-55B INDICATOR ALT-55	*CF	11	622-2855-011 HKXK		MTH 28-Feb-2002	O/C			
344023 AFT	RADIO ALT RECEIVER ANTENNA *CF			S67-2002 23455		MTH 28-Feb-2002	O/C			
344023 FORWARD	RADIO ALT TRANSMITTER ANTENNA *CF			S67-2002 23457		MTH 28-Feb-2002	O/C			
344024	EGPWS COMPUTER S2800-422	*CF	1	965-0976-040-204-20 4 888		MTH 28-Feb-2002	O/C			
345004 AFT	XPNDR BOTTOM ANTENNA *CF			DMNI50-2-2 81430		MTH 28-Feb-2002	O/C			
345004 FORWARD	XPNDR BOTTOM ANTENNA *CF			DMNI50-2-2 81429		MTH 28-Feb-2002	O/C			
345005 TOP AFT	TRANSPONDER DIVERSITY ANTENNA 85226	*CF		DMNI50-2-2 82008		MTH 28-Feb-2002	O/C			
345005 TOP FORWARD	TRANSPONDER DIVERSITY ANTENNA 85226	*CF		DMNI50-2-2 82003		MTH 28-Feb-2002	O/C			
345007 NO.1	DISTANCE MEASURING EQUIPMENT (DME) ANTENNA 85226	*CF		DMNI50-2-2 82013		MTH 28-Feb-2002	O/C			
345007 NO.2	DISTANCE MEASURING EQUIPMENT (DME) ANTENNA 85226	*CF		DMNI50-2-2 82983		MTH 28-Feb-2002	O/C			
345011 NO. 1	ADF RECEIVER MODULE DF-850	*CF	K	7510114-901 01105162		MTH 28-Feb-2002	O/C			
345011 NO. 2	ADF RECEIVER MODULE *CF			7510112-901 01090502		MTH 28-Feb-2002	O/C			
345014 NO. 1	ADF ANTENNA AT-860	*CF		7510300-901 01085750		MTH 28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
345017	MARKER BEACON ANTENNA *CF			31-10-01 3958		MTH 28-Feb-2002	O/C			
345018	GLIDESLOPE ANTENNA *CF			RGS10-48 A8176		MTH 28-Feb-2002	O/C			
345029 NO. 1	NAV CLUSTER MODULE XN-850	*CF	E	7510164-921 01106322		MTH 28-Feb-2002	O/C			
345029 NO. 2	NAV CLUSTER MODULE XN-850	*CF	E	7510164-921 01096267		MTH 28-Feb-2002	O/C			
345032 NO.1	VHF NAV RECEIVER NV-850	*CF	M	7510134-931 01106445		MTH 28-Feb-2002	O/C			
345032 NO. 2	VHF NAV RECEIVER NV-850	*CF	M	7510134-931 01106408		MTH 28-Feb-2002	O/C			
345034 NO. 1	ATC TRANSPONDER XS-852	MCO		7517400-902 01095966		MTH 18-Sep-2007 HRS 1129	O/C		0	
345034 NO. 2	ATC TRANSPONDER XS-852	MCO		7517400-902 01085841		MTH 18-Sep-2007 HRS 1129	O/C		1129	
345036 NO. 1	DME INTERROGATOR DM-850	*CF	K	7510184-902 01106011		MTH 28-Feb-2002	O/C			
345036 NO. 2	DME INTERROGATOR DM-850	*CF	K	7510184-902 01106012		MTH 28-Feb-2002	O/C			
345038 NO. 1	INTEGRATED NAV UNIT RNZ-850	MCO		7510100-731 01106115		MTH 24-Jan-2005 HRS 592	O/C		0	
345038 NO. 2	INTEGRATED NAV UNIT RNZ-850B	MCO		7510100-733 01106098		MTH 24-Jan-2005 HRS 592	O/C		0	
345077	DATA TRANSFER UNIT DTU-100	MCO		1406-01-1 1636		MTH 07-Aug-2009 HRS 1450	O/C		0	
345079 NO. 1	GPS FLT MGMT COMPUTER UNS-1CSP	*CF	12	1019-41-201 598		MTH 28-Feb-2002	O/C			
345088 NO. 1	RADIO MANAGEMENT UNIT RM-850	MCO		7012100-825 02113651		MTH 11-Nov-2003 HRS 354	O/C		519	
345088 NO. 2	RADIO MANAGEMENT UNIT RM-850	*CF	AM	7012100-825 01103388		MTH 28-Feb-2002	O/C			
345093 NO.1	GPS ANTENNA ANTENNA	*CF		10706 7183		MTH 28-Feb-2002	O/C			
345093 NO.2	GPS ANTENNA ANTENNA	*CF		10706 7233		MTH 28-Feb-2002	O/C			
345201 LEFT	NAV ANTENNA DMN4-17/P	*CF		DMN4-17-1N 1081297		MTH 28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
345201 RIGHT	NAV ANTENNA DMN4-17/P	*CF		DMN4-17-1N 1081302	MTH	28-Feb-2002	O/C			
345301 LEFT	DME INDICATOR DI-851	*CF	A	7513006-911 01102334	MTH	28-Feb-2002	O/C			
345301 RIGHT	DME INDICATOR DI-851	*CF	A	7513006-911 01102335	MTH	28-Feb-2002	O/C			
346001	TCAS PROCESSOR TPU-67A	SAT		066-01146-1211 41156	MTH HRS	07-Aug-2003 284	O/C		268	
346002 BOTTOM	TCAS ANTENNA ANT-67A	MCO		071-01548-0100 11482	MTH HRS	12-Dec-2002 150	O/C		0	
346002 TOP	TCAS ANTENNA ANT-67A	*CF		071-01548-0200 8891	MTH	28-Feb-2002	O/C			
346012 346006	TCAS II MODULE	*CF		071-00097-1000 3311	MTH	28-Feb-2002	O/C			
351001	OXYGEN PRESSURE (EI002) GAGE MD-97	*CF		C668512-0101 K21711	MTH	28-Feb-2002	O/C			
351004 COPILOT	OXYGEN MASK	MCO		MC10-16-100 100072	MTH HRS	03-Apr-2008 1201	72	0	30-Apr-2014	47 m 10 d
351004 PILOT	OXYGEN MASK	MCO		MC10-16-100 115817	MTH HRS	03-Apr-2008 1201	72	0	30-Apr-2014	47 m 10 d
351006	OXYGEN CYLINDER	MCO		804882-14 10405	MTH HRS	24-Jan-2005 592	180	43	30-Jun-2016	73 m 10 d
351007	OXYGEN REGULATOR	MCO		804881-01 490	MTH HRS	24-Jan-2005 592	O/C	0		
351008	PASSENGER OXYGEN CONTROL VALVE 9914067-19	*CF		P21006 1503	MTH	28-Feb-2002	O/C			
352001	PASSENGER OXYGEN ALTITUDE PRESSURE SWITCH P24032	*CF		379	MTH	28-Feb-2002	O/C			
361010	DOOR SOLENOID VALVE	*CF		5035-00-1 455	MTH	28-Feb-2002	O/C			
361011 LEFT	HEAT EXCHANGER ACTUATOR 9914519-4	*CF		1E50-2 9AU250	MTH	28-Feb-2002	O/C			
361011 RIGHT	HEAT EXCHANGER ACTUATOR 9914519-4	*CF		1E50-2 8AU200	MTH	28-Feb-2002	O/C			
361100 LEFT	BLEED AIR TEMPERATURE (ST021) SWITCH	*CF		1173T0635 3146	MTH	28-Feb-2002	O/C			
361100 RIGHT	BLEED AIR TEMPERATURE (ST020) SWITCH	*CF		1173T0635 3244	MTH	28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
361101 LEFT	BLEED AIR OVERTEMP (ST017) SWITCH 9914149-2	*CF		1173T181-2 1431		MTH 28-Feb-2002	O/C			
361101 RIGHT	BLEED AIR OVERTEMP (ST014) SWITCH 9914149-2	*CF		1173T181-2 1433		MTH 28-Feb-2002	O/C			
361102 LEFT	BLEED AIR MANIFOLD TEMPERATURE (TT001) SENSOR 9914519-2	MCO		1E51-1 7BA330		MTH 26-May-2006 HRS 859	O/C	0		
361102 RIGHT	BLEED AIR MANIFOLD TEMPERATURE (TT002) SENSOR 9914519-2	*CF		1E51-1 11AU389		MTH 28-Feb-2002	O/C			
361103 LEFT	HEAT B/A EXCHANGER 9912486-2	*CF		8230-2 S4883T0469		MTH 28-Feb-2002	O/C			
361103 RIGHT	HEAT B/A EXCHANGER 9912486-2	*CF		8230-2 S4883T0434		MTH 28-Feb-2002	O/C			
361104 LEFT	PRECOOLER VD003 VALVE 9912486-2	*CF		1407-10 494A		MTH 28-Feb-2002	O/C			
361104 RIGHT	PRECOOLER VD003 VALVE 9912486-2	*CF		1407-10 431A		MTH 28-Feb-2002	O/C			
361205 NO. 2 361208 : 2	APU CHECK VALVE 9914171-1	*CF		8C210 3074		MTH 28-Feb-2002	O/C			
361208	APU CHECK VALVE 9914171-1	*CF		8C210 2960		MTH 28-Feb-2002	O/C			
361500 NO. 1	B/A CHECK VALVE 9914171-1	*CF		8C210 3058		MTH 28-Feb-2002	O/C			
361500 NO. 2	B/A CHECK VALVE 9914171-1	*CF		8C210 3084		MTH 28-Feb-2002	O/C			
361534	SERVICE AIR REGULATOR 9912510-1	MCO		1H75-18 8AN11		MTH 14-Mar-2005 HRS 622	O/C	0		
49APU1 490000	APU 9912484-1	*CF		3800722-1 P284		MTH 28-Feb-2002	E/C			
490001	APU ELECTRONIC CONTROL 9912484-1	*CF		2119552-2 91H0113		28-Feb-2002	O/C			
490003	BLEED AIR SHUTOFF VALVE 9914047-1	MCO		50230-8 0581E		26-May-2006 APUH 545	O/C	0		
490004	DC AMMETER S3439-3	*CF		MD144-3 K21518		28-Feb-2002	O/C			
490005	OVERHEAT DETECTOR 9912416-1	*CF		3001-212-1004/455-9 204011		28-Feb-2002	O/C			
490006	HOURLMETER 9912416-1	*CF		C664503-0104 SN-UNKNOWN		28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
492003	COMPRESSOR ROTOR	*CF		3822523-003 010350102262		28-Feb-2002 APUS 0	12000	0	12000	10661
492004	TURBINE ROTOR	*CF		3842340-2 010134509229		28-Feb-2002 APUS 0	4000	0	4000	2661
493000	FUEL CONTROL ASSEMBLY	*CF		3883900-1 0100328		28-Feb-2002	O/C			
493001	TEE-FLOW DIVIDER VALVE	*CF		3883921-2 SN-UNKNOWN		28-Feb-2002	O/C			
494000	ELECTRICAL IGNITER LEAD	*CF		3888302-20 SN-UNKNOWN		28-Feb-2002	O/C			
494001	IGNITER PLUG	*CF		304634-2 SN-UNKNOWN		28-Feb-2002	O/C			
494002	IGNITION UNIT	*CF		3888000-7 010218023240		28-Feb-2002	O/C			
497006	RPM/MAX INDICATOR	ICT		M453 22978		16-Jun-2003 APUH 131	O/C	0		
499000	LOW OIL PRESSURE SWITCH	*CF		3876351-1 010922700388		28-Feb-2002	O/C			
499001	LUBE PUMP ASSEMBLY	*CF		3881825-1 P405		28-Feb-2002	O/C			
499002	OIL LEVEL SWITCH	MCO		3876318-3 060147000253		13-Sep-2006 APUH 579	O/C	0		
521003	ACOUSTIC LOWER FWD SEAL	*CF		9522-13 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
521004	ACOUSTIC UPPER SEAL	*CF		9522-11 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
521005	ACOUSTIC LOWER AFT SEAL	*CF		9522-15 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
527000	EMERGENCY EXIT SWITCH	*CF		8-405-04 B52798		MTH 28-Feb-2002	O/C			
531001 LEFT NOSE LANDING GEAR	TRUNNION SUPPORT ASSEMBLY	*CF		6613020-55 SN-UNKNOWN		MTH 28-Feb-2002 LDG 0	25500	0	25500	24413
531001 RIGHT NOSE LANDING GEAR	TRUNNION SUPPORT ASSEMBLY	*CF		6613020-56 SN-UNKNOWN		MTH 28-Feb-2002 LDG 0	25500	0	25500	24413
531002 NOSE GEAR	ACTUATOR ATTACH FITTING	*CF		6211190-41 SN-UNKNOWN		MTH 28-Feb-2002 LDG 0	25500	0	25500	24413
561001 LEFT	MAIN WINDSHIELD	*CF		9914380-9 NP139721-9 01283H9912		MTH 28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
561001 RIGHT	MAIN WINDSHIELD 9914380-14	MCO		NP139731-2 08352H4295	MTH HRS	07-Aug-2009 1450	O/C	0		
561004 LEFT	ELECTRICALLY HEATED COCKPIT FORWARD SIDE WINDOW 9914379-5	*CF		NP139722-5 01302H2107	MTH	28-Feb-2002	O/C			
561004 RIGHT	ELECTRICALLY HEATED COCKPIT FORWARD SIDE WINDOW 9914379-6	*CF		NP139722-6 01242H6969	MTH	28-Feb-2002	O/C			
561005 LEFT	OPENABLE COCKPIT AFT SIDE WINDOW 9914116-33	*CF		NP139703-3 669	MTH	28-Feb-2002	O/C			
561005 RIGHT	OPENABLE COCKPIT AFT SIDE WINDOW 9914116-34	*CF		NP139703-4 746	MTH	28-Feb-2002	O/C			
562001 LEFT NO. 2	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
562001 LEFT NO. 3	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
562001 LEFT NO. 4	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
562001 LEFT NO. 5	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
562001 LEFT NO. 6	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
562001 LEFT NO. 7	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
562001 RIGHT NO. 1	EMERGENCY DOOR WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
562001 RIGHT NO. 2	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
562001 RIGHT NO. 3	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
562001 RIGHT NO. 4	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
562001 RIGHT NO. 5	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
562001 RIGHT NO. 6	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
562001 RIGHT NO. 7	CABIN WINDOW 9914159-12	*CF		167400-03 SN-UNKNOWN	MTH	28-Feb-2002	O/C			
571001 LEFT MAIN LANDING GEAR	FORWARD TRUNNION FITTING *CF			6622123-1 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	23800	0	23800	22713

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
571001 RIGHT MAIN LANDING GEAR	FORWARD TRUNNION FITTING *CF			6622123-2 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	23800	0	23800	22713
571002 LEFT MAIN LANDING GEAR	AFT TRUNNION FITTING *CF			6622124-1 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	23800	0	23800	22713
571002 RIGHT MAIN LANDING GEAR	AFT TRUNNION FITTING *CF			6622124-2 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	23800	0	23800	22713
571003 LEFT MAIN LANDING GEAR	ACTUATOR FITTING ASSEMBLY *CF			6621125-5 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	23800	0	23800	22713
571003 RIGHT MAIN LANDING GEAR	ACTUATOR FITTING ASSEMBLY *CF			6621125-6 SN-UNKNOWN	MTH LDG	28-Feb-2002 0	23800	0	23800	22713
712001 LEFT	ENGINE AFT ISOLATOR 9912480-2	*CF		LM451-SA2 LK0499	MTH HRS	28-Feb-2002 0	10000	0	10011	8401.9
712001 RIGHT	ENGINE AFT ISOLATOR 9912480-2	*CF		LM451-SA2 LK0502	MTH HRS	28-Feb-2002 0	10000	0	10011	8401.9
712002 LEFT BOTTOM	FORWARD ENGINE ISOLATOR 9912480-1	*CF		LM451-SA4 LK1023	MTH HRS	28-Feb-2002 0	10000	0	10011	8401.9
712002 LEFT UPPER	FORWARD ENGINE ISOLATOR 9912480-1	*CF		LM451-SA4 LK1004	MTH HRS	28-Feb-2002 0	10000	0	10011	8401.9
712002 RIGHT BOTTOM	FORWARD ENGINE ISOLATOR 9912480-1	*CF		LM451-SA4 LK0977	MTH HRS	28-Feb-2002 0	10000	0	10011	8401.9
712002 RIGHT UPPER	FORWARD ENGINE ISOLATOR 9912480-1	*CF		LM451-SA4 LK1063	MTH HRS	28-Feb-2002 0	10000	0	10011	8401.9
712005	ENG VIBRATION MONITOR 9912519-2	*CF		2789 090123	MTH	28-Feb-2002	O/C			
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE			PW545A DB0445	MTH	28-Feb-2002	E/C			
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE			PW545A DB0480	MTH	28-Feb-2002	E/C			
721010 E1 <i>721010X : E1**L</i>	ACCESS GEARBOX SHAFT *CF			30J2201-01 A000YA21	MTH	28-Feb-2002	O/C			
721010 E2 <i>721010X : E2**R</i>	ACCESS GEARBOX SHAFT *CF			30J2201-01 A0011APL	MTH	28-Feb-2002	O/C			
722001 E1 <i>722001X : E1**L</i>	OIL PUMP ASSEMBLY *CF			30J2106-01 43A302	MTH	28-Feb-2002	O/C			
722001 E2 <i>722001X : E2**R</i>	OIL PUMP ASSEMBLY *CF			30J2106-01 43A381	MTH	28-Feb-2002	O/C			
723010 E1 <i>722609X : E1**L</i>	LP COMPRESSOR FAN ROTOR *CF			30J2091-01 A000RNFT	MTH LDG	28-Feb-2002 -19	15000	0	14981	13894

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
723010 E2 <i>722609X : E2**R</i>	LP COMPRESSOR FAN ROTOR *CF			30J2091-01 A0011XC9	MTH LDG	28-Feb-2002 -19	15000	0	14981	13894
723020 E1 <i>722611X : E1**L</i>	LP COMPRESSOR BOOST ROTOR *CF			30J2210-01 A000Y489	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
723020 E2 <i>722611X : E2**R</i>	LP COMPRESSOR BOOST ROTOR *CF			30J2210-01 A0010XY3	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
723030 E1 <i>722610X : E1**L</i>	1ST STAGE HP COMPRESSOR ROTOR *CF			30J2081-01 A000Y16X	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
723030 E2 <i>722610X : E2**R</i>	1ST STAGE HP COMPRESSOR ROTOR *CF			30J2081-01 A0010MX2	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
723040 E1 <i>723705X : E1**L</i>	2ND STAGE HP COMPRESSOR ROTOR *CF			30J2122-01 A000Y4AC	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
723040 E2 <i>723705X : E2**R</i>	2ND STAGE HP COMPRESSOR ROTOR *CF			30J2122-01 A0010TRT	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
723060 E1 <i>724825X : E1**L</i>	CENTRIFUGAL IMPELLER *CF			30J1450-01 A000XRMD	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
723060 E2 <i>724825X : E2**R</i>	CENTRIFUGAL IMPELLER *CF			30J1450-01 A0011EF2	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
724001 E1 INNER <i>724001X : E1**L</i>	COMBUSTION CHAMBER LINER *CF			30J2034-01 A000XTN8	MTH	28-Feb-2002	O/C			
724001 E2 INNER <i>724001X : E2**R</i>	COMBUSTION CHAMBER LINER *CF			30J2034-01 A0011HX2	MTH	28-Feb-2002	O/C			
725010 E1 <i>724706X : E1**L</i>	1ST-STAGE TURBINE DISK *CF			30J1551-01 A000YP45	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
725010 E2 <i>724706X : E2**R</i>	1ST-STAGE TURBINE DISK *CF			30J1551-01 A0011K2P	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
725020 E1 <i>724708X : E1**L</i>	2ND-STAGE TURBINE DISK *CF			30H3152 68B463	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
725020 E2 <i>724708X : E2**R</i>	2ND-STAGE TURBINE DISK *CF			30H3152 68B468	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
725030 E1 <i>724709X : E1**L</i>	3RD-STAGE TURBINE DISK *CF			30H3153 67B888	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
725030 E2 <i>724709X : E2**R</i>	3RD-STAGE TURBINE DISK *CF			30H3153 67B890	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
725040 E1 <i>724710X : E1**L</i>	4TH-STAGE TURBINE DISK *CF			30H3154 68B125	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394
725040 E2 <i>724710X : E2**R</i>	4TH-STAGE TURBINE DISK *CF			30H3154 68B154	MTH LDG	28-Feb-2002 -19	13500	0	13481	12394

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
733001 LEFT	FUEL FLOW TRANSMITTER 9914413-1	MCO		9-231-28 6753	MTH HRS	21-Jan-2007 992	O/C	0		
733001 RIGHT	FUEL FLOW TRANSMITTER 9914413-1	*CF		9-231-28 L8296	MTH	28-Feb-2002	O/C			
733004 LEFT	FUEL PRESSURE SWITCH 9914112-3	MCO		6057-3 2515	MTH HRS	09-Aug-2008 1262	O/C	0		
733004 RIGHT	FUEL PRESSURE SWITCH 9914112-3	*CF		6057-3 1634	MTH	28-Feb-2002	O/C			
731002 E1 <i>731002X : E1**L</i>	FLOW DIVIDER VALVE 30J1415-02	*CF		819710-2 F52770	MTH	28-Feb-2002	O/C			
731002 E2 <i>731002X : E2**R</i>	FLOW DIVIDER VALVE 30J1415-02	*CF		819710-2 F47361	MTH	28-Feb-2002	O/C			
732001 E1 <i>732001X : E1**L</i>	HYDROMECHANICAL FUEL CONTROL 30J2120-02	*CF		823700-2 F53073	MTH	28-Feb-2002	O/C			
732001 E2 <i>732001X : E2**R</i>	HYDROMECHANICAL FUEL CONTROL 30J2120-02	*CF		823700-2 F53631	MTH	28-Feb-2002	O/C			
741001 E1 <i>741001X : E1**L</i>	IGNITION EXCITER 31J2807-06	*CF		9060420-4 NN01107930	MTH	28-Feb-2002	O/C			
741001 E2 <i>741001X : E2**R</i>	IGNITION EXCITER 31J2807-06	*CF		9060420-4 NN01128581	MTH	28-Feb-2002	O/C			
742001 E1 INBOARD <i>742001X : E1*LI</i>	IGNITOR 31J1552-01	MCO		9058600-1 NNA06309226	MTH HRS	13-Sep-2006 937	O/C	0		
742001 E1 OUTBOARD <i>742001X : E1*LO</i>	IGNITOR 31J1552-01	MCO		9058600-1 NNA06309254	MTH HRS	13-Sep-2006 937	O/C	0		
742001 E2 INBOARD <i>742001X : E2*RI</i>	IGNITOR 31J1552-01	MCO		9058600-1 NNA06309240	MTH HRS	13-Sep-2006 937	O/C	0		
742001 E2 OUTBOARD <i>742001X : E2*RO</i>	IGNITOR 31J1552-01	MCO		9058600-1 NNA06309257	MTH HRS	13-Sep-2006 937	O/C	0		
742002 E1 <i>742002X : E1**L</i>	SHORT IGNITOR LEAD 31J2346-07	MCO		9059190-7 NN01044727	MTH HRS	13-Sep-2006 937	O/C	0		
742002 E2 <i>742002X : E2**R</i>	SHORT IGNITOR LEAD 31J2346-07	MCO		9059190-7 NNA04207057	MTH HRS	13-Sep-2006 937	O/C	0		
742003 E1 <i>742003X : E1**L</i>	LONG IGNITOR LEAD 31J2346-08	MCO		9059190-8 NN00407549	MTH HRS	13-Sep-2006 937	O/C	0		
742003 E2 <i>742003X : E2**R</i>	LONG IGNITOR LEAD 31J2346-08	MCO		9059190-8 NN02028795	MTH HRS	13-Sep-2006 937	O/C	0		
751003 E1 <i>751003X : E1**L</i>	COMPRESSOR BLEED VALVE ASSY *CF			30J2207-01 42A453	MTH	28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
751003 E2 <i>751003X : E2**R</i>	COMPRESSOR BLEED VALVE ASSY *CF			30J2207-01 44A908		MTH 28-Feb-2002	O/C			
751004 E1 <i>751004X : E1**L</i>	BLEED SERVO VALVE *CF			31J2857-04 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
751004 E2 <i>751004X : E2**R</i>	BLEED SERVO VALVE MCO			31J2857-04 TRO879		MTH 05-Oct-2005 HRS 742	O/C	0		
751005 E1 <i>751005X : E1**L</i>	LINEAR TRANSDUCER *CF			31J2071-01 1535		MTH 28-Feb-2002	O/C			
751005 E2 <i>751005X : E2**R</i>	LINEAR TRANSDUCER *CF			31J2071-01 1583		MTH 28-Feb-2002	O/C			
761001 LEFT	THROTTLE DETENT VALVE *CF			5303-2A 2162		MTH 28-Feb-2002	O/C			
761001 RIGHT	THROTTLE DETENT VALVE *CF			5303-2A 2163		MTH 28-Feb-2002	O/C			
761001 E1 <i>761001X : E1**L</i>	ELECTRONIC ENGINE CONTROL 30J2123-02 MCO			817962-8-010 02024570		MTH 10-Jan-2003 HRS 163	O/C	0		
761001 E2 <i>761001X : E2**R</i>	ELECTRONIC ENGINE CONTROL 30J2123-02 ICT			817962-8-010 00013092		MTH 17-Jun-2002 HRS 69	O/C	0		
771004	N1 SPEED/ITT TEMP INDICATOR 9912497-8 *CF			10636N04M00 01090739A		MTH 28-Feb-2002	O/C			
771005	N2/OIL PRESS/OIL TEMP INDICATOR 9912497-9 MCO			10637N04M00 9909587A		MTH 27-Feb-2008 HRS 1180	O/C	0		
771004 E1 <i>771004X : E1**L</i>	SPEED N1 SENSOR *CF			31J2072-01 CH761		MTH 28-Feb-2002	O/C			
771004 E2 <i>771004X : E2**R</i>	SPEED N1 SENSOR *CF			31J2072-01 CH799		MTH 28-Feb-2002	O/C			
771005 E1 <i>771005X : E1**L</i>	SPEED N2 SENSOR *CF			31J2073-01 CH1637		MTH 28-Feb-2002	O/C			
771005 E2 <i>771005X : E2**R</i>	SPEED N2 SENSOR *CF			31J2073-01 CH1688		MTH 28-Feb-2002	O/C			
772001 E1 <i>772001X : E1**L</i>	TEMPERATURE SENSOR *CF			31J2113-03 RTH8835		MTH 28-Feb-2002	O/C			
772001 E2 <i>772001X : E2**R</i>	TEMPERATURE SENSOR *CF			31J2113-03 RTH9454		MTH 28-Feb-2002	O/C			
783001 LEFT ENGINE <i>783001X : E1**L</i>	THRUST REVERSER ASSEMBLY 9912609-1 *CF			64ND-78002-3 471		MTH 28-Feb-2002 LDG 0	20000	0	20000	18913
783001 RIGHT ENGINE <i>783001X : E2**R</i>	THRUST REVERSER ASSEMBLY *CF			64ND-78002-4 472		MTH 28-Feb-2002 LDG 0	20000	0	20000	18913

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
783002 LEFT	THRUST REVERSER VALVE *CF			65680 3814		MTH 28-Feb-2002	O/C			
783002 RIGHT	THRUST REVERSER VALVE *CF			65680 3796		MTH 28-Feb-2002	O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR *CF			64ND-78204-5 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR *CF			64ND-78204-5 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR *CF			64ND-78204-5 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR *CF			64ND-78204-5 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
783101 LEFT	ARM PRESSURE SWITCH *CF			6607A7-45 B0042557		MTH 28-Feb-2002	O/C			
783101 RIGHT	ARM PRESSURE SWITCH *CF			6607A7-45 B017681		MTH 28-Feb-2002	O/C			
783102 LEFT	THRUST REVERSER ISOLATION VALVE *CF			13027-4 4614		MTH 28-Feb-2002	O/C			
783102 RIGHT	THRUST REVERSER ISOLATION VALVE *CF			13027-4 4635		MTH 28-Feb-2002	O/C			
783103 LEFT INBOARD	STOW LIMIT SWITCH *CF			53ND78304-1 SN-UNKNOWN		MTH 07-Nov-2002	O/C			
783103 LEFT OUTBOARD	STOW LIMIT SWITCH *CF			53ND78304-1 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
783103 RIGHT INBOARD	STOW LIMIT SWITCH *CF			53ND78304-1 SN-UNKNOWN		MTH 07-Nov-2002	O/C			
783103 RIGHT OUTBOARD	STOW LIMIT SWITCH *CF			53ND78304-1 SN-UNKNOWN		MTH 28-Feb-2002	O/C			
783104 LEFT	DEPLOY LIMIT SWITCH MCO			53ND78304-5 NSN		MTH 24-Jan-2005 HRS 592 LDG 439	O/C			0
783104 RIGHT	DEPLOY LIMIT SWITCH *CF			53ND78304-5 SN-UNKNOWN		MTH 07-Nov-2002	O/C			
793002 LEFT	OIL TEMP XMTR SENSOR *CF			102-00083 3791		MTH 28-Feb-2002	O/C			
793002 RIGHT	OIL TEMP XMTR SENSOR *CF			102-00083 3795		MTH 28-Feb-2002	O/C			
793102 LEFT	ENGINE OIL TRANSMITTER 9912464-1 *CF			APTE-237D-1000-25 0D 66079774		MTH 28-Feb-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
793102 RIGHT	ENGINE OIL TRANSMITTER 9912464-1	*CF		APTE-237D-1000-25 0D 6619443		MTH 28-Feb-2002	O/C			
793117 LEFT	OIL PRESSURE SWITCH 9912466-2	*CF		1153P0098-01 611		MTH 28-Feb-2002	O/C			
793117 RIGHT	OIL PRESSURE SWITCH 9912466-2	*CF		1153P0098-01 612		MTH 28-Feb-2002	O/C			
793003 E1 <i>793003X : E1**L</i>	FUEL OIL HEAT EXCHANGER D2552-600B	*CF		31J2955-02 M50156		MTH 28-Feb-2002	O/C			
793003 E2 <i>793003X : E2**R</i>	FUEL OIL HEAT EXCHANGER D2552-600B	*CF		31J2955-02 M52966		MTH 28-Feb-2002	O/C			
801000 LEFT ENGINE	STARTER/GENERATOR 9912499-6	MCO		300SGL138Q-4 6273XL		MTH 03-Apr-2008 HRS 1201	1000	0	2201	591.9
801000 RIGHT ENGINE	STARTER/GENERATOR 9912499-6	MCO		300SGL138Q-4 5709XL		MTH 03-Apr-2008 HRS 1201	1000	0	2201	591.9
801100 APU	STARTER/GENERATOR 9912499-29	MCO		300SGL138Q-5 3155		MTH 13-Sep-2006 APUH 579	1000	0	1579	-30.1



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
SB 560XL-05-01	CONVERSION FROM CALENDAR SCHEDULE MAINTENANCE PROGRAM TO MSG-3 SCHEDULE MAINTENANCE PROGRAM									
<i>05SB-01 : XL</i>				OPTIONAL		MTH		A/R		
SB 560XL-21-04 R1	EXHAUST DUCT CONDENSATION CONTAINMENT					MTH	16-Jun-2003	-		Complete
<i>21SB-04 : XLR1</i>		ICT		RECOMMENDED		HRS	234			
NOT APPLICABLE										
SB 560XL-21-05	CABIN WARM AIR DISTRIBUTION DUCT IMPROVEMENTS					MTH	09-Aug-2008	-		N/A
<i>21SB-05</i>		MCO		RECOMMENDED		HRS	1262			
SB 560XL-21-11	SERVICE PORT DRIP SHIELD IMPROVEMENT					MTH	17-Jun-2002	-		Complete
<i>21SB-11 : XL</i>		ICT		RECOMMENDED		HRS	69			
SB 560XL-21-15	COCKPIT TEMPERATURE SENSOR IMPROVEMENT					MTH	16-Jun-2003	-		Complete
<i>21SB-15 : XL</i>		ICT		DISCRETIONARY		HRS	234			
SB 560XL-21-16	ACM ASPIRATOR TUBING ATTACHMENT IMPROVEMENT					MTH		-		
<i>21SB-16 : XL</i>				DISCRETIONARY						
SB 560XL-21-18 R1	TEMPERATURE CONTROLLER UPGRADE					MTH	09-Aug-2008	A/R		N/A
<i>21SB-18 : XLR1</i>		MCO		RECOMMENDED		HRS	1262			
SB 560XL-21-19	EMER PRESS OPERATION IMPROVE					MTH	26-May-2006	A/R		Complete
<i>21SB-19 : XL</i>		MCO		RECOMMENDED		HRS	859			
SB 560XL-21-23	FORWARD EVAPORATOR INSTALLATION AND WIRING MODIFICATION					MTH		A/R		
<i>21SB-23 : XL</i>				OPTIONAL						
SB 560XL-21-24	AFT EVAPORATOR INSTALLATION AND WIRING MODIFICATION					MTH		A/R		
<i>21SB-24 : XL</i>				OPTIONAL						
SB 560XL-21-25	BRUSHLESS GASPER AIR BOOST BLOWER INSTALLATION AND WIRING MODIFICATION					MTH		A/R		
<i>21SB-25 : XL</i>				OPTIONAL						
SL 560XL-21-03	COCKPIT TEMPERATURE SENSOR MODIFICATION					MTH	17-Jun-2002	-		Complete
<i>21SL-03 : XL</i>		ICT		RECOMMENDED		HRS	69			
SL 560XL-21-04	AIR CYCLE MACHINE ASPIRATOR TUBING INSPECTION					MTH	11-Apr-2003	-		Complete
<i>21SL-04 : XL</i>		MCO		RECOMMENDED		HRS	204			
SL 560XL-21-05	R-134A AIR CONDITIONING SYSTEM WIRING INSPECTION					MTH	04-Feb-2009	A/R		Complete
<i>21SL-05 : XL</i>		MCO		RECOMMENDED		HRS	1362			
NOT APPLICABLE										
SL 560XL-21-06	DROPPED AISLE DUCT IMPROVEMENT					MTH	11-Apr-2003	-		Complete
<i>21SL-06 : XL</i>		MCO		RECOMMENDED		HRS	204			
SL 560XL-21-07	XMTL H/W 2215460-21-2762 ECU					MTH	11-Apr-2003	A/R		Complete
<i>21SL-07 : XL</i>		MCO		SUPERSEDED		HRS	204			
SL 560XL-22-01	AILERON, RUDDER, AND ELEVATOR AUTOPILOT SERVO INSTALLATION INSPECTION					MTH	17-Jun-2002	-		Complete
<i>22SL-01 : XL</i>		ICT		RECOMMENDED		HRS	69			
SL 560XL-22-02	XMTL HNYWEL SB 4006719-22-0019					MTH		A/R		
<i>22SL-02 : XL</i>				DISCARD						
SB 560XL-23-03	AIRSHOW CABIN DISPLAY MODIFICATION					MTH		-		
<i>23SB-03 : XL</i>				OPTIONAL						
SB 560XL-23-05 R1	RNZ-850 NAVIGATION RADIO UPGRADE					MTH	24-Jan-2005	-		Complete
<i>23SB-05 : XLR1</i>		MCO		MANDATORY		HRS	592			
SL 560XL-23-04	AIRSHOW IMPROVE/SOFTWARE UPGR					MTH	11-Apr-2003	A/R		Complete
<i>23SL-04 : XL</i>		MCO		SUPERSEDED		HRS	204			
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL 560XL-23-05	TRANSMITTAL OF HONEYWELL PUBLICATION NUMBER A21-3851-001, RCZ INTEGRATED COMMUNICATION UNIT					MTH	16-Jun-2003	-		Complete
<i>23SL-05 : XL</i>		ICT		RECOMMENDED		HRS	234			
SL 560XL-23-07	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7511001-23-6026 SRZ 850/851 INTEGRATED RADIO SYSTEM					MTH		-		
<i>23SL-07 : XL</i>				DISCRETIONARY						
SB 560XL-24-02 R1	CONCORDE BATTERY INSTALLATION					MTH		-		
<i>24SB-02 : XLR1</i>		*CF		OPTIONAL						

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
SB 560XL-24-11 R1 24SB-11 : XLR1	EMER LITE BAT PCK CIRC BRL MOD			DISCRETIONARY			A/R			
SB 560XL-24-14 R2 24SB-14 : XLR2	APU STARTER/GENERATOR WIRING IMPROVEMENT	MCO		RECOMMENDED	MTH 11-Mar-2010 HRS 1573.2 LDG 1064		300			Complete
SB 560XL-24-15 24SB-15 : XL	TAILCONE/STINGER ELECTRICAL CONNECTOR IMPROVEMENT			DISCRETIONARY	MTH		A/R			
SL 560XL-24-01 24SL-01 : XL	BATTERY DISCONNECT RELAY BUS BAR GROUNDING PLATE INSPECTION	MCO		RECOMMENDED	MTH 24-Sep-2003 HRS 316		-			Complete
SL 560XL-24-02 24SL-02 : XL	MAIN ENGINE AND APU GROUND INSTALLATION INSPECTION AND BOND CHECK			DISCRETIONARY	MTH		-			
SB 560XL-25-08 25SB-08 : XL	AFT DIVIDER IMPROVEMENT	MCO		OPTIONAL	MTH 29-Apr-2004 HRS 430		-			Complete
SB 560XL-25-09 25SB-09 : XL	GALLEY STORAGE DOOR HINGE IMPROVEMENT	MCO		RECOMMENDED	MTH 24-Jan-2005 HRS 592		-			N/A
NOT APPLICABLE										
SB 560XL-25-10 R1 25SB-10 : XLR1	AFT DIVIDER DOOR SWITCH IMPROVEMENT			OPTIONAL			-			
SB 560XL-25-11 R1 25SB-11 : XLR1	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)			OPTIONAL	MTH		-			
SB 560XL-25-12 R1 25SB-12 : XLR1	GLARESHIELD LEATHER STRIP INSTALLATION			OPTIONAL	MTH		-			
SB 560XL-25-15 25SB-15 : XL	IMPROVEMENT TO THE AFT DIVIDER			SUPERSEDED			A/R			
SL 560XL-25-02 25SL-02 : XL	TOILET SHROUD ASSEMBLY INSPECTION	MCO		RECOMMENDED	MTH 24-Jan-2005 HRS 592		-			Complete
SL 560XL-25-05 25SL-05 : XL	CABIN SYSTEMS AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) 920040 SERVICE BULLETIN 920040-44-01 SAVE MAIN CPU CMOS SETUP SETTINGS TO FLASH MEMORY			OPTIONAL	MTH		A/R			
SL 560XL-25-10 25SL-10 : XL	TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARY BUCKLE PLASTIC HANDLE	MCO		MANDATORY	MTH 03-Apr-2008 HRS 1201		A/R			Complete
NOT APPLICABLE										
SL 560XL-25-11 25SL-11 : XL	TRANSMITTAL OF ROCKWELL COLLINS SERVICE BULLETIN 9200XX-44-4 AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) AND AIRSHOW GENESYS DATA COMMUNICATION UNIT (DCU)			DISCRETIONARY	MTH		A/R			
SB 560XL-26-01 26SB-01 : XL	INSP/REPLC TEMP PRESSURE SWTC	ICT		SUPERSEDED	MTH 16-Jun-2003 HRS 234		A/R			Complete
SB 560XL-26-02 26SB-02 : XL	FIRE BOTTLE WIRE ID SLEEVE I	MCO		MANDATORY	MTH 24-Jan-2005 HRS 592		A/R			Complete
ASL 560XL-26-01 26ASL-01 : XL	TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36-THERMISTORS DETECTORS	MCO		MANDATORY	MTH 23-Feb-2008 HRS 1176		A/R			Complete
SB 560XL-27-13 R1 27SB-13 : XLR1	AFT AILERON TUBE IMPROVEMENT	MCO		SUPERSEDED	MTH 24-Sep-2003 HRS 316		A/R			Complete
SB 560XL-27-13 R2 27SB-13 : XLR2	AFT AILERON SECTOR TUBE FINISH IMPROVEMENT	MCO		RECOMMENDED	MTH 24-Jan-2005 HRS 592		-			Complete
SB 560XL-27-17 R2 27SB-17 : XLR2	ELEVATOR TRIM TAB INSPECTION/REPAIR	ICT		RECOMMENDED	MTH 16-Jun-2003 HRS 234		-			Complete
SB 560XL-27-20 27SB-20 : XL	RUDDER FAIRLEAD TUBE SUPPORT MODIFICATION	MCO		RECOMMENDED	MTH 11-Apr-2003 HRS 204		-			Complete
SB 560XL-27-21 R1 27SB-21 : XLR1	AILERON PULLEY BRACKET ACCESS IMPROVEMENT			OPTIONAL	MTH		A/R			
SERVICE BULLETIN ON HOLD.										

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
SB 560XL-27-22 R1 27SB-22 : XLR1	AILERON WING CABLE PULLEY BRACKET REPLACEMENT	MCO		MANDATORY	MTH HRS	13-Sep-2006 937	A/R			Complete
SB 560XL-27-26 27SB-26 : XL	ELEV TRIM WHEEL INSTL IMPROVE	MCO		SUPERSEDED	MTH HRS	18-May-2005 661	A/R			Complete
SB 560XL-27-28 27SB-28 : XL	RUDDER PEDAL POSITION ADJUSTMENT MODIFICATION			DISCRETIONARY	MTH		A/R			
SB 560XL-27-29 27SB-29 : XL	SPEED BRAKE ELECTRICAL CONNECTOR REPLACEMENT	MCO		RECOMMENDED	MTH HRS	09-Aug-2008 1262	A/R			Complete
SB 560XL-27-31 27SB-31 : XL	FLAP HANDLE AND FLAP HANDLE GUARD IMPROVEMENT			OPTIONAL	MTH		A/R			
ASL 560XL-27-10 27ASL10 : XL	TRANSMITTAL OF TEMPORARY FAA APPROVED AIRPLANE FLIGHT MANUAL	MCO		MANDATORY	MTH HRS	11-Apr-2003 204	-			Complete
ASL 560XL-27-12 27ASL12 : XL	AILERON WING CABLE INSPECTION	MCO		SUPERSEDED	MTH HRS	15-Feb-2004 386	A/R			Complete
SL 560XL-27-08 27SL-08 : XL	RUDDER ASSEMBLY CONDUIT TUBE INSPECTION	MCO		RECOMMENDED	MTH HRS	11-Apr-2003 204	-			Complete
SL 560XL-27-13 27SL-13 : XL	ELEVATOR TRIM CABLE INSPECTION	MCO		RECOMMENDED	MTH HRS	24-Jan-2005 592	-			Complete
SL 560XL-27-14 27SL-14 : XL	HORI & VERT STAB EROSION BOOT			OPTIONAL			-			
SL 560XL-27-17 27SL-17 : XL	ELEVATOR TRIM WHEEL INSPECTION			RECOMMENDED	MTH HRS		300		1648	38.9
SB 560XL-28-02 28SB-02 : XL	WNG FUEL BST PMP FARING INSUL	MCO		SUPERSEDED	MTH HRS	18-May-2005 661	A/R			Complete
SB 560XL-28-03 28SB-03 : XL	WING FUEL BOOST PUMP FAIRING INSULATION INSTALLATON	MCO		MANDATORY	MTH HRS	18-May-2005 661	-			N/A
NOT APPLICABLE BY COMPONENT PART NUMBER.										
SB 560XL-29-03 29SB-03 : XL	HYDRAULIC SHUT-OFF VALVE INSTALLATION IMPROVEMENT	ICT		OPTIONAL	MTH HRS	16-Jun-2003 234	-			Complete
SB 560XL-29-04 29SB-04 : XL	WHEEL WELL HYDRAULIC LINE SUPPORT IMPROVEMENT	MCO		MANDATORY	MTH HRS	24-Jan-2005 592	-			Complete
SL 560XL-29-01 29SL-01 : XL	HYDRAULIC RESERVOIR INSPECTION	MCO		RECOMMENDED	MTH HRS	07-Nov-2002 141	-			Complete
SL 560XL-29-03 29SL-03 : XL	ENGINE HYDRAULIC HOSE INSPECTION			RECOMMENDED	MTH HRS		300		1725	115.9
SB 560XL-30-04 30SB-04 : XL	WING LEADING EDGE PICCOLO TUBE IMPROVEMENT	MCO		RECOMMENDED	MTH HRS	11-Apr-2003 204	-			Complete
SB 560XL-30-06 30SB-06 : XL	HORIZONTAL STABILIZER DEICE SYSTEM PRESSURE SWITCH INSTALLATION IMPROVEMENT	MCO		DISCRETIONARY	MTH HRS	14-Oct-2009 1489	A/R			Complete
ASL 560XL-30-02 30ASL02 : XL	AUTOPILOT SERVO ANTI-ICE INSP	ICT		MANDATORY	MTH HRS	17-Jun-2002 69	A/R			Complete
SB 560XL-31-02 31SB-02 : XL	STAB MISCOMPARE ANNUNC IMPROVESB	MCO		MANDATORY	MTH HRS	29-Apr-2004 430	A/R			Complete
SL 560XL-31-03 R1 31SL-03 : XLR1	INSTRUMENTAL PANEL INSTALLATION MODIFICATION			DISCRETIONARY	MTH		A/R			
SB 560XL-32-18 REV2 32SB-18 : XLR2	NLG ACTUATOR ISOLATOR INSTALLATION IMPROVEMENT			OPTIONAL			-			
SB 560XL-32-20 REV2 32SB-20 : XLR2	NOSE GEAR TORQUE-LINK QUICK DISCONNECT			OPTIONAL	MTH		A/R			
SB 560XL-32-23 REV1 32SB-23 : XLR1	UPLOCK SUPPORT FITTING LOCATION			DISCRETIONARY	MTH		-			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
SB 560XL-32-24 REV1	EMERGENCY GEAR EXTENSION BOTTLE ACTUATOR HANDLE PIVOT SCREW REPLACEMENT	MCO		MANDATORY	MTH HRS 592	24-Jan-2005	-			Complete
<i>32SB-24 : XLR1</i>										
SB 560XL-32-26 REV2	NOSE LANDING GEAR DOOR MECHANISM IMPROVEMENT	MCO		MANDATORY	MTH HRS 937	13-Sep-2006	A/R			Complete
<i>32SB-26 : XLR2</i>										
SB 560XL-32-27 <i>32SB-27 : XL</i>	MAIN LANDING GEAR TRAILING LINK PIVOT PIN RETENTION IMPROVEMENT			RECOMMENDED	MTH HRS 1087	10-Jul-2007	A/R			Complete
SB 560XL-32-28 REV1	200 POUND GROSS WEIGHT INCREASE			OPTIONAL	MTH		A/R			
<i>32SB-28 : XLR1</i>										
SB 560XL-32-29 <i>32SB-29 : XL</i>	NOSE WHEEL STEERING PULLEY BRACKET IMPROVEMENT			DISCRETIONARY	MTH		A/R			
SB 560XL-32-32 <i>32SB-32 : XL</i>	BRAKE HYDRAULIC PACK FILTER BOWL REPLACEMENT	MCO		RECOMMENDED	MTH HRS 1201	03-Apr-2008	A/R			Complete
SB 560XL-32-37 <i>32SB-37 : XL</i>	NOSE LANDING GEAR STEERING HARDWARE REPLACEMENT			DISCRETIONARY	MTH		A/R			
SB 560XL-32-40 <i>32SB-40 : XL</i>	LANDING GEAR ANNUNCIATION WIRING MODIFICATION	MCO		RECOMMENDED	MTH HRS 1262	09-Aug-2008	A/R			Complete
ASL 560XL-32-13 <i>32ASL13 : XL</i>	EMERGENCY BRAKE, FLAPS, EMERGENCY GEAR AND SPEED BRAKE HYDRAULIC/PNEUMATIC LINE CLAMP INSPECTION	MCO		MANDATORY	MTH HRS 316	24-Sep-2003	-			Complete
ASL 560XL-32-14 <i>32ASL14 : XL</i>	NOSE LANDING GEAR OLEO PRESSURE INSPECTION	MCO		MANDATORY	MTH HRS 615	04-Mar-2005	A/R			Complete
SL 560XL-32-15 <i>32SL-15 : XL</i>	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-1			OPTIONAL	MTH		A/R			
SL 560XL-32-16 <i>32SL-16 : XL</i>	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1601-32-4, LANDING GEAR - BRAKE ASSEMBLY - P/N 2-1601-1, INTRODUCTION OF NEW O-RING			DISCRETIONARY	MTH		A/R			
SL 560XL-32-18 <i>32SL-18 : XL</i>	TRANSMITTAL OF GOODRICH SERVICE BULLETINS 3-1571-32-2 AND 3-1571-32-3			RECOMMENDED	MTH LDG		300		1058	-29 Over Due
SL 560XL-32-19 R1 <i>32SL-19 : XLR1</i>	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-4 INTRODUCTION OF IMPROVED THERMAL RELIEF PLUG ASSEMBLY			DISCRETIONARY	MTH		A/R			
SL 560XL-32-20 <i>32SL-20 : XL</i>	TRANSMITTAL OF GOODRICH SERVICE LETTER 2056			RECOMMENDED	MTH LDG		150		908	-179 Over Due
SL 560XL-32-22 <i>32SL-22 : XL</i>	LANDING GEAR COMPONENT PLACARD INSTALLATION			OPTIONAL	MTH		A/R			
SL 560XL-32-23 <i>32SL-23 : XL</i>	EMERGENCY GEAR RELEASE INSPECTION			RECOMMENDED	MTH HRS		150		1619	9.9
SB 560XL-33-04 REV1	INDIRECT LIGHTING RELAY REPLACEMENT			OPTIONAL			-			
<i>33SB-04 : XLR1</i>										
SB 560XL-33-05 REV1	LED TAIL POSITION LIGHT INSTALLATION			OPTIONAL			-			
<i>33SB-05 : XLR1</i>										
SB 560XL-33-06 <i>33SB-06 : XL</i>	CABIN UPWASH/DOWNWASH INDIRECT LIGHTING IMPROVEMENT			OPTIONAL	MTH		A/R			
SB 560XL-33-08 REV2	LIGHTS - CHART LIGHT MODIFICATION			RECOMMENDED	MTH HRS 1087	10-Jul-2007	A/R			Complete
<i>33SB-08 : XLR2</i>										

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
SB 560XL-33-09 33SB-09 : XL	LIGHT EMITTING DIODE (LED) EMERGENCY OVERWING LIGHTING INSTALLATION			OPTIONAL	MTH		-			
SB 560XL-33-11 33SB-11 : XL	DROPPED AISLE LED LIGHT INSTA			OPTIONAL	MTH		A/R			
SB 560XL-33-15 33SB-15 : XL	WING TIP NAVIGATION AND ANTI-COLLISION LED LIGHT INSTALLATION			OPTIONAL	MTH		A/R			
SB 560XL-33-16 33SB-16 : XL	GROUND RECOGNITION LIGHT LED UPGRADE			OPTIONAL	MTH		A/R			
SL 560XL-33-04 33SL-04 : XL	AFT EMERGENCY LIGHTING BATTERY PACK COVER REMOVAL			OPTIONAL	MTH		-			
SB 560XL-34-26 REV1	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) COMPUTER SOFTWARE UPGRADE									
		MCO		RECOMMENDED	MTH	11-Apr-2003	-			Complete
					HRS	204				
34SB-26 : XLR1	NOT APPLICABLE									
SB 560XL-34-27 34SB-27 : XL	UNIVERSAL AVIONICS PERFORMANCE DATABASE			OPTIONAL	MTH		-			
	SERVICE BULLETIN ON HOLD.									
SB 560XL-34-28 34SB-28 : XL	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) COMPUTER SOFTWARE UPGRADE			OPTIONAL	MTH		-			
SB 560XL-34-29 34SB-29 : XL	HONEYWELL PRIMUS 1000 PHASE 3.0 SOFTWARE UPGRADE			RECOMMENDED	MTH	16-Jun-2003	-			Complete
		ICT			HRS	234				
SB 560XL-34-30 34SB-30 : XL	HONEYWELL PRIMUS 1000 PHASE 3.0 SOFTWARE UPGRADE			RECOMMENDED	MTH	11-Apr-2003	-			Complete
		MCO			HRS	204				
	NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
SB 560XL-34-32 REV1	CATEGORY II OPERATIONS			OPTIONAL	MTH		-			
34SB-32 : XLR1										
SB 560XL-34-37 34SB-37 : XL	ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) STEEP APPROACH SWITCH INSTALLATION			OPTIONAL	MTH		-			
SB 560XL-34-38 REV1	UNS1-CSP TO UNS1-CSP+ AND UNS1-ESP UPGRADE TO SOFTWARE CONTROL NUMBER (SCN) 802.2			OPTIONAL	MTH		-			
34SB-38 : XLR1										
SB 560XL-34-39 REV1	ENHANCED GROUND PROXIMITY WARNING SWITCH (EGPWS) -219-219 SOFTWARE			OPTIONAL	MTH		-			
34SB-39 : XLR1										
SB 560XL-34-40 R1 34SB-40 : XLR1	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) UPGRADE			OPTIONAL	MTH		A/R			
SB 560XL-34-41 REV2	NAVIGATION - HONEYWELL TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE			OPTIONAL	MTH		A/R			
34SB-41 : XLR2										
SB 560XL-34-44 R2 34SB-44 : XLR2	NAVIGATION - HONEYWELL MODE S TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE			OPTIONAL	MTH		A/R			
	SERVICE BULLETIN ON HOLD.									
SB 560XL-34-45 R1 34SB-45 : XLR1	ENHANCED VISION SYSTEMS (EVS) INSTALLATION			OPTIONAL	MTH		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
SB 560XL-34-46 34SB-46 : XL	HONEYWELL CD-820 FLIGHT MANAGEMENT SYSTEM (FMS) WIRING MODIFICATION	MCO		RECOMMENDED	MTH 13-Sep-2006 HRS 937		-			N/A
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 560XL-34-47 34SB-47 : XL	UNIVERSAL PERFORMANCE DATABASE UPGRADE	MCO		MANDATORY	MTH 05-Oct-2005 HRS 742		A/R			Complete
SB 560XL-34-49 R1 34SB-49 : XLR1	RAAS AUDIO INHIBIT SWITCH INS			OPTIONAL			A/R			
SB 560XL-34-50 R1 34SB-50 : XLR1	IC-615 VERTICAL GLIDE PATH AND FLIGHT DIRECTOR IMPROVEMENTS	MCO		SUPERSEDED	MTH 09-Aug-2008 HRS 1262		A/R			N/A
SB 560XL-34-50 R2 34SB-50 : XLR2	IC-615 VERTICAL GLIDE PATH AND FLIGHT DIRECTOR IMPROVEMENTS			RECOMMENDED	MTH HRS		300		300	-1309.1 Over Due
SB 560XL-34-52 REV1 34SB-52 : XLR1	UNIVERSAL PERFORMANCE DATABASE INSTALLATION			OPTIONAL	MTH		A/R			
SB 560XL-34-56 R1 34SB-56 : XLR1	UNIVERSAL UNS1-ESP AND UNS1-CSP+ UPGRADE TO SOFTWARE CONTROL NUMBER (SCN) 803.0			OPTIONAL	MTH		A/R			
SB 560XL-34-57 34SB-57 : XL	IC-600 FLIGHT DIRECTOR IMPROVEMENTS			DISCRETIONARY	MTH		A/R			
SB 560XL-34-58 REV1 34SB-58 : XLR1	IC-615 FLIGHT DIRECTOR IMPROVEMENTS			DISCRETIONARY	MTH		A/R			
ASL 560XL-34-08 34ASL08 : XL	TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001	MCO		MANDATORY	MTH 11-Apr-2003 HRS 204		-			Complete
SL 560XL-34-07 34SL-07 : XL	TRANSMITTAL OF HONEYWELL PUBLICATION NUMBER A21-3440-001, PRIMUS 1000/2000 INTEGRATED AVIONICS SYSTEM-AZ840/850 MICRO AIR DATA COMPUTER (MADC) - INSPECT FOR PRESENCE OF VENDOR SPECIFIC COMPONENTS AND REPLACE AS REQUIRED	MCO		RECOMMENDED	MTH 24-Jan-2005 HRS 592		-			Complete
SL 560XL-34-11 34SL-11 : XL	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014700-34-0040	MCO		RECOMMENDED	MTH 24-Jan-2005 HRS 592		-			N/A
NOT APPLICABLE										
SL 560XL-34-13 REV1 34SL-13 : XLR1	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 955-0976-34-70, ENHANCED GROUND PROXIMITY WARNING SYSTEM			DISCRETIONARY	MTH		-			
SL 560XL-34-17 34SL-17 : XL	XMTL HONEYWELL SWB TPU 67A-SW			DISCARD	MTH		A/R			
SL 560XL-34-18 34SL-18 : XL	ELEM SURVEL XPDR PRODUCT IMPR	MCO		MANDATORY	MTH 13-Sep-2006 HRS 937		-			N/A
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 560XL-36-05 36SB-05 : XL	B/A OVERHEAT ANNUN. IMPROVEMEN	MCO		SUPERSEDED	MTH 11-Apr-2003 HRS 204		A/R			Complete
SL 560XL-36-01R1 36SL-01 : XLR1	PARTICULATE TRAP DRAIN HOLE ADDITION	ICT		RECOMMENDED	MTH 16-Jun-2003 HRS 234		-			Complete
SL 560XL-36-01 36SL-01 : XL	PARTICULATE TRAP DRAIN HOLE	MCO		SUPERSEDED	MTH 11-Apr-2003 HRS 204		A/R			Complete
SL 560XL-36-02 36SL-02 : XL	ENGINE BLEED AIR COUPLING SAFETY WIRE ADDITION	ICT		MANDATORY	MTH 28-Feb-2002 HRS 11		-			Complete
SL 560XL-36-03 36SL-03 : XL	APU BLEED AIR ORIFICE REPLACEMENT			OPTIONAL	MTH		-			
SB 560XL-38-02 38SB-02 : XL	EXTERNALLY SERVICEABLE TOILET IMPROVEMENT			OPTIONAL	MTH		-			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
SB 560XL-49-02 R1 49SB-02 : XLR1	APU MAINTENANCE DATA PORT INSTALLATION	*CF		OPTIONAL		MTH	-			
SB 560XL-49-09 49SB-09 : XL	AUXILIARY POWER UNIT PRINTED CIRCUIT BOARD IMPROVEMENT	MCO		RECOMMENDED		MTH 11-Apr-2003 HRS 204	-			Complete
SB 560XL-49-10 49SB-10 : XL	APU ENGINE START IMPROVEMENT	ICT		SUPERSEDED		MTH 17-Jun-2002 HRS 69	A/R			Complete
SB 560XL-49-11 49SB-11 : XL	APU GENERATOR CNTRL WIRING MO	MCO		SUPERSEDED		MTH 11-Apr-2003 HRS 204	A/R			Complete
SB 560XL-49-15 49SB-15 : XL	APU ADD OIL LIGHT REMOVAL			DISCRETIONARY		MTH	A/R			
SB 560XL-49-16 49SB-16 : XL	APU STARTER GENERATOR COOLING KIT INSTALLATION			DISCRETIONARY		MTH	A/R			
SL 560XL-49-11 49SL-11 : XL	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-7896 OIL DIPSTICK REPLACEMENT			DISCRETIONARY		MTH	A/R			
SB 560XL-52-06 R1 52SB-06 : XLR1	CABIN DOOR LATCH PLATE INSPECTION	MCO		MANDATORY		MTH 07-Nov-2002 HRS 141	-			Complete
SB 560XL-52-12 52SB-12 : XL	CABIN DOOR COVER PLATE MOD	MCO		DISCRETIONARY		MTH 29-Apr-2004 HRS 430	A/R			Complete
SB 560XL-52-13 REV2 52SB-13 : XLR2	BAGGAGE DOOR HINGE CHANNEL IMPROVEMENT			RECOMMENDED		MTH	-			
SB 560XL-52-14 52SB-14 : XL	CABIN DOOR REINFORCEMENT MODIFICATION			DISCRETIONARY		MTH	A/R			
SB 560XL-52-15 REV1 52SB-15 : XLR1	CABIN ENTRY DOOR COUNTERBALANCE SPRING REPLACEMENT			DISCRETIONARY		MTH	A/R			
THIS SB SHOULD BE ACCOMPLISHED WITH THE PHASE 5 INSPECTION.										
SB 560XL-52-17 REV1 52SB-17 : XLR1	CABIN ENTRY DOOR OPERATION IMPROVEMENT	MCO		RECOMMENDED		MTH 09-Aug-2008 HRS 1262	A/R			Complete
SB 560XL-52-18 52SB-18 : XL	AFT BAGGAGE DOOR HINGE MONEL RIVET REPLACEMENT	MCO		RECOMMENDED		MTH 09-Aug-2008 HRS 1262	A/R			Complete
SL 560XL-52-03 52SL-03 : XL	CABIN DOOR ANNUNCIATION IMPROVEMENT	MCO		RECOMMENDED		MTH 18-May-2005 HRS 661	-			Complete
SL 560XL-53-05 53SL-05 : XL	FUSELAGE STINGER DRAIN HOLE INSTALLATION	MCO		MANDATORY		MTH 18-May-2005 HRS 661	A/R			Complete
SL 560XL-53-06 53SL-06 : XL	FUSELAGE FS 528.50 FRAME DRAIN HOLE INSTALLATION	MCO		RECOMMENDED		MTH 01-Mar-2006 HRS 821	-			Complete
SL 560XL-56-01 56SL-01 : XL	OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION	MCO		MANDATORY		MTH 19-May-2007 HRS 1047	A/R			Complete
SB 560XL-57-03 57SB-03 : XL	WING WIRE BNDL ANCHOR IMPROVE	ICT		SUPERSEDED		MTH 16-Jun-2003 HRS 234	A/R			Complete
SB 560XL-57-04 REV2 57SB-04 : XLR2	VORTEX GENERATOR ADHESIVE IMPROVEMENT	MCO		RECOMMENDED		MTH 24-Jan-2005 HRS 592	-			Complete
SB 560XL-71-06 71SB-06 : XL	COWLING IMPROVEMENT	ICT		MANDATORY		MTH 17-Jun-2002 HRS 69	-			Complete
SB 560XL-71-07 71SB-07 : XL	MOTIVE FLOW FUEL LINE BRACKET INSTALLATION	MCO		RECOMMENDED		MTH 24-Jan-2005 HRS 592	A/R			Complete
SB 560XL-71-09 71SB-09 : XL	ENGINE OIL DOOR DOUBLER INSTALLATION	MCO		RECOMMENDED		MTH 09-Aug-2008 HRS 1262	A/R			Complete
SL 560XL-71-02R1 71SL-02 : XLR1	ENGINE ELECTRICAL GROUND INSPECTION FOR RTV	MCO		RECOMMENDED		MTH 11-Apr-2003 HRS 204	-			Complete
SL 560XL-71-03 71SL-03 : XL	ENGINE MOUNT BOLT TORQUE INSPECTION	ICT		RECOMMENDED		MTH 16-Jun-2003 HRS 234	-			Complete

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
SL 560XL-71-04	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30240 REPLACEMENT OF THE ALTERNATOR SHAFT PLAIN SEAL									
71SL-04 : XL		MCO		DISCRETIONARY	MTH 24-Jan-2005 HRS 592		-			Complete
SL 560XL-71-06	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30248 TURBOFAN ENGINE FRONT FAN CASE ASSEMBLY VIBRATION DAMPER RING-INSTALLATION									
71SL-06 : XL		MCO		RECOMMENDED	MTH 05-Oct-2005 HRS 742		-			N/A
NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										
SL 560XL-71-07	XMTL P&W SPEC INSTRUCT 17-200									
71SL-07 : XL		MCO		MANDATORY	MTH 13-Sep-2006 HRS 937		A/R			N/A
NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										
SL 560XL-71-08	B/A TUBE SLEEVING INSTAL IMPR									
71SL-08 : XL		MCO		RECOMMENDED	MTH 13-Sep-2006 HRS 937		-			Complete
SL 560XL-72-03	TRANSMITTAL OF P&WC SERVICE BULLETIN PW500-72-30196 REV 1, TURBOFAN ENGINE REPLACEMENT OF TURBOFAN ENGINE P BELLOWS SEALS									
REV3		MCO		RECOMMENDED	MTH 24-Jan-2005 HRS 592		-			Complete
72SL-03 : XLR3										
SL 560XL-72-09	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30217, FUEL TUBE INSPECTION									
72SL-09 : XL		MCO		RECOMMENDED	MTH 07-Nov-2002 HRS 141		A/R			Complete
SL 560XL-72-11 R1	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30252 NUMBER FOUR BEARING OIL PRESSURE AND OIL SCAVENGE TUBES - REPLACEMENT OF									
LEFT ENGINE				CANCELLED	MTH					
72SL-11 : XLR1					HRS		300			
SERVICE BULLETIN/LETTER CANCELLED OR SUPERSEDED										
SL 560XL-72-11 R1	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30252 NUMBER FOUR BEARING OIL PRESSURE AND OIL SCAVENGE TUBES - REPLACEMENT OF									
RIGHT ENGINE				CANCELLED	MTH					
72SL-11 : XLR1					HRS		300			
SERVICE BULLETIN/LETTER CANCELLED OR SUPERSEDED										
SL 560XL-72-12	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30331 MODIFICATION OF FUEL PRESSURE HOSE AND TUBE ROUTING									
72SL-12 : XL				OPTIONAL	MTH		A/R			
SL 560XL-72-13	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30335 TURBOFAN ENGINE GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS BORESCOPE INSPECTION OF									
LEFT ENGINE				RECOMMENDED	MTH					
72SL-13 : XL					HRS		300		1463	-146.1
THIS SERVICE LETTER IS DUE AT HOT SECTION BUT NOT TO EXCEED 4100 TOTAL ENGINE HOURS.										Over Due
SL 560XL-72-13	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30335 TURBOFAN ENGINE GAS-GENERATOR-CASE TO INTERMEDIATE-CASE RETAINING-BOLTS BORESCOPE INSPECTION OF									
RIGHT ENGINE				RECOMMENDED	MTH					
72SL-13 : XL					HRS		300		1463	-146.1
THIS SERVICE LETTER IS DUE AT HOT SECTION BUT NOT TO EXCEED 4100 TOTAL ENGINE HOURS.										Over Due
SL 560XL-72-14	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30306 TURBOFAN ENGINE NEW TRANSFER TUBES WITH HEAT SHIELD									
LEFT ENGINE				RECOMMENDED	MTH					
72SL-14 : XL					HRS		300		1463	-146.1
										Over Due
SL 560XL-72-14	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30306 TURBOFAN ENGINE NEW TRANSFER TUBES WITH HEAT SHIELD									
RIGHT ENGINE				RECOMMENDED	MTH					
72SL-14 : XL					HRS		300		1463	-146.1
										Over Due

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
SL 560XL-72-17	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT, MODIFICATION OF									
LEFT ENGINE 72SL-17 : E1**L				MANDATORY	MTH		6		31-Jul-2010	2 m 11 d
CESCOM DEFAULTS TO MOST RESTRICTIVE TBO. PLEASE NOTIFY CESCOM OF CORRECT DUE POINT FOR YOUR AIRCRAFT.										
SL 560XL-72-17	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT, MODIFICATION OF									
RIGHT ENGINE 72SL-17 : E2**R				MANDATORY	MTH		6		31-Jul-2010	2 m 11 d
CESCOM DEFAULTS TO MOST RESTRICTIVE TBO. PLEASE NOTIFY CESCOM OF CORRECT DUE POINT FOR YOUR AIRCRAFT.										
SB PW500-72-30084 R2 E1	REPLACEMENT OF FAN CASE ASSEMBLY			RECOMMENDED			-			
SB PW500-72-30084 R2 E2	REPLACEMENT OF FAN CASE ASSEMBLY			RECOMMENDED			-			
SB PW500-72-30400 R1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			RECOMMENDED			A/R			
E1										
SB PW500-72-30400 R1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			RECOMMENDED			A/R			
E2										
SB PW500-72-30400 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			SUPERSEDED			A/R			
SB PW500-72-30400 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			SUPERSEDED			A/R			
SB PW500-72-30408 E1	REPLACEMENT OF ENGINE GASKET			RECOMMENDED			A/R			
SB PW500-72-30408 E2	REPLACEMENT OF ENGINE GASKET			RECOMMENDED			A/R			
SB PW500-72-30413 E1	INTRODUCTION OF DEEPER SUMP			RECOMMENDED			A/R			
SB PW500-72-30413 E2	INTRODUCTION OF DEEPER SUMP			RECOMMENDED			A/R			
SB PW500-72-30416 E1	REPLACEMENT OF NO.4 BEARING CARBON SEAL						A/R			
SB PW500-72-30416 E2	REPLACEMENT OF NO.4 BEARING CARBON SEAL						A/R			
SB PW500-72-30417 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			RECOMMENDED			A/R			
SB PW500-72-30417 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			RECOMMENDED			A/R			
SB 560XL-73-01 73SB-01 : XL	ENGINE FUEL LINE FITTING INSPECTION	ICT		MANDATORY	MTH 16-Jun-2003 HRS 234		-			Complete
ASL 560XL-73-11	TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN A30319 TURBOFAN ENGINE NEW FUEL MANIFOLD-INTRODUCTION OF									
LEFT ENGINE 73ASL-11 : E1**L		MCO		MANDATORY	MTH 03-Apr-2008 HRS 1201		A/R			Complete
INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.										



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
ASL 560XL-73-11	TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN A30319 TURBOFAN ENGINE NEW FUEL MANIFOLD-INTRODUCTION OF									
RIGHT ENGINE 73ASL-11 : E2**R		MCO		MANDATORY		MTH 03-Apr-2008 HRS 1201	A/R			Complete
INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.										
SL 560XL-73-03	TRANSMITTAL OF P&WC SERVICE BULLETIN 30249 TURBOFAN ENGINE FUEL MANIFOLD - INSPECTION/REPLACEMENT OF AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) A03008									
73SL-03 : XL		MCO		RECERTIFY		MTH 30-Apr-2004 HRS 430	-			Complete
NOT APPLICABLE										
SL 560XL-73-04 REV1	TRANSMITTAL OF P&WC SERVICE BULLETIN 30253 TURBOFAN ENGINE FUEL PRESSURE TUBE REPLACEMENT AND ATTENUATOR INTRODUCTION OF MODEL APPLICATION PW545A									
		MCO		RECOMMENDED		MTH 30-Apr-2004 HRS 430	-			Complete
73SL-04 : XLR1										
SL 560XL-73-08 73SL-08 : XL	XMTL P&W 30296R1	MCO		MANDATORY		MTH 13-Sep-2006 HRS 937	-			Complete
SL 560XL-73-12	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER									
73SL-12 : XL	PLATE/FAIRING/REPLACEMENT OF	MCO		RECOMMENDED		MTH 11-Mar-2010 HRS 1573.2 LDG 1064	12 300			Complete
SB PW500-72-30404 R3 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE						A/R			
SB PW500-72-30404 R3 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE						A/R			
SB PW500-72-30414 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE						A/R			
	INFORMATIONAL									
SB PW500-72-30414 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE						A/R			
	INFORMATIONAL									
SB 560XL-78-02 78SB-02 : XL	THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT					MTH	-			
	OPTIONAL									
SB 560XL-80-03 80SB-03 : XL	APU GENERATOR CONTROL UNIT (GCU) CURRENT LIMITING	MCO		RECOMMENDED		MTH 18-May-2005 HRS 661	-			Complete



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
AD 2000-15-51 27AD-01 : XL	AILERON CABLE FAIRLEAD TUBE AND AILERON CABLE SECTOR ICT			MANDATORY	MTH HRS 11	28-Feb-2002 11	-			Complete
AD 2006-16-18 34AD-13 : XL NOT APPLICABLE	SANDEL AVI MOD ST3400 TAWS/RM MCO			MANDATORY	MTH HRS 992	21-Jan-2007 992	A/R			N/A
AD 2006-19-04 34AD-14 : XL NOT APPLICABLE	HONEYWELL RCZ COMM & XPDRS MCO			MANDATORY	MTH HRS 992	21-Jan-2007 992	A/R			N/A
AD 2003-03-21 E1 73AD-01 : E1**L	TO PREVENT A FIRE IN THE ENGINE NACELLE AREA MCO				MTH HRS 204	11-Apr-2003 204	-			Complete
AD 2003-03-21 E2 73AD-01 : E2**R	TO PREVENT A FIRE IN THE ENGINE NACELLE AREA MCO				MTH HRS 204	11-Apr-2003 204	-			Complete
AD 1974-08-09 R2 053801	WASTE RECEPTACLE INSPECTION MCO			MANDATORY	MTH HRS		1000		1937	327.9
AD 1998-25-10 25AD-01 : XL NOT APPLICABLE-EQUIPMENT NOT INSTALLED	AIRCRAFT BELT INSPECTION ICT			MANDATORY	MTH HRS 11	28-Feb-2002 11	A/R			Complete
AD 2006-04-10 26AD-03 : XL	INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPLICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS. MCO			MANDATORY	MTH HRS 859	26-May-2006 859	A/R			Complete
AD 2007-11-17 26AD-05 : XL	IDENTIFY WIRES FOR FIRE EXTINGUISHING BOTTLES MCO			MANDATORY	MTH HRS 1176	23-Feb-2008 1176	A/R			Complete
AD 1995-22-01 33AD-01 : XL NOT APPLICABLE-EQUIPMENT NOT INSTALLED	AEROSPACE LIGHTING POWER UNIT ICT			MANDATORY	MTH HRS 11	28-Feb-2002 11	A/R			Complete
AD 1997-05-03 R1 34AD-07 : XLR1 NOT APPLICABLE-EQUIPMENT NOT INSTALLED	GNX-XLS AND GNS-XL GPS ICT			MANDATORY	MTH HRS 11	28-Feb-2002 11	A/R			Complete
AD 2001-23-17 34AD-09 : XL NOT APPLICABLE-EQUIPMENT NOT INSTALLED	GARMIN INTERNATIONAL GNS 430 ICT			MANDATORY	MTH HRS 11	28-Feb-2002 11	A/R			Complete
AD 2003-04-06 34AD-03 : XL	HONEYWELL PRIMUS RNZ-850/851 NM MCO			SUPERSEDED	MTH HRS 204	11-Apr-2003 204	A/R			Complete
AD 2006-22-05 34AD-15 : XL	HONEYWELL PRIMUS RNZ-850/851 NM MCO			MANDATORY	MTH HRS 1047	19-May-2007 1047	A/R			N/A
AD 2010-07-02	PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)			MANDATORY	MTH		30		03-Nov-2012	New Req



CESCOM 10 - Aircraft Status Report

Owner: **CHILDISH CREATIONS INTERNATIONAL, INC.**

Aircraft Model: **560XL - CITATION XL**

Aircraft Serial: **560XL-5233** Unit: **5233** Reg No: **N233XL**

Airworthiness: **28-Feb-2002**

Print Date: **20-May-2010 6:28PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	1609.1	1087	31-Mar-2010	.78
ENG 1	1609.1	1106	31-Mar-2010	.78
ENG 2	1609.1	1106	31-Mar-2010	.78
APU	907	1339	31-Mar-2010	.2

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
25FO-03XL 25FO-03 : XL	PLUMBING: EXTERNAL SERV TOILET FACTORY OPTION	*CF		130 FO		MTH 28-Feb-2002	-			
25FO-12XL/A 25FO-12 : XL/A	PEDESTAL: DOUBLE-WIDE FACTORY OPTION	*CF		649A FO		MTH 28-Feb-2002	-			
32FO-03XL/B 32FO-03 : XL/B	CONTROL: LND GEAR RH PANEL FACTORY OPTION	*CF		33B FO		MTH 28-Feb-2002	-			
34FO-06XL/P 34FO-06 : XL/P	DTU: PERMANENT UNS-1CSP FACTORY OPTION	*CF		696P FO		MTH 28-Feb-2002	-			
34FO-06XL/Q 34FO-06 : XL/Q	#2 UNS-1CSP: PROVISIONS FACTORY OPTION	*CF		696Q FO		MTH 28-Feb-2002	-			
34FO-08XL/B 34FO-08 : XL/B	TCAS II: TPU-67A FACTORY OPTION	*CF		635B FO		MTH 28-Feb-2002	-			
35FO-02XL/C 35FO-02 : XL/C	OXY SYSTEM: 76 CU FT FACTORY OPTION	*CF		66C FO		MTH 28-Feb-2002	-			
49FO-01XL/G 49FO-01 : XL/G	AUXILIARY POWER UNIT FACTORY OPTION	*CF		46G FO		MTH 28-Feb-2002	-			